Bear Brook and Ramsay Creek Watersheds Fluvial Geomorphological Study

Existing Conditions Summary Report Tewin Lands



Prepared for: Taggart Investments and Algonquins of Ontario 3187 Albion Road South Ottawa, ON K1V 8Y3

December 12, 2024

GEO Morphix Project No. 21063



| Ver. | Purpose/Change | Authored by | Approved by | Date |
|------|---|-------------|-------------|------------|
| 1.0 | First Submission | K. Woodrow | P. Villard | 2023-06-20 |
| 2.0 | Addressing City of Ottawa and Conservation Authority Comments | K. Woodrow | P. Villard | 2024-04-30 |
| 3.0 | Addressing Conservation Authority Comments | K. Woodrow | P. Villard | 2024-10-08 |
| 3.1 | Addressing Conservation Authority Comments | K. Woodrow | P. Villard | 2024-12-12 |

Disclaimer

This report presents professional opinions and findings of a scientific and technical nature based on the knowledge and information available at the time of preparation. This document is prepared solely for the Client, and the data, interpretations, suggestions, recommendations, and opinions expressed in the report pertain only to the project being completed for the Client.

Table of Contents

| 1 | Intro | ction | 1 | | | | | | |
|---|--------------|--|----|--|--|--|--|--|--|
| | 1.1 | ntroduction | 1 | | | | | | |
| | 1.2 | ntegrated Master Plan & Municipal Class EA Process | 2 | | | | | | |
| | 1.3 | ewin Overview and Community Vision | 2 | | | | | | |
| | 1.4 | ewin Intent: A Forward-Thinking Framework | 2 | | | | | | |
| | 1.5 | xisting Conditions Technical Reports | 4 | | | | | | |
| | 1.6 | ramework for Identifying Preliminary Opportunities | 4 | | | | | | |
| | 1.7 | cope of Tewin Fluvial Geomorphological Assessments | 5 | | | | | | |
| 2 | Backg | ound Review | 6 | | | | | | |
| | 2.1 | /atershed | 6 | | | | | | |
| | | .1.1 Terrain Analysis | 6 | | | | | | |
| | 2.2 | eology and Physiography | 8 | | | | | | |
| | 2.3 | istorical Assessment | 8 | | | | | | |
| | 2.4 | esktop Reach Delineation | 9 | | | | | | |
| 3 | Field | sessments | 10 | | | | | | |
| | 3.1 | apid Assessments | 15 | | | | | | |
| | 3.2 | etailed Geomorphological Assessment | 18 | | | | | | |
| 4 | Erosio | Hazard Assessment | 19 | | | | | | |
| | 4.1 | ethodology | 19 | | | | | | |
| | 4.2 | esults | 19 | | | | | | |
| | | .2.1 Unconfined Valley Reaches | 19 | | | | | | |
| | | .2.2 Confined Valley Reaches | 22 | | | | | | |
| 5 | Cross | g Assessment | 22 | | | | | | |
| 6 | Sumr | ry of Preliminary Opportunities | 23 | | | | | | |
| 7 | Conclusion24 | | | | | | | | |
| 8 | Refer | ces | 25 | | | | | | |

List of Figures

| Figure 1. Tewin Study Area identified in black outline | 1 |
|---|---|
| Figure 2. Longitudinal Profile of Bear Brook North Branch | 7 |
| Figure 3. Longitudinal Profile of Bear Brook South Branch | 7 |

List of Tables

| Table 1. General reach characteristics for Bear Brook reaches in Study Area | 11 |
|---|----|
| Table 2. General reach characteristics for Ramsay Creek reaches in Study Area | 14 |
| Table 3. Rapid geomorphological assessment results for Bear Brook reaches in Study Area | 16 |
| Table 4. Rapid geomorphological assessment results for Ramsay Creek reaches in Study Area | 17 |
| Table 5. Average channel parameters for detailed assessment sites | 18 |
| Table 6. Preliminary meander belt widths for unconfined reaches in Study Area | 21 |

Appendices

- Appendix A: Desktop Geomorphological Assessment of Bear Brook
- Appendix B: Study Area Mapping
- Appendix C: Historical Aerial Photographs
- Appendix D: Reach Characteristics Summary Table
- Appendix E: Photographic Record
- Appendix F: Detailed Assessment Summaries
- Appendix G: TRCA Meander Belt Width Values
- Appendix H: Utility Crossing Assessment

1 Introduction

1.1 Introduction

This fluvial geomorphological report is part of a set of technical reports which have been prepared as part of Phase 1 of the Tewin study process. The Tewin Study Area ("Study Area") lands were identified as a future urban development area in the new City of Ottawa Official Plan (2022). The Study Area is located in southeast Ottawa, generally bordered by Leitrim Road to the north, Farmers Way to the east, Thunder Road to the south, and Anderson Road and Ramsayville Road to the west. The Study Area is outlined in **Figure 1** below. These technical reports are intended to establish an understanding of the existing physical, social, and ecological conditions that characterize the Study Area. Where appropriate, these reports also identify preliminary opportunities to help guide the next phase of the master planning process.

This information will be used to identify opportunities and strategic considerations that will inform the Tewin community design process going forward, as well as frame the preparation of additional site-specific technical studies and recommendation reports. Development at Tewin will explore new approaches to planning, design and development, including alternative strategies and solutions that can successfully implement the key community objectives.



Figure 1. Tewin Study Area identified in black outline

MORPHIX

1.2 Integrated Master Plan & Municipal Class EA Process

The ambition and scale of Tewin requires ongoing internal and external consultation. The purpose of the integrated Master Plan and Municipal Class EA process is to consolidate the various technical and community planning elements of the project to promote coordinated community engagement through streamlined and aligned decision making. This format will ensure critical partners, consultants and stakeholders are brought together at major milestones to identify and track challenges and opportunities through the development process.

The integrated Master Plan and Municipal Class EA process will include a public consultation strategy and technical study review timeline that achieves the requirements of the Master Plan and Municipal Class EA concurrently. The statutory Municipal Class EA meetings will be timed to align with the development of the community objectives, urban framework, preferred plans, and the draft secondary plan. Additional public and targeted consultations will be planned to complement the statutory consultation requirements. The development of the One Planet Action Plan (OPAP) will occur in parallel, with the final OPAP available at the time of final secondary plan. Council approval. One Planet Living endorsement will follow Council approval of the secondary plan.

1.3 Tewin Overview and Community Vision

Tewin is planned to be a community of approximately 45,000 people and thousands of jobs. It will be more compact and dense than existing suburbs in Ottawa, with new urban areas integrated alongside valuable natural areas. Tewin will be an inclusive community, anchored in Algonquin wisdom and placekeeping principles, and welcoming to all. The community will have a meaningful mix of land uses and support active mobility, to achieve a complete, future ready community. The Tewin Project Team and City of Ottawa have committed to exploring appropriate options, alternatives and standards to enable Tewin to become a model of best practices in sustainable and inclusive community design in the North American context.

The integrated Master Plan and Municipal Class EA process will bring together various technical and community planning considerations.

The key objectives for Tewin are to create a community that is:

- Anchored in Algonquin wisdom, principles and placekeeping
- A benchmark for community design, demonstrating achievement of the 5 Big Moves identified in the Ottawa Official Plan
- Mobility-oriented and supportive, promoting a broad range of active forms of movement, where
 personal vehicles are optional
- Characterized by a meaningful mix of housing, community amenities, jobs and services in order to achieve a complete, future-ready community
- Designed to protect and integrate alongside valuable natural areas and agricultural lands; and
- Affordable, inclusive, healthy, welcoming and accessible to all

1.4 Tewin Intent: A Forward-Thinking Framework

Development at Tewin will explore new approaches to planning, design and development, finding successful options and alternatives to implement the key community objectives, in some cases likely going beyond what current development standards would allow for. The Tewin Project Team and the City of Ottawa have articulated these in the "Tewin Intent" which sets out the following:

1. Bold and Innovative Thinking:

Tewin is about creating a new kind of community, a future-focused model for smart, healthy and sustainable development. It will be a people-centred place that seeks to create the conditions for wellbeing. The Tewin Project Team will be open to bold ideas, innovative approaches, creative solutions, efficient use of land and resources, emerging technologies, smart city infrastructure that advances the City's goals and objectives, and other future-forward ideas and opportunities that will enable Tewin to reach its full potential.

2. Integrating Algonquin Values and Principles:

Algonquin principles, values and teachings will guide the planning, consultation, design and development process for Tewin. The integration of Algonquin principles and design intentions will ensure the community is nature-based and sensitive to Mother Earth while creating capacity-building and economic development opportunities for the Algonquin people.

3. Sustainability and Resilience:

Tewin will be a model community that will position Ottawa as a leader in integrated sustainable design with the goal of being a resilient and holistic community. Tewin will be guided by the One Planet Living framework and Algonquin values of respect for the earth. The Community Design Plan will respond to the City's High Performance Development Standard and Climate Change Master Plan and will result in a Community Energy Plan. A Community Energy Plan and performance-based sustainability metrics that address climate mitigation and adaptation, and the other categories of the High-Performance Development Standards will be established from the start and monitored over time.

4. Systems-Based Environmental Planning

Tewin's organization and functions will be designed to respect nature and integrate natural features and landscapes into its form, character, and spirit. To that end, the Tewin Project Team is committed to pursuing a systems-based approach to natural heritage protection, environmental management, and water management in a way that is inclusive and integrated and encourages stewardship and a positive relationship with the natural world. Natural features are regarded as opportunities rather than constraints, will be woven into the fabric of the community, and will be central to its design and character.

5. Alternative Design Solutions:

Designing a community of the future requires progressive and forward-thinking infrastructure solutions. The Tewin Project Team is committed to being solutions-oriented and will consider alternative design and engineering standards that prioritize natural systems, pedestrians, cyclists and transit users, and which efficiently use available land and resources.

Surface water management strategies that achieve quality, conveyance and storage objectives will be based on the fundamentals of natural cycles, green/soft infrastructure, and multi-use opportunities that complement the human realm. Infrastructure design will consider the needs of those involved in the construction, operation and maintenance of municipal services to find opportunities to efficiently service the community and showcase sustainable practices while meeting the community's needs.

A framework for assessing alternative design standards will be established to consider and review alternatives against existing standards within the context of goals and objectives for the City and Tewin.

6. Cost-Effectiveness and Efficiency:

Tewin will demonstrate best practices in efficient and compact development. As a dense, mixed-use community of scale, Tewin will achieve a critical mass of people and jobs to support new infrastructure investments. The Tewin Project Team is committed to exploring opportunities to optimize the community's efficiency through a range of strategies, including prioritizing space-efficient modes of transportation, use of technology, green infrastructure, innovative construction practices, shared-use agreements, and mixed-use forms of development that will promote the efficient use and optimization of land; housing affordability; and supporting the long-term financial viability of the community and city resources.

7. Integrated Planning Process:

We are committed to advancing Tewin through a comprehensive and integrated planning and environmental assessment process where possible or applicable. The process will bring together various planning, environmental, transportation, urban design, infrastructure, economic, financial, social and

technical considerations. The process will be underpinned by engagement with the Algonquin people, other stakeholders, and the public.

8. Collaboration and Problem Solving:

The Tewin Project Team and City of Ottawa Project Team are committed to working collaboratively together to move Tewin forward in an expedited way. We will plan with a spirit of collaboration and joint problem-solving to ensure that the development of Tewin meets the best interests of the City of Ottawa and the Algonquins of Ontario.

9. Communication and Transparency

The Tewin Project Team and the City of Ottawa Project Team commit to open and transparent communication throughout the project. This will require proactively sharing information between the groups as decisions are made and to ensure relevant communication materials are distributed in a timely manner.

The Tewin Project Team and the City of Ottawa Project Team will ensure that all parties, including City Council, residents, and other stakeholders, are provided with pertinent details. Effective information sharing will ensure the project achieves outcomes that are, to the greatest extent possible, known by all involved.

1.5 Existing Conditions Technical Reports

A range of specialized consultants have been studying the physical environment of the Study Area to support community design, servicing strategies and the future development of Tewin. This data has been collected and reported on in a set of Existing Conditions and Opportunities Reports, of which this document is one. The full suite of reports includes the following:

- **Tewin Existing Conditions and Preliminary Opportunities Report** dated September 2024 and prepared by Urban Strategies
- Fluvial Geomorphology Study Tewin Lands: Existing Conditions Summary Report -Bear Brook and Ramsay Creek Watersheds dated October 2024 and prepared by GEO Morphix Ltd.
- **Tewin Lands: Existing Conditions Hydrogeological Study** dated September 2024 and prepared by Dillon Consulting
- Existing Conditions Geotechnical: Tewin Lands dated September 2024 and prepared by Paterson Group
- Tewin Lands: Natural Heritage Preliminary Existing Conditions Report dated April 2024 and prepared by Kilgour and Associates
- **Tewin Lands: Cumulative Hydrologic Impact Assessment** dated April 2024 and prepared by J.F. Sabourin and Associates
- **Tewin Lands: 2021-22 Field Monitoring Report** dated April 2024 and prepared by J.F. Sabourin and Associates
- **Tewin Lands Existing Conditions Water Budget** dated October 2024 and prepared by J.F. Sabourin and Associates
- Tewin Mobility Existing Conditions dated May 2024 and prepared by CGH Transportation
- Stage 1 Archaeological Assessment Tewin Lands dated July 14, 2023 and prepared by WSP Canada

1.6 Framework for Identifying Preliminary Opportunities

Given the unique scale, vision and project goals for Tewin, as well as the shared commitment to exploring new ways of advancing the community design process as expressed in the Tewin Intent, the Phase 1 reports for Tewin include a discussion of potential opportunities to be explored in subsequent stages of the integrated Master Plan and Municipal Class EA process. The identification of preliminary constraints and opportunities, as well as a preliminary community structure, is required in Phase 1 of the integrated Master Plan and Municipal Class EA process as per specific Terms of Reference that were established for each of the Tewin planning, environmental and transportation studies.

The opportunities introduced within these reports are based on a series of key policy directions and strategic considerations, including:

- **Ottawa's new Official Plan**, which promotes the creation of complete, transit-supportive communities
- **Algonquin values and principles**, underscored by respect for nature, integration of water, and planning the natural environment to achieve long-term vitality over many generations
- **The Tewin Intent**, which promotes innovative thinking and alternative, performance-based solutions
- **One Planet Living**, a holistic framework for achieving environmental resiliency, sustainable development, and reduced carbon emissions
- **Provincial policy** direction focused on supporting housing development and facilitating growth, in order to address the province's housing supply challenges
- An integrated, systems-based approach to planning at Tewin that brings together diverse planning, environmental, technical and economic considerations

1.7 Scope of Tewin Fluvial Geomorphological Assessments

The extent of fluvial geomorphic assessment activities completed to-date span several tributaries of Bear Brook and Ramsay Creek, including the Smith Gooding Municipal Drain and Johnson Municipal Drain. Both field-based and desktop-based assessments have been completed. The field-based assessments provide preliminary observations in support of future activities within the Tewin Area in the City of Ottawa, Ontario (**Figure 1**). The information provided by the field assessments informed an erosion hazard assessment and crossing assessment for several watercourses within the Tewin Study Area and adjacent lands. The field information will continue to serve and inform additional planning aspects relating to fluvial geomorphology, such as erosion thresholds for long-term erosion mitigation. As part of the Tewin Lands field-based fluvial geomorphic assessments, GEO Morphix Ltd. ("GEO Morphix") completed the following:

- Background review of all existing documents related to the Tewin Study Area and topography, physiography, and geology maps of the local watersheds and study area
- Reach delineation for all watercourses in the Study Area, including various tributaries downstream of the study area boundary
- Historical assessment of changes in land use and channel form and function using historical aerial photographs
- Site reconnaissance, including rapid geomorphological assessments and channel characterization for all reaches identified on participating lands
- Detailed geomorphological assessments of erosion-sensitive reaches identified by site reconnaissance to inform future erosion threshold analysis
- Hazard delineation and erosion setbacks for all confined and unconfined reaches in the Tewin Study Area to support the preliminary review of existing environmental constraints
- Assessment of existing drainage crossings that overlap with the proposed servicing lines route

A desktop-based geomorphological inventory and assessment was conducted by GEO Morphix along Bear Brook, downstream of the Tewin Study Area. The desktop assessment examined watercourse characteristics in a hierarchical, nested approach in terms of spatial scale. The Bear Brook watershed was assessed at the watershed/sub-watershed scale, then reach scale, then sub-reach and geomorphic unit scale. The purpose of the desktop-based analyses was to document existing conditions and the extent of potential future concerns along the Bear Brook main channel as areas within its headwaters undergo land use changes. The following tasks were completed as part of the desktop-based assessment:

- Review of cumulative hydrologic inputs of Bear Brook and select tributaries for multiple hydrological scenarios and storm conditions (JFSA, 2024)
- Review of watershed characteristics (e.g., surficial geology, topography, land cover/use)
- Division of the main channel through the assessment area into "valley segments"
- Historical aerial imagery analysis to identify historical geomorphological and anthropogenic changes along the channel and channel corridor



• An inventory of Points of Interest observed in the aerial imagery at which the Bear Brook main channel may have higher sensitivity to proposed future land use changes

The results of the field-based fluvial geomorphic assessments are presented herein. Results of the desktop-based geomorphological inventory and assessment for Bear Brook are provided in **Appendix A**.

2 Background Review

2.1 Watershed

The Tewin Study Area (8.9 km²) is situated in the headwaters of the Bear Brook and Ramsay Creek watersheds. Bear Brook is a tributary of the South Nation River and drains an area of approximately 490 km². A section of the Smith Gooding and Johnson Municipal Drains (tributaries to Bear Book) also bisect the Tewin Lands. Ramsay Creek is a tributary of Green's Creek which drains an area of approximately 71.97 km² and 113.34 km² respectively; Green's Creek is a tributary of the Ottawa River. The Tewin Study Area occupies roughly 2% of the overall Bear Brook subwatershed and 5% of the overall Ramsay Creek watershed area. The tributaries and Municipal Drain extents are shown in **Appendix B**, for reference.

Landuse along the channel reaches within the Tewin Study Area is a mix of forested and agricultural lands. The headwater reaches of Ramsay creek, upstream of Leitrum Road, are straight drainage channels. The tributaries of Bear Brook which drain and traverse the Tewin Study Area are a mix of headwater drainage features, municipal drains, and relatively sinuous reaches with floodplains situated in confined valley settings.

2.1.1 Terrain Analysis

Terrain analysis of a high-resolution digital elevation model (DEM) was used to classify the channel valley type (confined; unconfined) for each of the channel reaches within the study area. A high-resolution bare-earth DEM was obtained for the study area from a publicly available LiDAR dataset maintained by OMNRF (2019/2020 data). The bare-earth elevation raster was used to generate a hillshade model of the study that was used for the interpretation and analysis of geomorphic features (e.g. stream channels and valley walls). Following from SNCA guidance documents, a reach was classed as confined where all or a portion of the channel was situated in a valley where both valley walls extended to a height of 3m or more above the floodplain, or if absent, the channel. Additional field observations were also used to verify channel and valley form. A hillshade model of the LiDAR data is provided in **Appendix B**.

A review of the longitudinal profiles along Bear Brook within the Study Area was also preformed using the LiDAR dataset. Longitudinal channel bed profiles were generated by taking samples of elevation at 1 m intervals along the channel flow path. The sampled elevations in meters were then plotted with horizontal distance downstream. Features along the watercourse, including crossings, beaver dams (observed during rapid assessments or aerial interpretation), and confluences were overlayed on the plot to provide geomorphic context. It should be noted that the long profiles are based on 2020 data, and as such, there may be differences between 2020 and present-day conditions. Given the Municipal Drain status of many of the watercourse segments within the Tewin study area, ongoing maintenance activities in these drains may also adjust specific conditions at any given time.

The length of Bear Brook was divided into Bear Brook North and Bear Brook South, which are presented below in **Figures 2** and **3**.

Overall, the longitudinal profiles along the main branch of Bear Brook exhibited the greatest change in slope around beaver dams, crossings, and tributary confluences. Generally, the areas with relatively lower gradients tended to precede beaver dams, most likely due to the deposition caused by backwatering and slower flows, as observed in the field assessments summarized in Section 3.







Figure 3. Longitudinal Profile of Bear Brook South Branch

→ MORPHIX[™]

2.2 Geology and Physiography

Surficial geology and physiography act as primary controls regarding channel development, as they greatly influence the hydrological and sediment characteristics of a given drainage system. Channel morphodynamics are largely governed by the flow regime and the availability and type of sediments within the stream corridor. These factors are explored as they not only offer insight into existing conditions, but also potential changes that could be expected in the future as they relate to proposed development within the stream's catchment area. A map showing the surficial geology throughout the subject lands is provided in **Appendix B**.

The Tewin Study area is located in a physiographic region known as the Russell and Prescott Sand Plains (region 50) which is adjacent to the Ottawa Valley Clay Plains (Region 49) located immediately to the north and east of the Tewin Study area (Chapman and Putnam, 1984). This region of sand plains is characterized by a relatively level surface located at approximately 80 m above sea level. The sand deposits across the study area are associated with the Champlain Sea, an inlet to the Atlantic Ocean which extended into the present-day Ottawa River Valley at the end of the most recent glacial period (c. 10,000 ago). Across the Tewin Study Area, the surficial geology is mapped as fine-to-mediumgrained (nearshore deposits) along the western boundary of the area, with silt and clay (off-shore marine deposits) mapped across the central portion of the study area (OGS, 2010). The surficial deposits along the northeastern corner of the area are mapped as medium-to fine-grained sands characteristics of deltaic and estuarine deposits (OGS, 2010). The fine-grained, silt and clay deposits, mapped across most of site originated in a glaciomarine context in the brackish waters of the Champlain Sea with sediments sourced from Canadian Shield granite (Alysworth and Lawrence, 2003; Hunter, Crow, and Brooks, 2010; Chapman and Putnam, 1984). These courser-grained materials are non-cohesive and more susceptible to erosion. Whereas the finer silty and clay-sized materials that are mapped across most of the Tewin Study Area have a greater cohesive bond and are, therefore, more resistant to erosion. For a more detailed characterization of subsurface conditions, refer to the Existing Conditions - Geotechnical: Tewin Lands report prepared by Paterson Group (2024) and the Tewin Lands: Existing Conditions Hydrogeological Study prepared by Dillon Consulting (2024).

2.3 Historical Assessment

A series of historical aerial photographs were reviewed to determine changes to watercourse systems and surrounding land use/cover over time. This information partly provides an understanding of the historical factors that have contributed to current channel morphodynamics. Aerial photographs from 1965 to 2019 from the City of Ottawa (https://maps.ottawa.ca/geoottawa/) were reviewed. Historical aerial photographs are included in **Appendix C**, for reference.

Aerial photographs from 1965 only cover the upstream reaches of Ramsay Creek within the Study Area. Ramsay Creek's main branch meanders through a mix of active agricultural field and treed areas. Many of its tributaries have been historically straightened for agricultural purposes and drain the surrounding actively cultivated fields. Riparian vegetation along Ramsay Creek and its tributaries is relatively sparse and composed of grasses and herbaceous vegetation. Few rural dwellings are established along Leitrim Road, Ramsayville Road, and Anderson Road in 1965.

Little visible change occurs between 1965 and 1976 imagery for Ramsay Creek. The upstream reaches of Ramsay Creek and its tributaries within the Study Area (i.e., south of Leitrim Road) exhibit little planform development. Riparian vegetation remains sparse and active agriculture remains the dominant land use adjacent to the reaches.

Bear Brook and its tributaries within the Study Area are generally visible in the 1975 imagery. The surrounding land use is predominantly active agriculture, and several rural dwellings are located sparsely across the lands. The main branch of Bear Brook meanders through active agricultural fields. Several of the reaches along the main branch and its tributaries exhibit straightened planforms and drain the surrounding fields. Sparse parcels of land containing forested areas are concentrated with the southern portion of the Study Area and the riparian edges at these locations are wide and composed of mature trees. The riparian edges along the remaining reaches are generally narrow and sparse. Notably Highway 417 located northeast of the site is constructed between 1965 and 1976.

Historical imagery between 1976 and 1991 show little observable changes in channel planform throughout the Study Area for Bear Brook and tributaries. Land use remains predominantly active agriculture. However, many of the fields along the northern and southern border of the site, and many previously cultivated fields surrounding the Study Area appear to transition to treed areas. Several additional rural dwellings are established along the bordering roads. Riparian vegetation along the main branches of Ramsay Creek and Bear Brook matures, as well as many of the upstream Bear Brook reaches located in the southern portion of the Study Area.

Changes in channel planform between 1991 and 1999 imagery are minimally observed. Land use remains active agriculture and trees in the southern and northern portions of the Study area increasingly mature. Riparian edges along the agricultural ditches remain narrow or non-existent.

Between 1999 and 2011 major changes within the Study Area include the development of the Anderson Links Golf Course, located in the northeastern corner of the site on previously farmed land. This resulted in the incorporation of outlets to the main branch of Bear Brook through a series of constructed ponds. Several large beaver ponds are observed along upstream reaches of Bear Brook, resulting in slight changes in channel planform due to backwatering. Much of the land use remains active agriculture and forested plots increase in maturity.

Little changes occur across the Study Area between 1999 and 2019. Treed areas in the north and south are mature and many of the tributaries are not visible due to the dense canopy coverage. The large beaver ponds in the south have de-watered as of 2019 imagery, leaving large grassy floodplains. The riparian edges along many of the tributaries flowing through active agriculture remains narrow. Surrounding land use from 1965 to 2019 has transitioned from agriculture to treed areas; however, agriculture remains prominent within the Study Area.

2.4 Desktop Reach Delineation

Reaches are homogeneous segments of channel used in geomorphological investigations. Reaches are divided as such because they are expected to have similar inputs and outputs in terms of sediments and discharge. They are also expected to react similarly throughout to flow events and other stressors. They are studied semi-independently as each is expected to function in a manner that is at least slightly different from adjoining reaches. This allows for a meaningful characterization of a watercourse as the aggregate of reaches, or an understanding of a particular reach, for example, as it relates to a proposed activity.

Reaches are delineated based on changes in the following:

- Channel planform
- Channel gradient
- Physiography
- Land cover (land use or vegetation)
- Flow, due to tributary inputs
- Soil type and surficial geology
- Certain types of channel modifications by humans

This follows scientifically defensible methodology proposed by Montgomery and Buffington (1997), Richards et al. (1997), and the Toronto and Region Conservation Authority (2004).

A reach map is provided in **Appendix B**. Reaches within the Tewin Study Area consist of Bear Brook and Ramsay Creek Tributaries, labelled with a **BB** and **RC** prefix, respectively. Reaches are numbered downstream to upstream to provide geographic context. The extent of the Smith Gooding and Johnson Municipal Drains are also displayed on the mapping provided in **Appendix B**. Reaches situated along the drains are denoted with drain name prefix: Smith Gooding Municipal Drain (SG) and Johnson Municipal Drain (J).

Reach delineation was extended within the Tewin Study Area, while also including reaches along Ramsay Creek and Bear Brook downstream of the Study area to better identify areas sensitive to erosion. It

should be noted that field assessments were generally limited to reaches on participating lands within the Tewin Study Area.

3 Field Assessments

Field investigations along Bear Brook and Ramsay Creek were completed over several months between October 2021 and December 2023. Field investigations were completed on a reach-by-reach basis on participating properties within and downstream of the Tewin Development Lands.

Field assessments were completed along each accessible reach following standard, accepted protocols. Reach-by-reach observations generally included the following:

- Confirmation of desktop reach delineation extents
- Instream estimates of bankfull channel geometry
- Bed and bank material composition and structure
- Description of riparian vegetation type and cover
- Observations of erosion, scour, or deposition

Tables 1 and **2** summarize observations and measurements for all reaches within the Study Area for Bear Brook and Ramsay Creek, respectively. **Appendix D** provides supplemental field data for other reaches within the Tewin Secondary Plan Area for reference. Representative photographs are included in **Appendix E** to supplement and support the observations.

Table 1. General reach characteristics for Bear Brook reaches in Study Area

| | Avg. | Avg. | Substrate | | | Dinarian | | |
|-------------------|--|-----------------------|--|-----------------------|-------------|--|---|--|
| Reach | Bankfull Width (m) | Bankfull Depth (m) | Riffle | Pool | Valley Type | Vegetation | Notes | |
| BB5-5A | 11.2 | - | Unknow backw | vn due to vatering | Confined | Confined Trees, Grass, Herbaceous Fall/sloughing and minor undercutting; deep wate soft sediment prohibited depth measuremer | | |
| BB5-5A-2 | 1.8 | 0.5 | Clay, Silt, Sand | Clay, Silt, Sand | Confined | Trees dominant, Grasses | Woody debris jams present, bank angle 5-30% through mid to upstream extend, erosion predominant at downstream extent | |
| BB5-5A-3 | 7.2 | 0.9 | Gravel, Small Cobble, Large Cobble | Silt, Sand, Gravel | Confined | Reach modified by previous upstream beave Trees failure, evidence of undercutting, active bed a bank erosion | | |
| BB5-5A-3-1 | 5.0 | 1.5 | Gravel, Small Cobble, Parent | Silt, Sand Gravel | Confined | Trees | Reach break moved and heavily modified due to beaver pond and activity, leaning mature trees on eroded banks, | |
| BB5-5A-3- 1A | 4.7 | 1.4 | Clay, Silt, Sand | Clay, Silt, Sand | Unconfined | Trees, shrubs, grasses, herbaceous | Reach ends at beaver formed pond, channel appears stable, low entrenchment | |
| BB5-5A-3- 1A-1 | 4.7 | 1.4 | Clay, S | ilt, Sand | Unconfined | Trees | Instream vegetation heavy, characteristic of a ditch | |
| BB5-5A-3A | 5.4 | 1.5 | Clay, Silt, Gravel, Small Cobble | Clay, Silt | Confined | Trees, grasses, herbaceous | Reach backwatered due to large downstream beaver dam, instream logs and trees observed from bank failure, riffle-run development present | |
| BB5-5A-3B | 3.2 | 1.0 | Clay, Silt, Sand, Gravel | Clay, Silt, Sand | Unconfined | Grasses, Herbaceous | Increased sinuosity moving downstream, massive banks and valley wall failure observed, riffle-run development present | |
| BB5-5A-3B- 1 | 2.7 | 0.5 | No riffle-poo | l development | Unconfined | Trees, Herbaceous | Channel primarily dry and poorly defined, majority of erosion occurs in the downstream portion | |
| BB5-5A-3C | 5.6 | 1.9 | Clay, Silt, Gravel | Clay, Silt, Sand | Unconfined | Grasses, Herbaceous | Evidence of enlarging, erosion and minor adjustment may be related to beaver activity | |
| BB5-5A-3D | 6.3 | 2.5 | No riffle-poo | l development | Unconfined | Grasses | Channel backwatered from downstream beaver dam, high water levels, reach may have riffle-pool development under in absence of backwater conditions | |
| BB5-5A-3D- 1 | 3D- No defined channel, and no bankfull indicators No riffle-pool development | | l development | Unconfined | Grasses | Feature was characteristic of a ditch | | |
| BB5-5B | No defined channel, and no bankfull indicators | | No riffle-pool development | | Confined | Grasses, Herbaceous | Feature was characteristic of a large online pond at the time of assessment. Flows are restricted through a | |

| | Avg. | Avg. | g. Substrate | | | Dinarian | | |
|-----------------|--|-----------------------|--|---------------------|------------------|---|--|--|
| Reach | Bankfull Width (m) | Bankfull Depth (m) | Riffle | Pool | Valley Type | Vegetation | Notes | |
| | | | | | | | drain at the downstream extent prior to converging with BB5-5A | |
| BB5-5C | 7.8 | 1.0 | Clay, Silt, Sand, Gravel | Clay, Silt, Sand | Confined | Grasses | Wide agricultural swale, entrenched, multiple flow paths, riffle-run development, no deep pools observed, | |
| BB5-5C-1 | 7.9 | 1.3 | No riffle-poo | l development | Unconfined | Grasses, Herbaceous | Wide agricultural swale, entrenched, modified by agricultural activities, feature 100% run. | |
| BB5-5C-1A | 7.8 | 1.3 | No riffle-poo | l development | Unconfined | Grasses, Herbaceous | Wide swale, entrenched, accumulation of organics, no morphological adjustment in process | |
| BB5-5C-1A- 1 | 2.0 | 0.3 | No riffle-poo | l development | Unconfined | Grasses, Trees | Ditch-like characteristics of swale, heavily modified and straightened, several footbridges across, input from numerous storm drains/culverts from residential lots | |
| BB5-5C-1A- 2 | 1.5 | 0.3 | No riffle-poo | l development | Unconfined | Trees, Herbaceous | 100% runs, agricultural swale. Poorly defined with little geomorphic activity | |
| BB5-5D | 2 | 0.3 | No riffle-pool development | | Unconfined | Trees, Shrubs, Herbaceous | Flows may be perennial, leaning trees and shrubs on banks, feature 100% run, some sedimentation observed, no morphological adjustment in process | |
| BB5-5D-1 | 1.0 | 0.3 | No riffle pool development | | Unconfined | Trees, Shrubs, Herbaceous | Poorly defined feature flows behind residential lots. | |
| BB7 | BB7 Channel assessed from right of way, unable to full observations | | e to complete | Confined | Grasses, Trees | Limited channel access, undercutting and bank erosion observed | | |
| BB7-1 | | | | No | observations - n | on-participating lands | | |
| BB8 | | | R | leach outside of | Tewin study area | boundary but included | in mapping. | |
| BB8-1 | | | R | leach outside of | Tewin study area | boundary but included | in mapping. | |
| BB9 | 6.3 | 1.9 | Silt, Sand, Gravel | Clay, Silt, Sand | Unconfined | Grasses, Trees | Nearby beaver dam causing severe backwatering and intensifying erosion, dominated by runs | |
| BB10 | 4.8 | 2.8 | No riffle | Clay, Silt, Sand | Unconfined | Grasses, Herbaceous, Trees | No true riffles observed, high valley wall above stream banks, leaning trees, bank slumping and exposed tree roots observed, enlarging observed | |
| BB10-1 | 3.5 | 1.3 | Silt, Sand, Gravel | Clay, Silt, Sand | Unconfined | Grasses, Herbaceous | Downstream of golf course, J shaped trunks, no true riffles observed, reach dominated by runs, channel entrenched | |
| BB10-1A | 1.4 | 0.3 | Clay, Silt, Till | Clay, Silt, Till | Unconfined | Grasses, Trees | Narrow corridor of grasses through golf course, minor slumping observed, little geomorphic activity overall | |
| BB10-1B | 1.6 | 0.3 | Clay, Silt | Clay, Silt | Unconfined | Grasses | Straight ditch, all runs observed, algae and few cattails present, minor slumping observed, little geomorphic activity overall | |
| BB11 | 48 | 2.8 | Silt, Sand, Till | Silt, Sand, Till | Unconfined | Grasses | Straightened ditch, little geomorphic activity | |
| BB12 | 4.2 | 1.4 | Silt, sand, gravel, small cobble | Clay, silt, sand | Unconfined | Grasses, Herbaceous | Few pools observed, predominantly riffles and runs, sediment deposits observed through reach, evidence of enlarging | |

| | Avg. | Avg. | Sub | strate | | Dinarian | | |
|-------|-----------------------|-----------------------|-----------------------|---------------------|-------------|-----------------|--|--|
| Reach | Bankfull Width (m) | Bankfull Depth (m) | Riffle | Pool | Valley Type | Vegetation | Notes | |
| BB13 | 4.7 | 0.8 | Clay, Silt, Sand | Clay, Silt, Sand | Unconfined | Grasses, Shrubs | Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed | |
| BB14 | 3.8 | 1.0 | Clay, Silt, Sand | Clay, Silt, Sand | Unconfined | Grasses, Shrubs | Straight agricultural ditch, planform recovering towards sinuous, exposed till on bed and banks | |
| BB15 | 4.8 | 1.7 | Clay, Silt | Clay, Silt | Unconfined | Grasses | Straight ditched channel, heavy backwatering from large beaver dam, erosion less severe closer to downstream extent, minimal geomorphic activities | |
| BB16 | 4.1 | 1.2 | Clay, Silt, Gravel | Clay, Silt | Unconfined | Grasses | Straight ditched channel, channel morphology mostly comprised of runs | |

N/A – Measurements not possible either due to large channel size or lack of defined channel or poor bankfull indicators

| | Avg. | Avg. | Substrate | | | Dinarian | |
|-----------------|--|-----------------------|---------------------|---------------------|--------------------|--|--|
| Reach | Bankfull Width (m) | Bankfull Depth (m) | Riffle | Pool | Valley Type | Vegetation | Notes |
| RC4-1-1A | 4.8 | 0.7 | Clay, Silt | Clay, Silt | Unconfined | Trees, Grasses | Straight agricultural ditch, beaver dams retaining water, no flow observed, minor slumping observed, minimal geomorphic activity |
| RC4-1-1A- 1A | 5.3 | 0.9 | Clay, Silt, Sand | Clay, Silt, Sand | Unconfined | Trees, Grasses | Assessed as part of RCA-1-1A-1 |
| RCA-1-1A- 1 | 5.3 | 0.9 | Clay, Silt, Sand | Clay, Silt, Sand | Unconfined | Trees, Grasses | Former agricultural ditch, no flow observed, trees growing on channel bed, mostly stable |
| RCA-1-1A- 2 | 5.0 | 0.8 | Clay, Silt | Clay, Silt | Unconfined | Trees | Former agricultural ditch, no flow observed, trees growing on dry bed, minimal geomorphic activity |
| RCA-1-1A- 3 | 5.3 | 0.9 | Clay, Silt, Sand | Clay, Silt, Sand | Unconfined | Trees, Grasses | Assessed as a part of RCA-1-1A |
| RC5 | 5.1 | 0.7 | Clay, Silt | Clay, Silt | Unconfined | Trees, Herbaceous, Grasses | Shallow pooled water but no flow observed, grasses and wetland species observed growing on semi-dry bed, minimal geomorphic activity |
| RC5-1 | 4.8 | 1.0 | No riffle-poo | l development | Unconfined | Trees, Grasses | Straight agricultural ditch with some pools of water, no flow observed, some aquatic vegetation growing within channel |
| RC5-2 | | | | No obser | rvations due to po | oorly defined swale feat | ture |
| RC5-1-1 | 3.9 | 0.7 | No riffle-poo | l development | Unconfined | Grasses | Straight agricultural ditch with some pools of water, no flow observed, extreme riparian vegetation encroachment |
| RC5-1-2 | 1-2 2.7 0.5 No riffle-pool development | | l development | Unconfined | Grasses | Straight agricultural ditch with some pools of water, no flow observed, extreme riparian vegetation encroachment | |
| RC5-1-3 | 2.3 | 1.95 | No riffle-poo | l development | Unconfined | Grasses | Straight agricultural ditch with some pools of water observed. Extreme riparian vegetation encroachment |

Table 2. General reach characteristics for Ramsay Creek reaches in Study Area

3.1 Rapid Assessments

Channel instability was objectively quantified through the application of the Ontario Ministry of the Environment's (2003) Rapid Geomorphic Assessment (RGA). Observations were quantified using an index that identifies channel sensitivity based on evidence of aggradation, degradation, channel widening, and planimetric adjustment. The index produces values that indicate whether a channel is stable/in regime (score <0.20), stressed/transitional (score 0.21-0.40), or adjusting (score >0.41).

The Rapid Stream Assessment Technique (RSAT) was also employed to provide a broader view of the system as it considers the ecological function of the watercourse (Galli, 1996). Observations were made of channel stability, channel scouring or sediment deposition, instream and riparian habitats, and water quality. The RSAT score ranks the channel as maintaining a poor (<13), fair (13-24), good (25-34), or excellent (35-42) degree of stream health. Due to the absence of flowing water at the time of assessment, the RSAT was not applied.

A summary of RGA and RSAT scores for all the assessed reaches within and downstream the Tewin Development Block are provided in **Tables 3 and 4** below. The observations are supplemented and supported with representative photographs included in **Appendix E**.

Table 3. Rapid geomorphological assessment results for Bear Brook reaches in Study Area

| | | RGA (MOE, 200 | 3) | | RSAT | (Galli, 1996) | | |
|-------------------|-------------------------|---------------|--------------------------------------|--------------------------------------|---------------------------|---|--|--|
| Reach | Score | Condition | Dominant Systematic Adjustment | Score | Condition | Limiting Feature(s) | | |
| BB5-5A | 0.18 In Regime Widening | | 27 | Good | Physical instream habitat | | | |
| BB5-5A-2 | 0.30 | In Transition | Widening | 20 | Fair | Physical instream habitat | | |
| BB5-5A-3 | 0.61 | In Adjustment | Degradation | 23 | Fair | Channel scouring/ Sediment deposition | | |
| BB5-5A-3-1 | 0.41 | In Adjustment | Degradation | 24 | Fair | Channel souring/sediment deposition, Channel stability | | |
| BB5-5A-3-1A | 0.08 | In Regime | Widening | 31 | Good | Physical instream habitat/riparian habitat conditions | | |
| BB5-5A-3- 1A-1 | | | N/A feat | ure characterized | as swale | | | |
| BB5-5A-3A | 0.26 | In Transition | Widening | 23 | Fair | Channel scouring/sediment deposition | | |
| BB5-5A-3B | 0.29 | In Transition | Widening | 17 | Fair | Physical instream habitat | | |
| BB5-5A-3B-1 | | | N/A feat | ure characterized | as swale | | | |
| BB5-5A-3C | 0.17 | In Regime | Widening | 22 | Fair | Riparian habitat conditions | | |
| BB5-5A-3D | 0.20 | In Regime | Widening | 25 | Good | Riparian habitat condition | | |
| BB5-5A-3D-1 | | | N/A feat | ure characterized | as swale | | | |
| BB5-5B | | | N/A feat | ure characterized | as swale | | | |
| BB5-5C | 0.11 | In Regime | Planimetric adjustment | 24 | Fair | Riparian habitat conditions | | |
| BB5-5C-1 | | | N/A feat | ure characterized | as swale | | | |
| BB5-5C-1A | | | N/A feat | ure characterized | as swale | | | |
| BB5-5C-1A-1 | | | N/A feat | ure characterized | as swale | | | |
| BB5-5C-1A-2 | | 1 | N/A feat | ure characterized | as swale | 1 | | |
| BB5-5D | 0.17 | In Regime | Planimetric adjustment | 30 Good Physical instream conditions | | | | |
| BB5-5D-1 | | 1 | N/A feat | ture characterized as swale | | | | |
| BB7 | 0.26 | In Transition | Widening | 25 Good Channel stability | | | | |
| BB7-1 | | | No observa | tions. Non-partici | pating lands | | | |
| BB8 | | | Reach out of Tewin stud | dy area boundary | but included in mappir | ıg | | |
| BB8-1 | | T | Reach out of Tewin stud | dy area boundary | but included in mappir | ig | | |
| BB9 | 0.31 | In Transition | Degradation | 17 | Fair | Riparian habitat conditions | | |
| BB11 | 0.23 | In Transition | Widening | 25 | Good | Riparian habitat conditions | | |
| BB10 | 0.26 | In Transition | Widening | 20 | Fair | Riparian habitat conditions | | |
| BB10-1 | 0.19 | In Regime | Widening | 19 | Fair | Riparian habitat conditions | | |
| BB10-1A | 0.23 | In Transition | Degradation | 27 | Good | Riparian habitat conditions | | |
| BB10-1B | 0.18 | In Regime | Aggradation | 23 | Fair | Riparian habitat conditions | | |
| BB12 | 0.29 | In Transition | Widening | 21 | Fair | Riparian habitat conditions | | |

| | | RGA (MOE, 2003) | | | RSAT (Galli, 1996) | | | | |
|-------|-------|-----------------------|--------------------------------------|-------|--------------------|--|--|--|--|
| Reach | Score | Condition | Dominant Systematic Adjustment | Score | Condition | Limiting Feature(s) | | | |
| BB13 | 0.21 | In Transition | Widening | 25 | Good | Riparian habitat conditions | | | |
| BB14 | 0.32 | In Transition | Widening | 23 | Fair | Channel stability | | | |
| BB15 | 0.19 | In Regime Aggradation | | 24 | Fair | Physical instream habitat/Riparian habitat conditions | | | |
| BB16 | 0.29 | In Transition | Widening | 22 | Fair | Channel stability | | | |

Table 4. Rapid geomorphological assessment results for Ramsay Creek reaches in Study Area

| | | RGA (MOE, 20 | 03) | | RSAT | ' (Galli, 1996) | | |
|-------------|--|--------------------|--------------------------------------|-------------------|---|---|--|--|
| Reach | Score | Condition | Dominant Systematic Adjustment | Score | Condition | Limiting Feature(s) | | |
| RC4-1-1A | 0.12 | In Regime | Widening | 28 | Good | Physical instream habitat/water quality | | |
| RC4-1-1A-1A | 0.09 | In Regime | Widening | 25 | Good | Physical instream habitat | | |
| RC4-1-1A-1 | 0.09 | In Regime | Widening | 25 | Good | Physical instream habitat | | |
| RC4-1-1A-2 | 0.09 | In Regime | Widening | 26 | Good | Physical instream habitat | | |
| RC4-1-1A-3 | 0.09 | In Regime Widening | | 25 Good | | Physical instream habitat | | |
| RC5 | 0.09 In Regime Widening | | 30 Good | | Physical instream habitat | | | |
| RC5-1 | 0.04 In Regime | | Planimetric Adjustment | 19 | Fair | Physical instream habitat/Riparian habitat conditions | | |
| RC5-2 | | | N/A featu | ure characterized | as a swale | | | |
| RC5-1-1 | 0.04 | In Regime | Planimetric Adjustment | 19 | Fair | Physical instream habitat/Riparian habitat conditions | | |
| RC5-1-2 | 0.04 In Regime Planimetric Adjustment | | 19 | Fair | Physical instream habitat/Riparian habitat conditions | | | |
| RC5-1-3 | RC5-1-3 N/A feature characterized as a swale | | | | | | | |

MORPHIX

3.2 Detailed Geomorphological Assessment

Following the rapid field assessments, detailed geomorphological assessments were completed on seven reaches within the Tewin Study area and along downstream reaches within both the Bear Brook and Ramsay Creek watersheds. Detailed assessment locations were selected based on those reaches identified as most sensitive to erosion through a review of RGA scores and reach-level observations of current channel conditions.

Detailed assessments were completed on the following reaches: **BB5**, **BB5-5**, **BB5-5A-3**, and **BB-6** in October 2021. Additionally, detailed assessments were completed along the most sensitive downstream reaches of Ramsay Creek and Bear Brook at **BB1**, **RC1** and **RCB** in the summer of 2022 and winter of 2023. The locations of these sites are indicated in **Appendix B**.

For each assessment, the following activities were completed along an approximately 100 m length of the reach:

- Long profile of the channel bed, water level, and bankfull channel extent to determine channel bed and bankfull gradients, as well as water surface slope on the given day
- 8-10 detailed cross-sectional surveys of the channel to document average bankfull channel geometry
- Detailed instream measurements at each cross-section location including bankfull channel geometry, riparian vegetation type and cover conditions, bank material composition and structure, bank height/angle, presence of undercutting, and bank root density
- Bed material sampling at each cross-section location following a modified Wolman's (1954) Pebble Count Technique or substrate sample for laboratory grain size analysis

The detailed assessments' results are summarized below in **Table 5**. Summaries of the detailed assessments are available in **Appendix F**.

| | | | | Reach | | | |
|--|-------|-------|-------|--------------|-------|-------|-------|
| Channel parameter | BB1 | BB5 | BB5-5 | BB5- 5A-3 | BB6 | RC1 | RCB |
| Measured | | | | | | | |
| Average bankfull channel width (m) | 9.63 | 5.97 | 4.34 | 6.22 | 4.73 | 6.30 | 5.85 |
| Average bankfull channel depth (m) | 1.22 | 0.82 | 0.59 | 0.37 | 0.94 | 0.79 | 0.80 |
| Bed gradient (%) | 0.04 | 0.09 | 0.22 | 0.56 | 0.23 | 0.03 | 0.26 |
| Bankfull gradient (%) | 0.03 | 0.02 | 0.20 | 0.47 | 0.21 | 0.20 | 0.27 |
| D ₅₀ (mm) | <2 | <2 | <2 | 7.5 | <2 | <2 | <2 |
| D ⁸⁴ (mm) | <2 | <2 | <2 | 17 | <2 | <2 | <2 |
| Manning's n roughness coefficient | 0.055 | 0.040 | 0.040 | 0.040 | 0.040 | 0.045 | 0.045 |
| Computed | | | | | | | |
| Bankfull Discharge (m³/s)* | 4.88 | 3.20 | 1.99 | 2.23 | 2.23 | 4.87 | 4.67 |
| Average bankfull velocity (m/s)* | 0.42 | 0.66 | 0.78 | 0.97 | 0.88 | 1.10 | 1.00 |
| Bankfull shear stress (N/m ²) | 4.79 | 7.22 | 11.51 | 20.39 | 19.34 | 13.90 | 21.23 |

Table 5. Average channel parameters for detailed assessment sites

*Based on Manning's Equation

4 Erosion Hazard Assessment

4.1 Methodology

River and stream systems are dynamic in nature, changing and evolving due to erosional forces associated with flowing water and local slope composition and structure. Defining an erosion hazard for a given watercourse is useful for determining potential impacts or hazards to proposed activities adjacent to a given watercourse. It should be noted that unconfined and confined valley systems are assessed differently when defining the erosion hazard for a creek system. The Ontario Ministry of Natural Resources and Forestry (MNRF) outlines an approach for establishing the erosion hazard in both unconfined and confined systems.

The erosion hazard is delineated as a meander belt width in unconfined systems. Unconfined systems are those with poorly defined valleys or slopes well outside where the channel could realistically migrate. Unconfined systems are generally found within glaciated plains with flat or gently rolling topography. The meander belt width can be applied in unconfined systems based on 20 times the bankfull channel width. Alternatively, the meander belt width can be determined through a detailed geomorphological study that examines the largest channel meanders observed through historical and recent aerial photograph interpretation. The meander belt width can then be graphically defined using orthorectified aerial imagery by determining the channel centerline and central tendency (i.e., meander belt axis). In cases where the channel is not discernible in aerial photographs or has been substantially modified, empirical models can be used to estimate the meander belt width.

Confined systems are those where the watercourse is contained within a defined valley, where contact between the watercourse and a valley wall is possible. The Ontario Ministry of Natural Resources and Forestry (MNRF) outlines an approach for establishing the erosion hazard where watercourses are confined by valley walls. In confined systems, the erosion hazard is based on a combination of a toe erosion allowance and stable slope allowance. This approach defines an appropriate erosion setback or toe erosion allowance from a channel bank where the creek is within 15 m of the toe of the valley slope. A toe erosion allowance can be determined in several ways: use of an average annual recession rate; application of a 15 m toe erosion allowance in areas where the channel is within 15 m of the toe of slope; or use of soil information and field observations of geomorphic processes (MNRF, 2002). The stable slope allowance is determined through a valid geotechnical slope stability study.

It should be noted that South Nation Conservation considers confined systems as those with valley walls equal to or greater than 3 m in height (Ontario Regulation 170/06). Valley wall height can be confirmed through a combination of field observations and a desktop assessment of detailed topographic data. Ultimately, the final erosion hazard in confined systems is based on an appropriate toe erosion allowance (where the channel is within 15 m of the valley toe) and the stable slope allowance, as determined by a valid geotechnical study. Valley confinement and overall erosion hazards for confined systems have been identified by Paterson Group (2024).

4.2 Results

4.2.1 Unconfined Valley Reaches

When limited information is available, meander belt widths can be applied based on 20 times the bankfull channel width. A more detailed approach would include an assessment of the largest channel meanders observed through historical and recent aerial photography. In cases where the channel is not discernible in aerial photographs or the channel has been substantially modified, empirical models are also used to estimate the meander belt width.

A review of recent and historical aerial imagery was completed. Still, it did not indicate the presence of significant meanders along any of the reaches, either due to poor aerial coverage or the frequent presence of historically modified (i.e., straightened) drainage networks. Based on our review through the historical aerial record and our field observations, unconfined reaches within the Study Area are generally small and straightened. As such, measuring meander amplitudes through a formal overlay analysis of historic and recent aerial imagery was not possible. Given the limitations associated with the



aerial imagery and existing conditions of the creeks, definition of the erosion hazard for reaches within the Tewin Study Area was based on an empirical modelling approach to determine a range of potential meander belt widths.

The empirical relation from Williams (1986) was applied using average bankfull channel dimensions measured in the field by GEO Morphix to estimate the meander belt width (B_w) for each reach such that:

$$B_w = 4.3W_b^{1.12} + W_b$$

[Eq. 1]

where W_b is average bankfull channel width (m). An additional 20 percent factor of safety was also applied.

A meander belt width was also calculated based on the Toronto Region Conservation Authority (TRCA) (2004) empirical model:

$$B_w = -14.827 + 8.319 \ln (\rho g Q S * D A)$$

[Eq. 2]

where ρ is water density (1000 kg/m³), *g* is acceleration due to gravity (9.8 m/s²), *Q* is discharge (m³/s), *S* is channel slope (m/m), and *DA* is drainage area (km²). The parameters used for the TRCA meander belt width values are provided in **Appendix G**, for reference. It is anticipated that review and refinement of existing meander belt widths may be carried out during future detailed studies, which will include more site-specific hydrological input data.

Note that one standard error was also applied to the TRCA meander belt width calculation. Two standard errors are applied to large channels and where hydrological regime changes are anticipated. In this case, the reaches throughout the Study Area are relatively small, straight, and have shown limited to no change in cross-sectional geometry over the extent of our historical review. It is also anticipated that any future changes in hydrology will be addressed through adequate stormwater management. As such, one standard error is considered appropriate for all reaches.

Results of the empirical modelling exercise and preliminary recommendations for meander belt widths are outlined in **Table 6**. The preliminary meander belt widths are also mapped in **Appendix B**, for reference. The preliminary meander belt widths are provided for informational purposes.

| Reach | **TRCA (2004) Meander Belt Width (m) | **Modified Williams Width (1986) Meander Belt Width with Factor of Safety (m) | Preliminary Meander Belt Width Proposed (m) |
|---------------|--|---|---|
| BB5-5A-3-1A | * | 37 | 37 |
| BB5-5A-3-1A-1 | * | 35 | 35 |
| BB5-5A-3B | 20 | 23 | 48 |
| BB5-5A-3B-1 | * | 19 | 19 |
| BB5-5A-3C | 20 | 42 | 48 |
| BB5-5A-3D | 20 | 48 | 48 |
| BB5-5A-3D-1 | * | 17 | 17 |
| BB5-5C-1 | 30 | 62 | 30 |
| BB5-5C-1A | 30 | 61 | 30 |
| BB5-5C-1A-1 | * | 14 | 14 |
| BB5-5C-1A-2 | * | 10 | 10 |
| BB5-5D | * | 14 | 14 |
| BB5-5D-1 | * | 6 | 6 |
| BB9 | 48 | 48 | 48 |
| BB10 | 48 | 36 | 48 |
| BB10-1 | 23 | 25 | 25 |
| BB10-1A | * | 9 | 9 |
| BB10-1B | 9 | 11 | 11 |
| BB11 | 48 | 36 | 48 |
| BB12 | 48 | 31 | 48 |
| BB13 | 44 | 35 | 44 |
| BB14 | 44 | 28 | 44 |
| BB15 | 42 | 36 | 42 |
| BB16 | 42 | 30 | 42 |
| RC5 | * | 38 | 38 |

Table 6. Preliminary meander belt widths for unconfined reaches in Study Area

* Indicates negative values

** Includes 20% Buffer/Factor of Safety to account for potential under prediction; or 1 standard error for TRCA

It should be noted that the TRCA model is largely governed by drainage area and, as such, has difficulty predicting meander belt widths for small, low-order features. This can often result in negative values for the final predicted meander belt width. These values are non-sensical. As such, we recommend applying the meander belt widths determined based on Williams (1986), especially for small, low order streams. The William's equation was developed based on a dataset from natural channels, but it still provides an approach for erosion hazard delineation in modified systems. There is limited channel planform development on these reaches due to previous modifications (i.e., channel straightening), and the bankfull channel size is likely exaggerated because of ditching activities. As such, the meander belt widths are likely conservative based on the exaggerated field bankfull channel geometries. Furthermore, a modified version of the Williams equation has been used, which includes an additional bankfull channel width and additional factor of safety.

Note that meander belt widths are only provided on participating properties within the Tewin Study Area. The meander belt widths are considered preliminary and are subject to refinement following further field and desktop data review/analysis to be undertaken as part of more detailed planning

studies. In cases where enhancement or restoration activities are proposed, meander belt widths or erosion hazards would be refined for those features through future design stages.

4.2.2 Confined Valley Reaches

The Ontario Ministry of Natural Resources and Forestry (MNRF) outlines an approach for defining an appropriate erosion setback or toe erosion allowance either through use of an average annual recession rate; application of a minimum 15 m toe erosion allowance; or use of soil information and field observations of geomorphic processes (MNRF, Table 3, 2002).

Given the lack of visible channel definition and meanders through aerial photographs, an average annual recession rate could not be determined for confined reaches. A toe erosion allowance was ultimately applied based on field observations of geomorphic processes and local surficial geology, as per the MNRF Table 3 (2002). Results of the desktop assessment and field observations documented by the geotechnical consultant were also considered in the recommendation for toe erosion allowances.

Based on field observations of stiff clays and silts along channel banks and areas of modest, discontinuous erosion, we recommend a toe erosion allowance in the range of 5-8 m for all confined reaches where the channel is within 15 m of the valley slope. This recommendation also considers field observations made by the geotechnical consultant that identify "stiff, brown silty clay, which was underlain by firm, grey silty clay" as the material comprising the majority of slopes along the channels observed (Patterson, 2024). The 5-8 m range is also appropriate given the general stability of the watercourses, with little to no channel adjustment evident in aerial photographs or LiDAR data. Confined reaches where the erosion hazard is addressed by the toe erosion allowance are shown in the mapping provided under **Appendix B**. Note that confined reaches were determined based on a combination of field observations and a review of detailed topographic data for the Study Area (e.g., LiDAR).

Notably, the toe erosion allowance is one component of the erosion hazard delineation required for confined systems where the channel is situated within 15 m of the valley wall (MNRF, 2002). In addition to the toe erosion allowance, a stable slope allowance and erosion access allowance is also required. A slope stability assessment has been completed by Paterson Group and is summarized under separate cover (*Existing Conditions - Geotechnical: Tewin Lands dated September 2024*).

Meander belt widths have been provided for several reaches that were classified as confined by Paterson Group (2024). In these cases, adjacent slopes are close to SNC's 3 m slope height threshold for confinement. The meander belt widths for these reaches are provided for information and for situations where a reach may be found to be partially confined or where the SNC's 3 m height threshold is not met. Given that valley confinement is ultimately a geotechnical slope stability matter, the final erosion hazard extent for confined systems is based on the work completed by Paterson Group (2024).

5 Crossing Assessment

An assessment of existing drainage crossings that overlap with the potential servicing lines was completed in November and December 2022. This preliminary assessment aimed to provide information on potential crossing locations for future servicing infrastructure. Data gathered from this assessment are for information purposes and greater review will be required once the servicing strategy is better understood.

The proposed servicing lines run along specific existing roadways within and adjacent to the Tewin Study Area boundaries; a map of the proposed servicing lines is provided in **Appendix H**. The assessment involved identifying and documenting all crossing structures along the proposed route and observing the drainage ditches and watercourses upstream and downstream of the crossing structures. In total, 36 crossings were identified. Streams cross the proposed route at 16 of the 36 crossings. The other 20 crossings are either roadside ditches or agricultural ditches. Bankfull width and depth, plus any erosion and/or deposition observed near the stream crossings, was documented. A summary of the assessment is provided in **Appendix H**.

6 Summary of Preliminary Opportunities

Based on the information provided in this report, the strategic planning and community design objectives for Tewin, and the commitment to exploring bold and innovative strategies for Tewin, the following section identifies a series of preliminary opportunities for consideration. These preliminary opportunities may help inform the next phase of the integrated master planning and EA process and can be used to frame community design options and technical solutions.

The main activities relating to fluvial geomorphology completed to date include a large-scale characterization of the existing watercourses within the Tewin Lands, detailed geomorphological assessments at erosion-sensitive locations, determination of preliminary meander belt widths and toe erosion setbacks, and a high-level analysis of potential future impacts to Bear Brook downstream of the Study area.

Standard rapid geomorphological assessments (RGA/RSAT) were completed to document the existing conditions and characterize the dominant channel-forming processes of all watercourses within the study area. Through this, preliminary erosion hazard setbacks were delineated, and a baseline inventory of channel conditions and sensitive channel reaches was developed, which can serve, in part, as reference material moving forward. The identified sensitive channel locations were subject to further study by application of detailed geomorphological field assessments. Through this, detailed information relating to channel geometry, gradient, substrate, and bank conditions was obtained. This information will serve as a basis for the determination of erosion thresholds and erosion mitigation criteria for future stormwater management planning. The desktop-based analyses (**Appendix A**) provide high-level inference regarding potential impacts to the downstream channel and proximal infrastructure as a consequence of the proposed Tewin Study Area. This information, in part, can inform appropriate mitigation strategies.

Field characterizations indicate that the watercourse features within the Tewin Lands are generally degraded, largely from past and present agricultural activities. Many channel corridors have been evidently straightened, leading to the re-development of sinuous low-flow channels within the corridor and causing significant bank erosion. Riparian conditions across many of the major channels are often compromised, reducing stability and erosion resistance within the channel banks. Bed substrate is predominantly sand with observations of clay and silt also commonly noted throughout the study area, indicating potential excess sedimentation due to agricultural activities, as well as generally sensitive channel conditions.

Considering the aforementioned field characterizations, there exist many potential opportunities to improve existing channel conditions through future mitigation and enhancement activities. Opportunities generally relate to improving long-term channel stability, water quality, and overall stream health, as many watercourses within the study area are evidently degraded and negatively impacted by prior modification. Potential opportunities relating to fluvial geomorphology within and downstream of the Tewin Lands include, but are not limited to the following:

- Localized erosion mitigation and stabilization works within existing channels can address existing erosion issues
- Potential realignment of certain watercourse features following natural channel design can accommodate modifications to hydrological regimes in an appropriate manner
- Enhancements can be made to existing channel corridors to help reconnect watercourse features with the surrounding floodplain, and subsequently improve floodplain conditions
- Determination and field-validation of erosion thresholds at erosion-sensitive watercourse reaches, and the application of continuous hydrological and long-term erosion models can determine appropriate erosion mitigation criteria for stormwater management facilities
- Improvements to water quality and stream health can be achieved through stormwater management facility and outfall designs, including local landscape restoration plans
- General reference to this existing conditions report can assist in facilitating future related studies, and in providing a baseline characterization from which to ensure the integrity of the watercourses within and downstream of the Tewin Lands is maintained or improved upon following any hydrological modification



7 Conclusion

The aim of this existing conditions report was to synthesize all geomorphological observations collected to date for the tributaries of Bear Brook and Ramsay Creek within the Tewin Study Area in the City of Ottawa, Ontario.

Various fluvial geomorphic assessments have been completed to date to characterize the existing conditions of the watercourse and drainage features. This included a detailed desktop review of available geology, topography, and drainage area characteristics, watercourse reach delineation, rapid and detailed geomorphological assessments, as well as a preliminary erosion hazard assessment in support of constraint delineation. In addition to the existing conditions characterization, a desktop-based geomorphological inventory and assessment (**Appendix A**) was also completed.

Preliminary opportunities for watercourse-related enhancements have been explored based on the existing conditions characterizations. This information provides a baseline reference geomorphological characterization that will, in part, support future environmental and related studies for the Tewin Study Area.

We trust this report meets your current requirements. If you have any questions, please contact the undersigned.

Respectfully submitted,

Paul Villard Ph.D., P.Geo., CAN-CISEC, EP, CERP Director, Principal Geomorphologist

Kat Woodrow, M.Sc. Manager of Watershed Studies

8 References

Brierley, G. J. and Fryirs, K. A. 2005. Geomorphology and River Management: Applications of the River Styles Framework. Blackwell Publishing, Oxford, UK, 398pp.

Downs, P.W. 1995. Estimating the probability of river channel adjustment. Earth Surface Processes and Landforms, 20: 687-705.

Galli, J. 1996. Rapid Stream Assessment Technique, Field Methods. Metropolitan Washington Council of Governments.

J.F. Sabourin and Associates (JFSA). (2024). Tewin Lands: Cumulative Hydrologic Impact Assessment.

Ministry of Environment (MOE). 2003. Ontario Ministry of Environment. Stormwater Management Guidelines.

Montgomery, D.R. and J.M. Buffington. 1997. Channel-reach morphology in mountain drainage basins. Geological Society of America Bulletin, 109 (5): 596-611.

Ontario Geological Survey (OGS). 2003. Surficial Geology of Southern Ontario.

Richards, C., Haro, R.J., Johnson, L.B. and Host, G.E. 1997. Catchment and reach-scale properties as indicators of macroinvertebrate species traits. Freshwater Biology, 37: 219-230.

Toronto and Region Conservation Authority (TRCA). 2009. Don River Watershed Plan Implementation Guide.

Vermont Agency of Natural Resources (VANR). 2007. Step 7: Rapid Geomorphic Assessment (RGA). Phase 2 Stream Geomorphic Assessment

Appendix A Desktop Geomorphological Assessment of Bear Brook

Bear Brook Desktop Geomorphological Inventory and Assessment

Highway 417 to South Nation River



Prepared for: Taggart Investments and Algonquins of Ontario 3187 Albion Road South Ottawa, ON K1V 8Y3

Submitted: September 18, 2024

GEO Morphix Project No. 22024



| Ver. | Purpose/Change | Authored by | Approved by | Date |
|------|--|-------------|-------------|------------|
| 1.0 | | K. Woodrow | P. Villard | 2023-06-30 |
| 1.1 | Updated reference date for JFSA study (2024) | K. Woodrow | P. Villard | 2024-09-18 |
| | | | | |
| | | | | |
| | | | | |

Disclaimer

This report presents professional opinions and findings of a scientific and technical nature based on the knowledge and information available at the time of preparation. This document is prepared solely for the Client, and the data, interpretations, suggestions, recommendations, and opinions expressed in the report pertains only to the project being completed for the Client.

GEO MORPHIX**

Table of Contents

| 1 | Introd | luction | 1 |
|---|------------|--|---|
| 2 | Background | | |
| | 2.1 | Study Context and Objectives | 2 |
| | 2.2 | Study Extent | 2 |
| 3 | Geom | orphological Assessment Methods | 3 |
| | 3.1 | Watershed Characteristics | 3 |
| | 3.2 | Historical Aerial Image Analysis | 3 |
| | 3.3 | Valley Segment Delineation | 3 |
| | 3.4 | Context of Hydrological Inputs | 4 |
| | 3.5 | Point of Interest Inventory | 4 |
| 4 | Geom | orphological Assessment Results | 5 |
| | 4.1 | Watershed Characteristics and Historical Aerial Imagery Analysis | 5 |
| | 4.2 | Valley Segment Delineation | 6 |
| | 4.3 | Cumulative Hydrologic Impact Review | 8 |
| | 4.4 | Point of Interest Inventory1 | 0 |
| 5 | Concl | usion1 | 1 |
| 6 | Refer | ences1 | 2 |

GEO MORPHIX**

List of Figures

List of Tables

| Table 1: Subcategories for Points of Interest | . 5 |
|--|-----------|
| Table 2: Valley Segment Descriptions | . 7 |
| Table 3: Node Locations and Drainage Areas (JFSA, 2024) | . 8 |
| Table 4: Modelled 2-Year 24-Hour SCS Peak Flows (JFSA, 2024) and Estimated J32 Sub-Catchment Fractions | Q2 . 9 |
| Table 5: Point of Interest Inventory Breakdown | 10 |

Appendices

Appendix A.1: Study Area Mapping

Appendix A.2: Hydrological Node Locations

Appendix A.3: Surficial Geology Mapping

Appendix A.4: Historical Aerial Imagery

Appendix A.5: Geomorphological Points of Interest Locations

1 Introduction

This report provides a summary of the desktop-based geomorphological inventory and assessment conducted by GEO Morphix Ltd. (GEO Morphix) along Bear Brook, downstream of the Tewin Lands. The main Tewin Lands Study Area is located in southeast Ottawa, generally bordered by Leitrim Road to the north, Farmers Way to the east, Thunder Road to the south, and Anderson Road and Ramsayville Road to the west. The main Tewin Lands Study Area is outlined in **Figure 1** below.



Figure 1. The Tewin Study Area is identified in black outline

Bear Brook, which drains a significant portion of the Tewin Lands, is a tributary of the South Nation River and drains a total area of approximately 490 km² on the east side of the City of Ottawa. The study area associated with the desktop and hydrologic assessments extends along the main channel from Highway 417 to its confluence with South Nation River. A map of the desktop geomorphological inventory and assessment study area is provided in **Appendix A.1**. GEO Morphix would like to highlight that the purpose of the desktop geomorphological assessment is not to encourage intervention at any identified Point of Interest. Rather, the purpose of these assessments was to document existing conditions and the extent of potential future concerns along the Bear Brook main channel as areas within its headwaters undergo land use changes. Ultimately, the content of the geomorphological inventory will help contextualize and facilitate future studies upstream, as well as help inform the potential requirement for localized downstream erosion mitigation measures, where necessary.

The assessments described in this report examined characteristics in a hierarchical, nested approach in terms of spatial scale. The Bear Brook watershed was assessed at the watershed/sub-watershed scale, then reach scale, then sub-reach and geomorphic unit scale. The following are the tasks completed for analysis:

- Review of watershed characteristics (e.g., surficial geology, topography, land cover/use);
- Division of the main channel through the study area into "valley segments";

- Historical aerial imagery analysis to identify historical geomorphological and anthropogenic changes along the channel and channel corridor;
- An inventory of Points of Interest observed in the aerial imagery at which the Bear Brook main channel may have higher sensitivity to proposed future land use changes;
- Cumulative hydrologic impact assessment of Bear Brook and select tributaries for multiple hydrological scenarios and storm conditions (JFSA, 2024).

The following sections expand upon and provide context for these tasks. The results are presented in tabular format in the appropriate sections below, and supporting maps and other materials are provided in the appendices.

2 Background

2.1 Study Context and Objectives

The Desktop geomorphological assessment examined approximately 40 kilometers of the Bear Brook main channel downstream of the Tewin Lands. The study area extends along the main channel from Highway 417 to its confluence with South Nation River. A map of the study area is provided in **Appendix A.1**. The purpose of this analysis was to observe the Bear Brook main channel to document existing geomorphological conditions and locations that may be more sensitive to changes in the watershed where potential future concerns are most likely to arise within the channel corridor and riparian area. These locations, referred to as "Points of Interest", include locations where notable geomorphological activity, adjacent infrastructure, and past river modifications were observed in historic and contemporary aerial imagery of the study area.

Channel morphology and planform are largely governed by the flow regime and the availability and type of sediments (i.e., surficial geology) within a stream corridor. Physiography, topography, riparian vegetation, and land use also physically influence the channel. These factors provide insight into existing conditions and sensitivity to potential land use changes. The sensitivity of watercourse features, from a geomorphological perspective, is a function of driving and resisting forces and the controls that influence these forces. Driving forces are a product of drainage area, discharge, and slope (including channel and valley gradient). Resisting forces are a product of physiography and surficial geology (including parent materials and substrate). It is important to note that modifications to driving and resisting forces also impact channel sensitivity. These modifications may include riparian vegetation and historical modifications to channel form and function.

Conducting this analysis as a desktop exercise allowed a nested approach with observations at multiple spatial scales at which watershed/sub-watershed characteristics, reaches (i.e., "valley segments"), sub-reaches/geomorphic units, and Points of Interest were observable. This was done with the intent of identifying potential future concerns. The results from this desktop geomorphological assessment could be used to inform future, smaller scale analyses within the study area if they are warranted. We note that this assessment was completed solely as a desktop exercise using the highest resolution aerial imagery we could obtain, and that no associated fieldwork has been completed to verify results.

2.2 Study Extent

In terms of identifying an appropriate geographical extent of analysis for determining potential geomorphological impacts from changes to hydrology, the Toronto and Region Conservation Authority (TRCA) suggests that the limit of significant downstream impacts is associated with the capacity of the downstream watercourse to assimilate changes in hydrology (TRCA, 2012). Further, smaller streams and smaller drainage areas have less assimilation capacity are more sensitive than larger streams and drainage areas. This is due to the size of the features. The simplest method of identifying the potential capacity of a watercourse to assimilate changes in hydrology is to assess the relative scales of modified drainage area to the receiving watercourse's drainage area, or compare 2-year flows (TRCA, 2012). Specific to the relationship between drainage area and impact of land use changes, the Credit Valley Conservation Authority (CVC) recommends that calculations for downstream impact of land use changes
downstream to a point where the area of land use changes is 10% of the total drainage area (CVC, 2012). The extent of the study area for the Desktop geomorphological assessment was determined considering the above information. Thus, the study area extends from the headwaters to the confluence between Bear Brook and South Nation River. Upstream of this confluence along Bear Brook, approximately 3% of the total drainage area is associated with the Tewin Study Area. As such, the study area sufficiently captures the extent of the potential geomorphological impacts associated with future changes to hydrology.

3 Geomorphological Assessment Methods

3.1 Watershed Characteristics

To inform and provide context to the assessment, watershed characteristics were observed through a GIS mapping and spatial data review exercise. Watershed and sub-watershed boundaries (JFSA, 2024) were mapped along with the Bear Brook main channel and tributaries. Physiography, surficial geology, and topography layers were mapped as well to examine the relative changes in these characteristics along the main channel corridor. A map showing the course of the main channel and the surficial geology underlying it is provided in **Appendix A.3**. Aerial imagery was also analyzed to identify land use/cover.

Data reviewed as part of this analysis include the following:

- Surficial Geology Ministry of Northern Development and Mines (2010);
- Physiography of Southern Ontario Chapman and Putnam (1984);
- Watersheds Minor City of Ottawa (2021);
- Sub-watersheds City of Ottawa (2021);
- Ottawa High Resolution Digital Elevation Model Natural Resources Canada (2020).

3.2 Historical Aerial Image Analysis

Aerial imagery from readily available sources was examined to determine the extent of historical changes within the channel and its corridor due to anthropogenic and natural influences. The aerial imagery was also used in dividing the main channel into valley segments and identifying points of interest. Open source basemap imagery is available through the City of Ottawa open data website, which includes years 1965, 1976, 1991, 1999, 2005, 2010, 2011, 2014, 2015, 2017, and 2019. Each year was examined to determine qualitative historical channel adjustment and past modifications. At this time, channel migration rates were not explicitly calculated to quantitatively assess historical channel adjustment. Orthorectified imagery from the years 1965, 1976, and 2018 was used as the base imagery for maps presented in the appendices. Aerial imagery from the City of Ottawa occasionally did not extend to the downstream sections of Bear Brook, given its distance from the Ottawa city center. Where City of Ottawa datasets were unavailable, ArcGIS basemap imagery (2019), Google Earth, and other open-source aerial images were used to supplement City of Ottawa datasets.

3.3 Valley Segment Delineation

Characteristics of the main channel and adjacent landscape through the study area were observed throughout the review of watershed characteristics and historical aerial imagery analysis. The main channel was subsequently divided into "valley segments" based on observations made throughout those respective analyses. Valley segments are similar to reach breaks, which are sections of homogenous channel dominated by similar geomorphological qualities and processes, such as channel planform, gradient, physiography, and land cover. However, valley segments differ from reaches in that they are typically longer and have more flexibility in geomorphological qualities. The main features used to define valley segments in this desktop analysis are historical processes, underlying geology, channel form, anthropogenic channel modifications, surrounding land use, and riparian cover. For example, a break between valley segments was delineated at a location corresponding with a marked change in channel planform from relatively low-amplitude meanders to high-amplitude, tortuous meanders.

3.4 Context of Hydrological Inputs

The results of the Cumulative Hydrologic Impact Assessment (JFSA, 2024) were reviewed to inform anticipated geomorphological impacts along Bear Brook. The purpose of the cumulative hydrological impact review was to characterize the capacity of Bear Brook assimilate changes in hydrology associated with land-use changes within the Tewin Study Area, ultimately providing additional context to the overall geomorphological assessment. A total of six (6) hydrological scenarios produced by JFSA (2024) were reviewed for the assessment. Q_2 flows and contributing drainage areas were analyzed across the scenarios at six (6) different model nodes along Bear Brook and other tributaries, downstream of the Tewin Lands. Cross-scenario comparison of contributing flows at each node location allowed for inference regarding high-level hydrological (and consequently, potential geomorphological) impacts and the mitigating effects of SWM controls.

3.5 Point of Interest Inventory

Points of Interest (POIs) are locations at the sub-reach or geomorphic unit scale where the Bear Brook main channel may have higher sensitivity to future land use changes upstream due to historical human modification or ongoing geomorphological adjustments, for example. POIs were identified using aerial imagery available from the City of Ottawa. POIs observed in the imagery were assigned a category: Geomorphological Feature, Infrastructure, and Past Alterations (described below). A subcategory was assigned to each POI as well to provide a greater level of detail in the results. **Table 1** contains descriptions of each subcategory.

Geomorphological Features: Areas with aerial image evidence of channel adjustment.

Infrastructure: Areas of infrastructure adjacent to the channel, within approximately 20 m.

Past Alteration: Areas which, through historical imagery analysis, show signs of previous alterations by anthropogenic influences within the channel.

Table 1: Subcategories for Points of Interest

| Geomorphological Features | | | | | |
|---------------------------|--|--|--|--|--|
| v | Outside Meander Bend: A meander bend which exhibits signs of active erosion greater than a typical meander bend. | | | | |
| | Point Bar: Areas with point bar formation, visible in aerial images. Notable especially if the point bar is in areas where point bars are not typical (i.e. outside meander bend) | | | | |
| | Widening: Areas where the bank is showing signs of active erosion, such as gullies or rills. Or historical photograph analysis shows clear signs of channel widening. | | | | |
| loge | Large Woody Debris: Woody debris or leaning trees. | | | | |
| Subcate | Planimetric Adjustment: Any signs visible in the aerial image which could indicate that the creek is adjusting planimetrically. Examples include remnant channels, cutoff channels, medial bars, islands, or multi-channel formation. | | | | |
| | Uncharacterized Channel Adjustment: Creek adjustment is occurring and visible in aerial imagery, but the type is undefinable. | | | | |
| | Saturated Conditions/Impoundment: Saturated/impounded areas that affect the stream, such as backwatering or vegetation encroachment.* | | | | |
| | Aggradation: Evidence of aggradation such as sediment lobes, sandy streaks, or point bar accretion. | | | | |
| Infrastructure | | | | | |
| gory | Property: Locations where noticeable private or public property is adjacent to a location of possible increased erosion due to the channel. Distance to the channel is measured from nearest adjacent buildings or fence. | | | | |
| ubcat | Road: Any location where a road either crosses the creek or is adjacent to an area of possible increased erosion due to the channel. | | | | |
| S | Pedestrian Bridge: Locations of pedestrian bridge crossings across the channel. | | | | |
| | Past Alterations | | | | |
| ory | Weirs or Dams: Based on aerial image analysis, locations of possible weirs or dams. Status is unknown until structures can be verified in field. | | | | |
| categ | Straightening: Based on historical aerial images analysis available, locations of possible historical creek straightening. | | | | |
| Sub | Bank Protection: Any locations of bank protection visible in aerial images. From the desktop analysis, a majority of treatments appear to be rip-rap. | | | | |

* Not in technical sense; not evaluated.

4 Geomorphological Assessment Results

4.1 Watershed Characteristics and Historical Aerial Imagery Analysis

Bear Brook flows through a range of physiographic units and glacial and alluvial surficial geology deposits within the study area. A map showing the course of the main channel, the valley segments delineated for this assessment (denoted below in brackets as 'dBB#'), and the underlying surficial geology is provided in **Appendix A.3**. Upstream of the Highway 417 crossing (dBB1), the physiography varies between sand plains, till plains, and clay plains. Within the farthest upstream headwaters area streamflow is almost entirely through straightened and widened channels. The underlying surficial geology in this area is fine- to medium-grain sands that are glaciofluvial and glaciomarine in origin (surficial geology unit 11c). These materials are non-cohesive and more susceptible to erosion than cohesive materials (i.e., clays/till).

There is a distinct change in surficial geology as the headwaters approach Hwy 417; this area is underlain by silt and clay glaciomarine deposits (unit 10a). This surficial geology unit underlies the largest proportion of the main channel throughout the study area. The relatively straight, single-thread channels

in this section flow through well-defined floodplains. Downstream of this, as Bear Brook approaches its crossing with Hwy 417, stream channels with irregular and partially confined meanders traverse deltaic deposits of medium- to fine-grain sand (unit 11a). Node J32 is located in this area. Downstream of the Hwy 417 crossing, the surficial geology once again transitions to the glaciomarine clay deposits (unit 10a), and the trajectory of Bear Brook switches from northwest to easterly immediately downstream of the railway crossing south of Russell Road.

Downstream of the Hwy 417 crossing, the physiography is entirely clay plains, expect for one short section of kame moraine, comprised of sand and gravel. In the vicinity of Boundary Road (dBB2), the channel flows for several hundred meters across sand deposits associated with abandoned floodplain sediments (unit 12). Downstream of this point (dBB3), and until the Frank Kenny Road crossing, the stream flows almost entirely in a channel that has incised into the clay glaciomarine deposits described above (unit 10a). Node MK_DN5 is located in this area. Between Frank Kenny Road and Dunning Road (dBB4-dBB5), Bear Brook alternates between flowing through a compact sandy and silty glacial deposit (unit 5b) and the clay glaciomarine deposit (unit 10a). Node J23 is located near Frank Kenny Road in this section. The channel briefly flows through coarser, poorly sorted sand to boulder sized deposits that are glaciofluvial in origin (unit 7) in the vicinity of the Dunning Road crossing (dBB5).

Downstream of the Dunning Road crossing (dBB5-dBB6) it flows through the compact sandy and silty deposit (unit 5b) until just upstream of its crossing with Russell Road in the vicinity of the intersection with Saumure Road (dBB7-dBB8), at which point the underlying surficial geology returns to the clay glaciomarine deposits (unit 10a). Node J13 is located in this area. Between Indian Creek Road and Drouin Road (dBB9), a short section of Bear Brook flows through sand deposits associated with abandoned floodplain sediments again (unit 12). The watercourse flows through the clay glaciomarine deposits (unit 10a) (dBB10) again until the Bouvier Road crossing. Node J9 is located in this area. Here the surficial geology becomes dominated by modern alluvial deposits (unit 19) and the meander amplitudes progressively increase as Bear Brook approaches its confluence with the South Nation River (dBB11-dBB12). Node Sink-1 is located in this final section in valley segment dBB11.

The area surrounding Bear Brook is dominated by agricultural land uses with some residential properties as well. Bear Brook appears to have been straightened for a majority of the length examined, likely to accommodate agriculture. Most of the work occurred prior to 1965, which is the earliest imagery date examined. Prior to historical straightening, Bear Brook was sinuous with compound meandering form, oxbow lakes, wetlands, and a wide floodplain, as evidenced by channel remnants and geomorphological scars visible in the imagery. Contemporary Bear Brook is a straightened, single channel with narrow riparian zones and limited wetlands. Aerial photographs in 1965 indicate the land use was primarily agricultural with extremely limited riparian cover. In aerial imagery from 1976, areas of previously tilled agriculture begin to 'naturalize', as riparian cover appears to increase and more wetlands are apparent compared to the 1965 imagery. There is limited evidence of bank protection structures, although in-field verification would be required to confirm this.

4.2 Valley Segment Delineation

The Bear Brook main channel through the study area was divided into 12 valley segments to facilitate more detailed observations within localized geomorphological context. Valley segments are labelled sequentially from upstream to downstream. A map of the valley segments is provided along with the study area map in **Appendix A.1**. Descriptions of valley segments are provided below in **Table 2**. The extent of historical aerial imagery examined is provided in **Appendix A.4**.

Table 2: Valley Segment Descriptions

| Name | Description |
|------|---|
| dBB1 | dBB1 is sinuous and the location where the watercourse changes direction from flowing generally north to flowing generally east is within this segment, which is perhaps part of an original compound meander. There is evidence of older, more sinuous channels in the aerial imagery such as meander scars along this segment. Land use has varied greatly throughout the years, from open field, forest, wetland, and hedge row. The railway and Russell Road area constrain the movement of the creek here. There is also a property occupied by a lumber operation north of Russell Road and east of Spring Street just upstream of the segment break between dBB1 and dBB2. Based on aerial photographs, the site was constructed between the years 2005 and 2017 and owners have artificially adjusted the creek, creating a cutoff channel to straighten the channel away from their buildings. A vehicle crossing over the watercourse was constructed on this property between 2008 and 2011 to expand the area of operation. |
| dBB2 | The valley segment dBB2 is a single channel section of Bear Brook, straightened prior to 1965 to accommodate agriculture and the Boundary Road crossing. Between the years 1965 and 2019, the land surrounding the creek was permitted to naturalize. Today, it appears as shrubby wetland with grassy vegetation encroachment into the channel. Pockets of agriculture still exist along the south bank, but tilling is not as extensive as in 1965. |
| dBB3 | dBB3 is the longest valley segment delineated and is defined by its form and agricultural field land cover throughout the years. The confluence with McKinnons Creek is within this segment. The creek is straight throughout this segment with occasional meanders. There is little riparian cover through this segment, with tilled agriculture along most of the channel. Based on aerial imagery analysis, these conditions have remained the same since at least 1965. There is a fragmented forest stand near Milton Road and this area could be considered its own segment in a more localized assessment. Downstream of Milton Road, a remnant bed is visible in aerial imagery. However, the remnant bed must have formed before 1965, as there has been no change in the channel form between the years 1965 and 2019. Location iv for the drainage characterization is within this segment. |
| dBB4 | The riparian zone of dBB4 is agricultural land cover with little riparian cover. The valley segment dBB4 differs from other segments with its more sinuous form. There are signs the creek has been straightened downstream of Rockdale Road. Evidence of its previously sinuous channel form can be seen in the remnant bed, which is situated in a small pocket of 'naturalized' forest. This remnant channel bed is visible in aerial imagery prior to 2011. The confluence with Shaw Creek and location v for the drainage characterization are within this segment. |
| dBB5 | The valley segment dBB5 is defined by a heterogenous land cover and channel forms. A mix of private property, agricultural fields, and a golf course comprise the land use. The riparian cover varies between lawns and tilled agriculture. The planform is single channel with high amplitude meanders that flow into a golf course. |
| dBB6 | There is abundant evidence of previous straightening by human influence within the valley segment dBB6. In aerial images as recent as 1976, dBB6 is multi-channel, with islands, and oxbow wetlands. There is historical evidence of a large tributary discharging into this segment, which is not visible in modern aerial imagery. |
| dBB7 | Unlike other sections of Bear Brook, the valley segment dBB7 is highly sinuous and does not show signs of historical straightening. The meander of greatest amplitude along dBB7 is highly active with evidence of bank degradation, point bars, and compound meander formation. Widening, rills, and gullies can be seen in the aerial imagery, even along the inner bank of the meander bend. Other dynamic geomorphological processes such as backwatering and wetland formation is visible in aerial imagery from 2019. |
| dBB8 | The valley segment dBB8 is a long and homogenous section of creek with forested riparian cover and single channel form. The current riparian cover is modern, as it is only visible in imagery after 1976. There is planimetric adjustment in the valley segment dBB8 evidenced by an island forming in the upstream sections. |
| dBB9 | Valley segment dBB9 is single channel with meandering form. The meander amplitude in this segment is larger than dBB8 and is dominated by different geomorphological processes; there is no evidence of planimetric adjustment such as island formation in the aerial imagery. The riparian cover of this valley segment is forest and there is little evidence of historical straightening. The meanders are asymmetrical in shape and are unique to this segment. South Indian Creek discharges into Bear Brook within this segment. |

| Name | Description |
|-------|--|
| dBB10 | The valley segment dBB10 is a single channel with straightened form. There are several confluences with tributaries within this segment. There is more limited aerial imagery available this distant from the Ottawa City center, so only modern coverage was available. his segment is homogenous with forested riparian cover. The surficial geology of dBB10 is classified as modern floodplain alluvial deposits, unlike any other segment upstream. This indicates Bear Brook was once large enough within this segment to form a floodplain and deposit enough sediment to influence surficial deposits. |
| dBB11 | The valley segment dBB11 is sinuous with single channel form. The surficial geology is also modern alluvial sediment, and the riparian cover is dominated by forest. Major land use remains agriculture. Schnupp Road constrains any lateral movement of the meander in the downstream section. North Indian Creek discharges into Bear Brook within this segment. |
| dBB12 | The most recognizable valley segment, dBB12, is distinct in its meandering form. This segment is highly sinuous and forms the most downstream section of Bear Brook before its confluence with South Nation River. An oxbow feature can be observed in modern aerial imagery. Also unique to dBB12, Ettyville Road and Boileau Road were built to mirror the curves of the channel, but now possibly restrict and limit the movement of adjacent meanders. |

4.3 Cumulative Hydrologic Impact Review

The Cumulative Hydrologic Impact Assessment (JFSA, 2024) assessed the potential discharge contributions of different subcatchments within the Bear Brook watershed for multiple hydrological scenarios and storm conditions. The study area extends from just upstream of Hwy 417 to a few kilometers upstream of the confluence with the South Nation River near the town of Bourget.

Flow and drainage area information was extracted at six (6) hydrological model nodes. A map of the node locations within the study area is provided in **Appendix A.2** and a description of the node locations and their respective drainage areas is provided below in **Table 4**. Of particular significance, Node J32 resides near the downstream extent of Bear Brook within the Tewin Study Area, and consequently best captures the drainage contributions from within. We note that Node J32 has a drainage area of 49.98 km², of which, no more than 14.2 km² are attributable to the Tewin Study Area. As such, the results stated in this review are conservative with regards to the actual drainage contributions from the Tewin Lands.

| Location* | Node | Upstream Drainage Area (km²) | J32 Proportion of Downstream Drainage Areas |
|---|--------|------------------------------------|---|
| On Bear Brook south (upstream) of Hwy 417 adjacent to Hall Road (upstream of dBB1) | J32 | 49.98 | 1.00 |
| On McKinnons Creek east of Mer Bleue near the confluence with Bear Brook (dBB3) | MK_DNS | 33.61 | 1.49 |
| On Bear Brook adjacent to Frank Kenny Road (dBB3) | J23 | 175.88 | 0.28 |
| On Bear Brook east of Ruissellet Road (dBB7) | J13 | 232.74 | 0.21 |
| On Bear Brook east of Drouin Road (dBB10) | JG | 372.39 | 0.13 |
| Near Champlain Road on Bear Brook main channel (dBB11) | Sink-1 | 447.20 | 0.11 |

Table 3: Node Locations and Drainage Areas (JFSA, 2024)

*The respective Valley Segment where each flow node is located is indicated in brackets

The HEC-HMS software, developed by the Hydrologic Engineering Center (HEC) of the U.S. Army Corps of Engineers (USACE) was employed by JFSA to provide drainage area and discharge estimates for six nodes within the watershed: one along a channel within a subcatchments to Bear Brook and five along the main channel of Bear Brook. The HEC-HMS model prepared by JFSA is based a HEC-HMS originally prepared by South Nation Conservation (SNC) in the scope of the Bear Brook and Tributaries Flood

Hazard Mapping Report (2022). Sub-catchment boundaries and hydrologic parameters (e.g., proposed imperviousness) of the original SNC model were revised for the purposes of this assessment to capture the respective contributions and alterations of proposed land-use scenarios. The design storm volume used for JFSA revised HEC-HMS (48.47 mm 2-year 24-hour SCS) was derived from the IDF curves in the City of Ottawa Storm Sewer Design Guidelines.

A total of six (6) scenarios, based on the SNC "summer" hydrologic model, were assessed and modelled in HEC-HMS. Negligible differences noted for a number of scenarios, and as such, only the Existing Conditions (Scenario 1), Uncontrolled (Scenario 2) and Controlled (Scenario 3) scenarios are presented. The Uncontrolled scenario reflects urbanized or high-runoff conditions without SWM controls in the subcatchment where Tewin Lands are located, whereas the Controlled scenario reflects urbanized/highrunoff conditions with SWM controls implemented.

Summarized results from the Cumulative Hydrological Impact Assessment conducted by JFSA (2024) are provided below. The Q_2 discharge metric refers to the flood discharge with a theoretical return period of two years (i.e., exceedance probability of 50% in any given year) and is shown in **Table 5**. In a geomorphological context, the Q_2 flood discharge estimate provides a reasonable approximation of the bankfull discharge in alluvial stream channels. The Q_2 fractions are also presented in **Table 5** and show the relative proportion of Q_2 flows originating from sub-catchment area J32 (i.e. at the downstream extent of the Tewin Lands) at each sub-catchment area downstream along Bear Brook, until the terminal Sink-1 node.

| | Existing Conditions | | Uncontrolled Scenario | | Controlled Scenario | |
|--------|---------------------|-------------------------|-----------------------|-------------------------|---------------------|-------------------------|
| Node | Q₂ Flow (m³/s) | Q ₂ Fraction | Q₂ Flow (m³/s) | Q ₂ Fraction | Q₂ Flow (m³/s) | Q ₂ Fraction |
| J32 | 3.7 | 1.00 | 7.3 | 1.00 | 3.58 | 1.00 |
| MK_DNS | 18.4 | 0.20 | 18.40 | 0.40 | 18.38 | 0.19 |
| J23 | 28.9 | 0.13 | 33.00 | 0.22 | 28.70 | 0.12 |
| J13 | 43.2 | 0.09 | 46.50 | 0.16 | 42.65 | 0.08 |
| J6 | 53.6 | 0.07 | 56.20 | 0.13 | 52.77 | 0.07 |
| Sink-1 | 62.5 | 0.06 | 64.90 | 0.11 | 61.63 | 0.06 |

Table 4: Modelled 2-Year 24-Hour SCS Peak Flows (JFSA, 2024) and Estimated J32Sub-Catchment Q2 Fractions

The net discharge outputs from the sub-catchment represented by node J32 are estimated to range between 3.52 to 3.90 m³/s for all scenarios besides the Uncontrolled Scenario, which has an estimated Q_2 output of 7.30 m³/s. In the Existing Conditions and Controlled scenarios, the Q_2 contribution fraction of node J32 drops below 13% upon reaching node J23, approximately 13 km downstream. In the uncontrolled scenario, the Q_2 fraction at J23 is 22%. Q_2 fractions continue to decrease moving downstream. Flow contributions associated with node J32 in the Controlled and Existing Conditions scenarios account for approximately 6% of the discharge at the Sink-1 Node, which captures most of the Bear Brook watershed. The Uncontrolled Scenario estimate accounts for approximately 11% of the discharge at the Sink-1 node.

Overall, the results show that the proportion of urban flows originating from the Tewin Lands represent a small fraction of the total flows within the downstream sections Bear Brook relative to the respective drainage areas. For instance, node J32 only accounts for 6% of the Q_2 flows at node Sink-1, despite occupying approximately 11% of the Sink-1 drainage area. This suggests that with appropriate SWM controls, the urban flows from the Tewin Lands are not expected to adversely affect the downstream sections of Bear Brook, and in particular, the points of interest identified in Section 1. We note that these results are conservative given the fact that Node J32 captures drainage from additional lands,

external to the Tewin Lands and Subject Area. As such, Q_2 fractions at Sink-1 that are purely associated with the Tewin Lands are likely to range from 0.02 – 0.04.

4.4 Point of Interest Inventory

An inventory of points of interest was compiled through this preliminary desktop analysis, including geomorphological features, infrastructure, and past alterations along Bear Brook. A total of 117 locations of interest were found. A breakdown of POIs into the categories and subcategories is presented in **Table 3**.

| Geomorphological Features | | | | | | |
|---------------------------|------------------------------------|----|---------------------|--|--|--|
| | Outside Meander Bend | 3 | | | | |
| | Point Bar | 5 | | | | |
| Ž | Widening | 9 | Total: | | | |
| tego | Large Woody Debris | 21 | | | | |
| ıbca | Planimetric Adjustment | 6 | 54 | | | |
| SL | Uncharacterized Channel Adjustment | 2 | | | | |
| | Saturated Conditions/Impoundment 4 | | | | | |
| | Aggradation | 4 | | | | |
| | Infrastructure | | ſ | | | |
| lory | Property | 15 | | | | |
| categ | Road | 29 | Total: 52 | | | |
| Sub | Pedestrian Bridge | 8 | | | | |
| | Past Alterations | | | | | |
| ory | Weir or Dam | 3 | | | | |
| Subcateg | Straightening | 6 | Total: 11 | | | |
| | Bank Protection | 2 | | | | |

Table 5: Point of Interest Inventory Breakdown

The most common geomorphological feature observed was large woody debris, which is typically associated with channel widening processes. Point bars, channel widening processes, and planimetric adjustment processes were observed in relatively moderate frequencies, indicating some level of ongoing channel adjustment along Bear Brook. Road crossings and channel encroachment in proximity to roads was commonly observed throughout the study extent. Encroachment onto properties was also frequently observed. In total, infrastructure-related points of interest were most common, indicating locations that are sensitive to changes in hydrology and may consequently requires some level of mitigation activities to address the associated risks. Past alterations were typically associated with agricultural activities, such as channel straightening. Several weirs and dams, and occasional bank protection measures were identified within the study extent.

Detailed maps of the locations of all points of interest are provided in **Appendix A.5**. Accompanying descriptions of each POI are provided within **Appendix A.5** as well. This inventory is to inform decision making with regards to requirements for future studies, and provide a baseline characterization of Bear

Brook from which to facilitate potential mitigation activities associated with changes to the hydrological regime.

5 Conclusion

GEO Morphix conducted a desktop-based geomorphological inventory and assessment along Bear Brook on the east side of the City of Ottawa, summarized herein. Results from the Cumulative Hydrological Impact Assessment completed by JFSA (2024) were summarized to provide context and further exemplify the relatively minor (from a geomorphological perspective) drainage contributions from the Tewin Lands. The purpose of this desktop analysis was to document existing conditions and the extent of potential future concerns along the Bear Brook main channel as areas within its headwaters undergo land use changes. Existing geomorphological conditions are documented through the review of watershed characteristics, the historical aerial image analysis, and valley segment delineation. The Points of Interest inventory documents the extent of potential future concerns along Bear Brook. GEO Morphix does not encourage intervention at any identified Points of Interest. Rather, the outcome of this desktop analysis is intended as documentation for areas of potential concern that may be identified by other stakeholders. This inventory, in part, will serve to facilitate future land use changes in the Tewin Subject Lands upstream.

We trust this memo meets your current requirements. Should you have any questions, please contact us.

Respectfully submitted,

Paul Villard Ph.D., P.Geo., CAN-CISEC, EP, CERP Director, Principal Geomorphologist

Kat Woodrow, M.Sc. Manager of Watershed Studies

6 References

Chapman, L.J., and Putnam, D.F. (1984). Physiography of Southern Ontario; Ontario Geological Survey, Map P.2715. Scale 1:600 000.

Credit Valley Conservation (CVC). 2012. Stormwater Management Criteria.

J.F. Sabourin and Associates (JFSA). (2024). Tewin Lands: Cumulative Hydrologic Impact Assessment.

Ontario Watershed Information Tool: https://www.lioapplications.lrc.gov.on.ca/OWIT/Index.html?viewer=OWIT.OWIT&locale=en-ca

Toronto and Region Conservation Authority (TRCA). 2012. Stormwater Management Criteria.

Appendix A.1: Study Area Mapping





✓ Watercourse

Appendix A.2: Hydrological Node Locations





Watershed

Ottawa, Ontario



Minor Watersheds: City of Ottawa, 2011. Morphix June 2023. PN22024. Drawn By: L.L., M.O., K.S.

Appendix A.3: Surficial Geology Mapping



Appendix A.4: Historical Aerial Imagery













Main Branches

✓ Watercourse

Valley Segments - 1976 Aerial Imagery

Ottawa, Ontario

Imagery: Google Earth, 2018/City of Ottawa,1965,1976. Watercourse: MNRF, 2021. Main Branch/Valley Segment Delineation: GEO Morphix Ltd.,2022. Print Date: March 2023. PN22024. Drawn By: L.L.,M.O.





✓ Watercourse

Ottawa, Ontario

Appendix A.5: Geomorphological Points of Interest Locations













Main Branch

igodolPast Alteration



Ottawa, Ontario

Imagery: Google Earth, 2018. Watercourse: OHN, 2020. Main Branches, Valley Segment Delineation, Points of Interest: GEO Morphix Ltd., 2022. Print Date: June 2023. PN22024. Drawn By: M.O., L.L.

























| # | Valley Segment | Category | Sub- category | Notes |
|----|-------------------|-----------------------------|-------------------------|---|
| 1 | dBB1 | Infrastructure | Road | Highway 417 Crossing |
| 2 | dBB1 | Infrastructure | Property | VIA Rail crossing over Bear Brook |
| 3 | dBB1 | Infrastructure | Road | Russell Road approximately ~10 m from channel |
| 4 | dBB1 | Infrastructure | Property | VIA Rail ~10 m from the outer bank of meander bend |
| 5 | dBB1 | Infrastructure | Road | Hall Road crossing and likely straightened section Bear Brook |
| 6 | dBB1 | Past Alteration | Straightening | Previous channel straightened before 1965 (remnants of previous sinuous channel can be seen in 1965 aerial imagery) |
| 7 | dBB1 | Geomorphological Feature | Saturated Conditions | Isolated saturated conditions with vegetation encroachment, creek remains well defined |
| 8 | dBB1 | Infrastructure | Road | Russell Road is ~10 m from the creek along an outer meander bend |
| 9 | dBB1 | Geomorphological Feature | Large Woody Debris | Large woody debris across active channel |
| 10 | dBB1 | Infrastructure | Property | Building of Carlsbad Springs Bath House at the outer meander bend, ~ 10 m from bank |
| 11 | dBB1 | Infrastructure | Property | Building along the bank of Bear Brook |
| 12 | dBB1 | Infrastructure | Road | Russell Road bridge |
| 13 | dBB1 | Infrastructure | Property | Commercial lot at the outer meander bend, buildings ~10 m from top of bank |
| 14 | dBB1 | Past Alteration | Weirs or Dams | Dam or diversion structure placed to maintain artificial cutoff channel, placed between 2005 and 2011 |
| 15 | dBB1 | Infrastructure | Pedestrian Bridge | Bridge over artificial cutoff channel |
| 16 | dBB1 | Infrastructure | Pedestrian Bridge | Commercial road bridge over Bear Brook |
| 17 | dBB2 | Past Alteration | Weirs or Dams | Weir or dam isolating artificially dugout cutoff channel |
| 18 | dBB2 | Infrastructure | Property | Property adjacent to creek with loss of riparian vegetation |
| 19 | dBB2 | Infrastructure | Road | Boundary Road bridge |
| 20 | dBB2 | Geomorphological Feature | Aggradation | Medial bar formation between 1976 and 2019 |
| 21 | dBB2 | Geomorphological Feature | Aggradation | Medial bar formation between 1976 and 2019 |
| 22 | dBB2 | Geomorphological Feature | Saturated Conditions | Isolated saturated conditions, creek remains defined |
| 23 | dBB3 | Infrastructure | Road | Carlsbad Lane Road bridge |
| 24 | dBB3 | Past Alteration | Weirs or Dams | Structure perpendicular to active channel, crossing type not discernable, possibly beaver dam |
| 25 | dBB3 | Infrastructure | Road | Milton Road bridge |

| # | Valley Segment | Category | Sub- category | Notes |
|----|-------------------|-----------------------------|---------------------------|--|
| 26 | dBB3 | Infrastructure | Pedestrian Bridge | Farm crossing, status unknown |
| 27 | dBB3 | Infrastructure | Pedestrian Bridge | Crossing for agricultural uses, must be field verified |
| 28 | dBB3 | Past Alteration | Straightening | Channel has been intermittently straightened for ~2.5 km (likely agricultural activities) |
| 29 | dBB4 | Infrastructure | Road | Road culvert for Frank Kenny Road |
| 30 | dBB4 | Geomorphological Feature | Large Woody Debris | Debris jam in centre of active channel, possibly a beaver dam |
| 31 | dBB4 | Infrastructure | Road | Rockdale Road culvert |
| 32 | dBB4 | Geomorphological Feature | Large Woody Debris | Debris jam in centre of active channel, possibly a beaver dam |
| 33 | dBB4 | Past Alteration | Straightening | Channel straightening completed prior to 1976 |
| 34 | dBB5 | Infrastructure | Pedestrian Bridge | Pedestrian bridge on golf course |
| 35 | dBB5 | Infrastructure | Property | Building ~15 m from channel |
| 36 | dBB5 | Infrastructure | Road | McNeely Road culvert |
| 37 | dBB5 | Infrastructure | Pedestrian Bridge | Pedestrian bridge |
| 38 | dBB5 | Infrastructure | Road | Whispering Willow Drive along outer meander bend, ~15 m from bank |
| 39 | dBB5 | Infrastructure | Pedestrian Bridge | Pedestrian bridge on golf course |
| 40 | dBB5 | Geomorphological Feature | Meander Bend | Outside meander bend <20 m from Magladry Rd |
| 41 | dBB5 | Infrastructure | Property | Building off Madladry Rd is ~5 m from river bank |
| 42 | dBB5 | Infrastructure | Pedestrian Bridge | Pedestrian bridge for either trail or golf course |
| 43 | dBB5 | Infrastructure | Road | Road culvert for Dunning Road |
| 44 | dBB5 | Past Alteration | Straightening | Straightened section of channel through agricultural fields (occurred prior to 1965) |
| 45 | dBB5 | Infrastructure | Road | Road culvert for Sarsfield Road |
| 46 | dBB6 | Geomorphological Feature | Planimetric Adjustment | Channel previously more sinuous (formation of cutoff channel) |
| 47 | dBB6 | Past Alteration | Straightening | Aerial imagery suggests remnants of previous channel, channel likely previously straightened |
| 48 | dBB6 | Geomorphological Feature | Saturated Conditions | Impoundment causing backwatering in channel and saturated conditions in riparian zone |
| 49 | dBB6 | Infrastructure | Road | Road culvert for Ruissellet Road |
| 50 | dBB6 | Infrastructure | Property | Property loss on outside meander bend |
| 51 | dBB6 | Infrastructure | Property | Building ~30 m from banks of a straight portion of the creek |

| # | Valley Segment | Category | Sub- category | Notes |
|----|-------------------|-----------------------------|---------------------------|--|
| 52 | dBB7 | Geomorphological Feature | Saturated Conditions | Backwatering due to impoundment within portion of the creek |
| 53 | dBB7 | Geomorphological Feature | Planimetric Adjustment | Bank erosion or valley wall contact, evidence of rills and overland flow erosion on both banks, possibly indicating planimetric adjustment |
| 54 | dBB7 | Geomorphological Feature | Point Bar | Large point bar formation |
| 55 | dBB7 | Infrastructure | Property | Farm buildings ~20 m of active meander bend |
| 56 | dBB7 | Geomorphological Feature | Widening | Bank erosion, evidence of gullies and rills |
| 57 | dBB7 | Geomorphological Feature | Widening | General bank erosion, fracture line and slumping |
| 58 | dBB7 | Geomorphological Feature | Point Bar | Large point bar formation and slope erosion on opposite bank |
| 59 | dBB7 | Geomorphological Feature | Widening | Evidence of bank erosion (creek adjustment) |
| 60 | dBB7 | Geomorphological Feature | Planimetric Adjustment | Island formation and possible medial bar, indicates planimetric adjustment |
| 61 | dBB7 | Geomorphological Feature | Large Woody Debris | Large woody debris, likely result of fallen trees potentially from bank erosion |
| 62 | dBB7 | Geomorphological Feature | Uncharacterized | General bank erosion |
| 63 | dBB7 | Geomorphological Feature | Planimetric Adjustment | Medial bars or islands, evidence of planimetric adjustment |
| 64 | dBB7 | Geomorphological Feature | Point Bar | Point bar formation at valley wall contact |
| 65 | dBB7 | Geomorphological Feature | Widening | Evidence of bank erosion, with formation of rills and gullies |
| 66 | dBB7 | Geomorphological Feature | Aggradation | Sediment accumulation in centre of channel, possible medial bar |
| 67 | dBB7 | Geomorphological Feature | Widening | Bank erosion, evidence of gullies and rills |
| 68 | dBB8 | Infrastructure | Road | Birchgrove Road runs parallel to outside meander bend (bank is ~10 m from road) |
| 69 | dBB8 | Past Alteration | Bank Protection | Boulder or riprap treatment along the bank (road protection) |
| 70 | dBB8 | Geomorphological Feature | Large Woody Debris | Large woody debris |
| 71 | dBB8 | Infrastructure | Road | Russell Road bridge and road culvert |
| 72 | dBB8 | Geomorphological Feature | Large Woody Debris | Large woody debris, deposition in channel is evidence of island or bar formation |
| 73 | dBB9 | Geomorphological Feature | Planimetric Adjustment | Possible island formation (evident through historical aerial imagery) |
| 74 | dBB9 | Geomorphological Feature | Large Woody Debris | Large woody debris in creek |
| 75 | dBB9 | Geomorphological Feature | Large Woody Debris | Large woody debris in area |
| 76 | dBB9 | Geomorphological Feature | Point Bar | Large point bar |

| # | Valley Segment | Category | Sub- category | Notes |
|-----|-------------------|-----------------------------|-----------------------|---|
| 77 | dBB9 | Infrastructure | Road | Road culvert for Indian Creek Road |
| 78 | dBB9 | Geomorphological Feature | Large Woody Debris | Series of large woody debris blockages |
| 79 | dBB9 | Geomorphological Feature | Large Woody Debris | Large woody debris extends across active channel |
| 80 | dBB9 | Infrastructure | Property | Stormwater management pond and outfall adjacent to outside meander bend |
| 81 | dBB9 | Infrastructure | Property | Buildings of private property sits ~30 m away from bank, outer bend is constricted by road bridge |
| 82 | dBB9 | Infrastructure | Road | Drouin Road bridge |
| 83 | dBB10 | Past Alteration | Bank Protection | Bank protection, status unknown |
| 84 | dBB10 | Past Alteration | Straightening | Possible straightened section of creek through agricultural land, ~4 km long |
| 85 | dBB10 | Geomorphological Feature | Large Woody Debris | Large woody debris extends across active channel |
| 86 | dBB10 | Infrastructure | Road | Bouvier Road bridge |
| 87 | dBB10 | Geomorphological Feature | Uncharacterized | Bank slump (tree loss) |
| 88 | dBB11 | Geomorphological Feature | Widening | Bank has slumped, erosion and rills are evident |
| 89 | dBB11 | Geomorphological Feature | Widening | Bank erosion, erosion, and rills evident |
| 90 | dBB11 | Geomorphological Feature | Large Woody Debris | Large woody debris (likely man-made) |
| 91 | dBB11 | Infrastructure | Property | Property adjacent to outer meander bend |
| 92 | dBB11 | Infrastructure | Property | Three buildings ~10 m to channel |
| 93 | dBB11 | Infrastructure | Road | Champlain Street Road bridge, oblique to creek |
| 94 | dBB11 | Geomorphological Feature | Point Bar | Large point bar formation along inside meander bend |
| 95 | dBB11 | Geomorphological Feature | Widening | Isolated erosion along outside meander bend |
| 96 | dBB11 | Geomorphological Feature | Large Woody Debris | Blockage in channel - possibly farm weir, needs to be field verified |
| 97 | dBB11 | Infrastructure | Road | Schnupp Road 15 m to the outer meander bend |
| 98 | dBB11 | Geomorphological Feature | Large Woody Debris | Large woody debris |
| 99 | dBB12 | Infrastructure | Road | Schnupp Road 15 m to the outer meander bend |
| 100 | dBB12 | Infrastructure | Road | Road bridge for Boileau Road |
| 101 | dBB12 | Geomorphological Feature | Large Woody Debris | Large woody debris (along outer meander bend) |
| 102 | dBB13 | Geomorphological Feature | Widening | Bank erosion and slumping |

| # | Valley Segment | Category | Sub- category | Notes |
|-----|-------------------|-----------------------------|---------------------------|--|
| 103 | dBB12 | Infrastructure | Road | Road is along outside meander bend, and ~13 m away from bank |
| 104 | dBB12 | Infrastructure | Road | Outside meander bend along Ettyville Road ~10 m from bank |
| 105 | dBB12 | Infrastructure | Road | Ettyville Road is ~10 m from top of bank along an outside meander bend |
| 106 | dBB12 | Infrastructure | Road | Ettyville Road is ~10 m from the outside of a meander bend |
| 107 | dBB12 | Geomorphological Feature | Large Woody Debris | Series of large woody debris blockages |
| 108 | dBB12 | Geomorphological Feature | Large Woody Debris | Large woody debris blockages |
| 109 | dBB12 | Geomorphological Feature | Large Woody Debris | Large woody debris pile along one bank |
| 110 | dBB12 | Geomorphological Feature | Meander Bend | Meander bend is showing signs of active erosion along outer bend (cutoff channel may eventually form) |
| 111 | dBB12 | Geomorphological Feature | Planimetric Adjustment | Remnants of previous channel (cutoff from the main channel) |
| 112 | dBB12 | Geomorphological Feature | Large Woody Debris | Large woody debris extending from one bank across channel, diverting flows towards opposite bank, where erosion is evident |
| 113 | dBB12 | Geomorphological Feature | Large Woody Debris | Large woody debris along a high sinuosity segment of Bear Brook and outer meander bend |
| 114 | dBB12 | Geomorphological Feature | Aggradation | Lobate bar forming at the confluence of Bear Brook with a small tributary |
| 115 | dBB12 | Infrastructure | Road | Robillard Road bridge |
| 116 | dBB12 | Geomorphological Feature | Large Woody Debris | Large woody debris (possibly man-made) |
| 117 | dBB12 | Geomorphological Feature | Meander Bend | Outer meander bend erosion with potential impacts to private property |

Appendix B Study Area Mapping



Study Area

Figure 1 Tewin Lands Ottawa, Ontario

Legend





Imagery: City of Ottaway, 2019. Watercourse: MNRF, 2020/GEO Morphix Ltd., 2022. Reach Break and ID, Detailed Assessment Location: GEO Morphix Ltd., 2022. Headwater Drainage Feature Extent: Kilgour, 2022. 50 cm Contour: MNRF, 2019. Study Area: Algonquins of Ontario/Taggart, 2021. Print Date: October 2024. PN 22024. Drawn By: M.O., K.W., G.U., K.M.



Surficial Geology

Figure 2 Tewin Lands Ottawa, Ontario

Legend





Imagery: City of Ottaway, 2019. Watercourse: MNRF, 2020/GEO Morphix Ltd., 2022. Reach Break and ID, Detailed Assessment Location: GEO Morphix Ltd., 2022. Surficial Geology: MNRF, 2024. Headwater Drainage Feature Extent: Kilgour, 2022. Study Area, Tewin Lands: Algonquins of Ontario/Taggart, 2021. PN 22024. Print Date: October 2024. Drawn By: M.O., K.W., G.U., K.M.




Preliminary Erosion Hazard Mapping

Figure 4a Tewin Lands Ottawa, Ontario

Legend





 Λ

Imagery: City of Ottaway, 2019. Watercourse: MNRF, 2020/GEO Morphix Ltd., 2022. Reach Break and ID, MBW, Confined Valley: GEO Morphix Ltd., 2022/2024. Headwater Drainage Feature, Extent: Kilgour, 2022. 50 cm Contour: MNRF, 2019. Study Area, Tewin Lands: Algonquins of Ontario/Taggart, 2021. PN 21063. Print Date: October 2024. Drawn By: M.O., K.W.





Preliminary Erosion Hazard Mapping



Legend





0

 Λ

Imagery: City of Ottaway, 2019. Watercourse: MNRF, 2020/GEO Morphix Ltd., 2022. Reach Break and ID, MBW, Confined Valley: GEO Morphix Ltd., 2022/2024. Headwater Drainage Feature, Extent: Kilgour, 2022. 50 cm Contour: MNRF, 2019. Study Area, Tewin Lands: Algonquins of Ontario/Taggart, 2021. PN 21063. Print Date: October 2024. Drawn By: M.O., K.W.

Appendix C Historical Aerial Photographs





Location: Ottawa, ON Year: 1976 Source: GEO Ottawa Red dot: intersection of Ramsay Creek Main Branch with Tewin Study Area Boundary Blue dot: intersection of Bear Brook Main Branch with Tewin Study Area Boundary



Location: Ottawa, ON Year: 1999 Source: GEO Ottawa Ramsay Creek Main Branch with Te

Red dot: intersection of Ramsay Creek Main Branch with Tewin Study Area Boundary Blue dot: intersection of Bear Brook Main Branch with Tewin Study Area Boundary



Location: Ottawa, ON Year: 2011 Source: GEO Ottawa Red dot: intersection of Ramsay Creek Main Branch with Tewin Study Area Boundary Blue dot: intersection of Bear Brook Main Branch with Tewin Study Area Boundary



Location: Ottawa, ON Year: 2022 Source: GEO Ottawa Red dot: intersection of Ramsay Creek Main Branch with Tewin Study Area Boundary Blue dot: intersection of Bear Brook Main Branch with Tewin Study Area Boundary

Appendix D Reach Characteristics Summary Table

| Date Assessed Reach | Bed Substrate | Bank Substrate | Evidence of Erosion | Valley Type | RGA Score | RGA Classification | RGA Limiting Factor(s) | RSAT Score | RSAT Classification | RSAT Limiting Factor(s) | Avg Bankfull Width (m) Avg Bankfu | ıll Depth (m) Bank Angle | Erosion Percer | it Riparian Vegetation | Aquatic Vegetation | Notes |
|--|--|--------------------------------|---------------------------------------|--------------------------|-------------|----------------------|---------------------------|---------------|---------------------|---|-----------------------------------|--------------------------|----------------|------------------------------|------------------------------------|--|
| 2022-06-29 BB1 | Clay, silt, sand, gravel | Clay, silt, sand | Undercutting, bank slumping | Unconfined | 0.41 | In Adjustment | WI | 21 | Fair | Channel stability | 10.63 | 1.97 60-90 | 60-100% | Trees, shrubs, grasses | Rooted submergent, rooted floating | Bank failure observed Many down trees, low gradient. |
| 2022-06-29 BB2 | Clay, silt, sand, gravel | Clay, silt, sand | Undercutting, banks slumping | Unconfined | 0.41 | In Adjustment | wi | 22 | Fair | Channel stability | 9.11 | 2.11 60-90 | 60-100% | Trees, shrubs, grasses | Rooted emergent, rooted floating | pool-riffle formations observed, evidence of erosion |
| 2021 11 02 882 | Sand day | Class and | Baala alumaiaa | Unserficed | 0.377 | la Tanasikia a | | 27 | Cond | | 0.72 | 1 59 50 00 | 5 20% | T | Dented emerat | Several debris jams from beaver |
| 2021-11-02 883 | Sand, clay | Clay, sand | Banks slumping | Uncontined | 0.377 | In Transition | WI | 27 | Good | Channel stability | 8.73 | 1.68 60-90 | 5-30% | Trees, grasses | Kooted emergent | Valley wall contact, erosion |
| 2021-11-03 BB3-1 | Clay, silt, sand | Clay, silt, sand | Undercutting | Confined | 0.321 | In Transition | wi | 28 | Good | Channel stability, physical instream habitat | 1.20 | 0.29 60-90 | 5-30% | Trees, grasses | Rooted emergent | reach Poorly defined swale type |
| 2021-11-02 BB3-2 | Silt, sand | Sand, silt | Minimal, generally stable | Confined | 0.214 | In Transition | PI | 31 | Good | Channel stability, physical instream habitat | 1.07 | 0.17 30-60 | <5% | Ttrees, grasses, shrubs | Rooted emergent | channel near BB3 confluence More confined at DS extent, v- |
| 2021-11-02 BB3-3 | Silt, sand | Clay, silt, sand | Undercutting | Confined | 0.339 | In Transition | DI | 32 | Good | Channel stability, physical instream habitat | 0.97 | 0.34 60-90 | 5-30% | Trees, shrubs | Rooted emergent | shaped valley Several debris jams from beaver |
| 2021-11-02 BB4 | Clay, sand | Clay, sand | Banks slumping | Unconfined | 0.399 | In Adjustment | wi | 30 | Good | Water quality | 7.73 | 1.54 60-90 | 5-30% | Trees, grasses | Rooted emergent | dams, chutes observed, entrenched |
| | | | | | | | | | | | | | | | | undercutting common, exposed |
| 2021-11-01 BB4-2 | Clay, silt, sand, cobble | Silt, sand, clay | Undercutting | Unconfined | 0.304 | In Adjustment | DI | 32 | Good | Physical instream habitat, channel scouring, sediment deposition | 0.87 | 0.30 60-90 | 30-60% | Trees, grasses | Rooted emergent | geomorphic units Exposed till noted, lack of clear |
| 2021-11-01 BB4-2A | Clay, silt, sand, gravel | Silt, sand, clay | Undercutting | Unconfined | 0.279 | In Adjustment | DI | 31 | Good | Physical instream habitat, channel scouring, sediment deposition | 0.77 | 0.31 60-90 | 5-30% | Trees, grasses | Rooted emergent | geomorphic units |
| | | | | | | | | | | | | | | | | Several debris jams associated with beaver activity, entrenched, |
| 2021-11-01 BB5 | Sand, clay | Clay, sand | Banks slumping | Unconfined | 0.402 | In Adjustment | wi | 26 | Good | Channel stability | 6.60 | 1.42 60-90 | 5-30% | Trees, grasses | Rooted emergent | no true riffles, slumping and undercutting common |
| 2021-11-03 BB5-1 | Silt clay, sand | Silt clay sand | Minimal generally stable | Unconfined | 0.256 | In Transition | DI | 24 | Excellent | Physical instream babitat, channel scouring, sediment deposition | 0.93 | 0.22 60.90 | ~5% | Тгаас дгэссас | Pooted emergent | swale/wetland feature. Very |
| | Sity day, said | Site, etdy, suita | mining percent score | onconnica | 0.230 | in rensition | | 54 | Execution | inforce instruction number, channel sconnig, scannelle acposition | 0.55 | 0.12 00 00 | 1570 | 11003, 5103303 | Noted emergent | Characteristic of an anatomosing |
| 2021-11-03 BB5-1-1 | Silt, clay | Silt, clay | Fluvial entrainment | Unconfined | 0.155 | In Regime | PI | 35 | Excellent | Physical instream habitat, channel scouring, sediment deposition | 1.32 | 0.20 0-30 | <5% | Grasses, shrubs | Rooted emergent | swale, poorly defined, lack of geomorphic activity |
| | | | | | | | | | | | | | | | | Poorly defined in sections, a saturated swale, lack of |
| 2021-11-03 BB5-1-2 | Silt, clay | Silt, clay | Fluvial entrainment | Unconfined | 0.77 | In Regime | AI | 30 | Good | Physical instream habitat | 2.75 | 0.10 0-30 | <5% | Grasses, shrubs | Rooted emergent | geomorphic activity Multiple threaded channels as it |
| 2021-11-04 BB5-2 | Silt, clay, sand | Silt, clay | Fluvial entrainment | Confined | 0.25 | In Transition | AI | 32 | Good | Physical instream habitat | 1.51 | 0.74 30-60 | <5% | Grasses, trees | Rooted emergent | enters BB5 floodplain Beaver dam and ponds present, |
| 2021-11-03 BB5-3 | Sand, clay | Sand, clay | Undercutting | Confined | 0.201 | In Transition | wi | 31 | Good | Channel stability, physical instream habitat | 1.40 | 0.28 30-90 | 5-30% | Trees | Rooted emergent | type channel Poorly defined swale feature in |
| | | | | | | | | | | | | | | | | upstream half of reach, only defined ~200 upstream of BB5 |
| 2021-11-03 BB5-4 | Sand, clay | Sand, clay | Fluvial entrainment | Confined | 0.179 | In Regime | AI, PI | 30 | Good | Channel scouring, sediment deposition, phsyical instream habitat | 1.80 | 0.37 30-60 | 5-30% | Grasses, trees | Rooted emergent | confluence Only accessed DS of |
| 2021-11-01 BB5-5 | Sand, clay | Sand, clay | Undercutting | Confined | 0.333 | In Transition | wi | 28 | Good | Channel stability | 4.08 | 1.28 60-90 | 30-60% | Grasses, trees | Rooted emergent | hydrocorridor. Beaver dam at DS extent causing scour DS |
| | | | | | | | | | | | | | | | | Significant channel alteration and backwatering from downstream |
| 2021-10-29 BB5-5A | N/A | Silt, clay, sand | Banks slumping | Confined | 0.18 | In Regime | WI | 27 | Good | Physical instream habitat | 11.17 | N/A 30-90 | 60-100% | Trees, grasses | Rooted emergent | restricted. |
| | | | | | | | | | | | | | | | | agricultural field, unconfined at US extent, transition to partial, |
| 2021-10-29 BB5-5A-2 | Clay, silt, sand, gravel | Clay, silt, sand | Banks slumping | Confined | 0.304 | In Transition | WI | 20 | Fair | Physical instream habitat | 3.43 | 0.50 30-60 | 30-60% | Trees, grasses | Rooted emergent | confined at DS extent Reach modified by previous |
| | | | | | | | | | | | | | | | | upstream beaver dam failure, evidence of undercutting, active |
| 2021-10-27 BB5-5A-3 | Clay, silt, sand, gravel | Clay, silt, sand | Undercutting | Confined | 0.61 | In Adjustment | AI | 23 | Fair | Channel scouring, sediment deposition | 7.27 | 1.00 30-90 | 60-100% | Trees | Rooted submergent | bed and outer bank erosion Upstream reach break at rail trail, |
| 2021-10-29 BB5-5A-3-1 | Parent, clay, silt, sand, gravel, small cobble | Clay, silt, sand | Undercutting | Confined | 0.41 | In Adjustment | AI | 24 | Fair | Channel scouring, sediment deposition | 5.00 | 1.53 30-90 | 60-100% | Trees | Rooted submergent | upstream of trail Reach ends at heaver formed pond |
| 2021-10-29 BB5-5A-3-1A | clay, silt and sand | Clay, silt, sand | Fluvial entrainment | Confined | 0.085 | In Regime | wi | 31 | Good | Riparian habitat conditions | 4.73 | 1.41 30-60 | 5-30% | Trees, shrubs, grasses | Rooted emergent | channel appears stable, low entrenchment |
| | | | | | | | | | | | | | | | | Proposed downstream reach break/split slightly downstream |
| | | | | | | | | | | | | | | | | of BB5-5A-3A-1 confluence. Increasing sinuosity moving |
| 2021-10-28 BB5-5A-3A | Clay, silt, gravel, small cobble | Clay, silt | Banks slumping | Confined | 0.26 | In Transition | wi | 23 | Fair | Riparian habitat conditions | 5.60 | 1.55 60-90 | 60-100% | Trees, grasses, herbaceous | Rooted emergent | downstream, massive bank and valley wall failure observed. |
| | | | | | | | | | | | | | | | | break/split slightly downstream of BB5-5A-3A-1 confluence. |
| | | | | | | | | | | | | | | | | Increasing sinuosity moving downstream, massive bank and |
| 2021-10-28 BB5-5A-3B 2021-10-28 BB5-5A-3B-1 | Clay, silt, sand, gravel Clay, silt, sand, gravel | Clay, silt Clay, silt, sand | Banks slumping Fluvial entrainment | Unconfined Unconfined | 0.29 N/A | In Transition N/A | WI N/A | 17 N/A | Fair N/A | Channel stability, physical instream habitat, riparian habitat N/A | 3.50 | 0.93 60-90 0.54 30-60 | 60-100% <5% | Grasses, herbaceous Trees | Rooted emergent Rooted emergent | valley wall failure observed. Watercourse primarily dry |
| 2021-10-28 BB5-5A-3B-2 | Clay, silt, sand, gravel | Clay, silt | Fluvial entrainment | Unconfined | N/A | N/A | N/A | N/A | N/A | N/A | 2.12 | 0.67 30-60 | <5% | Grasses, herbaceous | Rooted emergent | Wetland at upstream extent Erosion observed intensified by |
| | | | | | | | | | | | | | | | | beaver activity/proposed reach break to move ~200m ds to |
| 2021-10-28 BB5-5A-3C | Clay, silt, gravel | Clay, silt | Banks slumping | Unconfined | 0.17 | In Regime | WI | 22 | Fair | Riparian habitat conditions | 6.25 | 1.88 60-90 | 60-100% | Grasses, herbaceous | Rooted emergent | beaver dam Channel backwatered from |
| | | | | | | | | | | | | | | | | downstream beaver dam, steep banks, entrenched channel. |
| 2021 10 29 BRE 64 2D | NA | Clay, silt | Paaks slumping | Unconfined | 0.3 | In Rogimo | 14/1 | 25 | Good | Dispring babitat conditions | 6.35 | 3 50 50 00 | 60.100% | Graces herbaseous trees | Pootod amorgant | 200 m DS to existing beaver |
| 2021-10-28 883-34-30 | | Clay, sit | banks siumping | oncommed | 0.2 | in Regime | WI | 25 | 6000 | Nparian natital conditions | 0.23 | 2.30 00-50 | 00-100% | Grasses, nerbaceous, trees | Kooted emergent | Feature was characteristic of a |
| | | | | | | | | | | | | | | | | assessment. Flows are restricted through a drain at the |
| 2021-10-27 BB5-5B | Clay, silt | Unknown due to pondir | ng Banks slumping | Confined | N/A | N/A | N/A | N/A | N/A | N/A | N/A N/A | 30-60 | 30-60% | Grasses, herbaceous | Rooted emergent | downstream extent prior to converging with BB5-5A |
| | | | | | | - | | | | | | | 1 | | | Wide agricultural swale, entrenched, multiple flow paths, |
| 2021-10-27 BB5-5C | Clay, silt, sand | Clay, silt | Banks slumping | Confined | 0.11 | In Regime | PI | 24 | Fair | Riparian habitat conditions | 7.78 | 1.06 60-90 | 30-60% | Grasses | Rooted emergent | riffle-run development, no deep pools observed, |
| | | | | | | | | | | | | | | | | Wide agricultural swale, entrenched, modified by |
| 2021-10-26 BB5-5C-1 | Clay, silt, sand, gravel | Clay, silt, sand | Banks slumping | Unconfined | N/A | N/A | N/A | N/A | N/A | N/A | 7.90 | 1.32 60-90 | 30-60% | Grasses, herbaceous | Rooted emergent | agricultural activities, feature 100% run. |

| | | | | | | 1 | | | 1 | | | | | | | | MCI I I I I |
|--|--|--|--|--|--|--|--|--|--|--|---|--|--|--|--|--|---|
| | | | | | | | | | | | | | | | | | Wide swale, entrenched, accumulation of organics, no |
| | | | | | | | | | | | | | | | | | morphological adjustment in |
| 2021-10-26 | BB5-5C-1A | Clay, silt, sand | Clay, silt, sand | Banks slumping | Unconfined | N/A | N/A | N/A | N/A | N/A | N/A | 7.80 | 1.29 60-90 | 30-60% | Grasses, herbaceous | Rooted emergent | process Ditch-like characteristics of swale, |
| | | | | | | | | | | | | | | | | | heavily modified and |
| | | | | | | | | | | | | | | | | | across, input from numerous |
| 2024 40 25 | | et. 11 | ci | | | | | | | | N/A | 2.00 | 0.20 0.20 | | | | storm drains/culverts from |
| 2021-10-26 | BB5-5C-1A-1 | Clay, slit | Clay, slit | Fluvial entrainment | Unconfined | N/A | N/A | N/A | N/A | N/A | N/A | 2.00 | 0.30 0-30 | <5% | Grasses, trees | Kooted emergent | 100% runs, agricultural swale. |
| | | - | | | | | | | | | | | | | | | Poorly defined with little |
| 2021-10-26 | BB5-5C-1A-2 | Clay, silt | Clay, silt | Fluvial entrainment | Unconfined | N/A | N/A | N/A | N/A | N/A | N/A | 4.25 | 0.58 0-30 | <5% | Trees, shrubs, herbaceous | Rooted emergent | geomorphic activity Flows may be perennial, leaning |
| | | | | | | | | | | | | | | | | | trees and shrubs on banks, |
| | | | | | | | | | | | | | | | | | feature 100% run, some sedimentation observed. no |
| | | | | | | | | | | | | | | | | | morphological adjustment in |
| 2021-10-26 | BB5-5D | Clay, silt, sand | Clay, silt | Fluvial entrainment | Unconfined | 0.17 | In Regime | PI | 30 | Good | Physical instream habitat | 4.86 | 0.84 30-60 | 5-30% | Trees, shrubs, herbaceous | Rooted emergent | process Poorly defined feature flows |
| 2021-10-26 | BB5-5D-1 | Clay, silt | Clay, silt | Fluvial entrainment | Unconfined | N/A | N/A | N/A | N/A | N/A | N/A | 4.50 | 0.66 0-30 | <5% | Trees, shrubs, herbaceous | Rooted emergent | behind residentials lots. |
| 2021-11-01 | BRG | Sand clay | Sand clav | Ranks slumning | Confined | 0.264 | In Transition | 14/1 | 22 | Eair | Channel stability | 4.30 | 1 16 60-90 | 30-60% | Grasses trees | Pooted emergent | Partially confined by valley wall contact |
| 2021-11-01 | 550 | Sand, clay | Sand, clay | banks storiping | commed | 0.204 | mmanacion | | | ran | | 4.50 | 1.10 00-50 | 50-00% | 0183363, (1663 | Rooted enlergent | Observations only completed |
| 2021 11 04 | 007 | | 1 Statutes and statut | Danka shumaina | Confirmal | 0.264 | In Transition | | 25 | Grad | Channel statility | 21/2 | co. 00 | 20.00% | T | Dented amount | within right of way, no reach |
| 2021-11-04 | BB8 | | Likely sand, clay | Banks sumping | Contined | 0.264 | in transition | VVI | 25 Includ | ed in manning but no | channel stability IV/A | N/A | 60-90 | 30-00% | Trees, grasses | Rooted emergent | access |
| | 550 | | | | | | | | Includ | co in hopping out no | assisted, busilee of retirin study area. commed | | | | | | Less confined at upstream extent, |
| | | | | | | | | | | | | | | | | | several leaning trees, significant bank erosion observed |
| 2021-10-21 | BB8-1 | Clay, silt, sand | Clay, silt | Fluvial entrainment | Confined | 0.424 | In Adjustment | wi | 19 | Fair | Channel scouring, physical instream habitat | 2.53 | 0.85 60-90 | 60-100% | Trees, grasses | NA | knickpoint in reach from willow |
| | | | | | | | | | | | | | | | | | Nearby beaver dam causing |
| | | | | | | | | | | | | | | | | | intensifying erosion, dominated |
| 2021-10-25 | BB9 | Clay, silt, sand, gravel | Clay, silt, sand | Banks slumping, exposed roots | Unconfined | 0.311 | In Transition | DI | 17 | Fair | Riparian habitat conditions | 5.80 | 1.45 30-90 | 60-100% | Grasses, trees | Rooted emergent | by runs |
| | | | | | | | | | | | | | | | | | Dry at upstream extent, low flow |
| 2021 10 25 | 000 1 | Class all and | Class silk send | NI (F9/ | Unanafinad | N/A | | | | N/A | N/A | 21/2 | | -59/ | Usebaasse bases | De stad subscenest | drainage throughout downstream |
| 2021-10-25 | 889-1 | Clay, slit, sand | Clay, slit, sand | None <5% | Unconfined | N/A | N/A | N/A | N/A | N/A | N/A N/A | N/A | | <5% | Herbaceous, trees | Rooted submergent | morphological adjustment |
| 2021-10-25 | BB10 | Clay, silt, sand | Clay, silt, sand | Undercutting, banks slumping, exposed roots | Unconfined | 0.26 | In Transition | wi | 20 | Fair | Riparian habitat conditions | 4.80 | 2.85 30-90 | 60-100% | Grasses, herbaceous, trees | Rooted emergent | observed |
| | | | | | | | | | | | | | | | | | No true riffles observed, high valley wall above stream banks, |
| | | | | | | | | | | | | | | | | | leaning trees, bank slumping and |
| 2021-10-25 | BB10-1 | Clay, silt, sand, gravel | Clay, silt, sand | Exposed roots, banks slumping | Unconfined | 0.19 | In Regime | wi | 19 | Fair | Riparian habitat conditions | 3.53 | 1.25 30-90 | 30-60% | Grasses, herbaceous | Rooted emergent | exposed tree roots observed, enlarging observed |
| | | | | , , , , , , , , , , , , , , , , , , , | | | | | | | | | | | | | Downstream of golf course, J |
| | | | | | | | | | | | | | | | | | shaped trunks, no true riffles observed, reach dominated by |
| 2021-10-21 | BB10-1A | Clay, silt, till | Clay, silt | Banks slumping | Unconfined | 0.233 | In Transition | DI | 27 | Good | Riparian habitat conditions, channel stability | 1.41 | 0.33 30-60 | 5-30% | Grasses | Rooted emergent | runs, channel entrenched |
| | | | | | | | | | | | | | | | | | Straight ditch, all runs observed, algae and few cattails present |
| | | | | | | | | | | | | | | | | | minor slumping observed, little |
| 2021-10-21 | BB10-1B | Clay, silt | Clay, silt | Banks slumping | Unconfined | 0.18 | In Regime | AI | 23 | Fair | Riparian habitat conditions | 1.60 | 0.35 30-60 | <5% | Grasses | Attached algae, rooted emergent | geomorphic activity overall |
| 2021 10 11 | PP11 | Clay Silt Till | Clay Silt till | Paper clumping | Unconfined | 0.22 | In Transition | DI | 27 | Cood | Rianzais habitat conditions | 1.40 | 0 22 20 60 | 5 20% | Grassas fourtroop | Restad emergent | Little geomrophic activity |
| 2021-10-11 | BBII | | clay, siit, tii | Banks sumping | oncommed | 0.23 | in mansicion | DI | 21 | 8000 | | 1.40 | 0.32 50*00 | 3-30% | diasses, iew tiees | Kooted enleigent | Culvert at Anderson Rd. 3.8 |
| 2021-10-25 | BB12 | Clay, silt, sand, gravel, small cobble | Clay, silt, sand | Banks slumping | Unconfined | 0.29 | In Transition | AI, WI | 21 | Fair | Riparian habitat conditions | 4.23 | 1.36 60-90 | 30-60% | Grasses, herbaceous | Rooted emergent | diameter |
| | | | | | | | | | | | | | | | | | channel geometry throughout, |
| | | | | | | | | | | | | | | | | | |
| 2024 40 20 | | d. 11 | ci (h. 191 | | 0.6.1 | 0.400 | | | | | | | 0.05 50.00 | 5 300/ | | | some undercutting and exposed |
| 2021-10-28 | BB12-1 | Clay, silt | Clay, silt, till | Banks slumping | Confined | 0.103 | In Regime | AI, DI | 23 | Fair | Riparian habitat conditions, physical instream habitat | 1.49 | 0.36 60-90 | 5-30% | Grasses, trees | Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched |
| 2021-10-28 | BB12-1 | Clay, silt | Clay, silt, till | Banks slumping | Confined | 0.103 | In Regime | AI, DI | 23 | Fair | Riparian habitat conditions, physical instream habitat | 1.49 | 0.36 60-90 | 5-30% | Grasses, trees | Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially |
| 2021-10-28 | BB12-1 | Clay, silt | Clay, silt, till | Banks slumping | Confined | 0.103 | In Regime | AI, DI | 23 | Fair | Riparian habitat conditions, physical instream habitat | 1.49 | 0.36 60-90 | 5-30% | Grasses, trees | Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands |
| 2021-10-28 2021-10-20 | BB12-1 BB13 | Clay, silt | Clay, silt, till Clay, silt | Banks slumping Banks slumping | Confined | 0.103 | In Regime | AI, DI | 23 | Fair Good | Riparian habitat conditions, physical instream habitat | 1.49 | 0.36 60-90 | 5-30% | Grasses, trees Grasses | Rooted emergent Attached algae, rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed |
| 2021-10-28 2021-10-20 2021-10-20 | B812-1 B813 B814 | Clay, silt | Clay, silt, till Clay, silt Clay, silt | Banks slumping Banks slumping Banks slumping | Confined Unconfined | 0.103 | In Regime | AI, DI AI, WI | 23 | Fair Good Fair | Riparian habitat conditions, physical instream habitat Channel stability Channel stability | 1.49 | 0.36 60-90 | 5-30% <5% | Grasses, trees Grasses Grasses shrubs | Rooted emergent Attached algae, rooted emergent Bonted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recruering planform |
| 2021-10-28 2021-10-20 2021-10-20 | BB12-1 BB13 BB14 | Clay, silt Clay, silt Clay, silt, sand | Clay, silt, till Clay, silt Clay, silt Clay, silt, sand | Banks slumping Banks slumping Banks slumping | Confined Unconfined Unconfined | 0.103 | In Regime In Transition In Transition | AI, DI AI, WI WI | 23 25 23 | Fair Good Fair | Riparian habitat conditions, physical instream habitat Channel stability Channel stability | 1.49 1.60 3.60 | 0.36 60-90 0.35 30-60 0.88 60-90 | 5-30% <5% 60-100% | Grasses, trees Grasses Grasses, shrubs | Rooted emergent Attached algae, rooted emergent Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 | BB12-1 BB13 BB14 BB15 | Clay, silt Clay, silt Clay, silt, sand Clay, silt | Clay, silt, till Clay, silt Clay, silt, sand Clay, silt | Banks slumping Banks slumping Banks slumping Banks slumping | Confined Unconfined Unconfined Unconfined | 0.103 | In Regime In Transition In Transition In Regime | AI, DI AI, WI WI AI | 23 25 23 24 | Fair Good Fair Fair | Riparian habitat conditions, physical instream habitat Channel stability Channel stability Channel stability Channel stability, physical instream habitat | 1.49 1.60 3.60 4.80 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 | 5-30% <5% 60-100% 5-30% | Grasses, trees Grasses Grasses, shrubs Grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight dirched channel |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 | BB12-1 BB13 BB14 BB15 BB16 | Clay, silt Clay, silt Clay, silt, sand Clay, silt Clay, silt, gravel | Clay, silt, till Clay, silt Clay, silt Clay, silt Clay, silt Clay, silt Clay, silt | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping | Confined Unconfined Unconfined Unconfined Unconfined | 0.103 0.21 0.32 0.19 0.29 | In Regime In Transition In Transition In Regime In Transition | AI, DI AI, WI WI AI WI | 23 25 23 24 22 | Fair Good Fair Fair Fair | Riparian habitat conditions, physical instream habitat Channel stability Channel stability Channel stability Channel stability, physical instream habitat Channel stability | 1.49 1.60 3.60 4.80 4.17 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 | 5-30% <5% 60-100% 5-30% 60-100% | Grasses, trees Grasses Grasses, shrubs Grasses Grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted emergent Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2021-10-20 | BB12-1 BB13 BB14 BB15 BB16 BC1 | Clay, silt Clay, silt Clay, silt, sand Clay, silt, gavel Clay, silt, gravel Clay, silt, gravel | Clay, silt, till Clay, silt Clay, silt, sand Clay, silt Clay, silt | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undersulting banks slumping | Confined Unconfined Unconfined Unconfined Unconfined | 0.103 0.21 0.32 0.19 0.29 | In Regime In Transition In Transition In Regime In Transition | AI, DI AI, WI WI AI WI | 23 25 23 24 22 15 | Fair Good Fair Fair Fair | Riparian habitat conditions, physical instream habitat Channel stability Channel stability Channel stability Channel stability Channel stability Piorarian habitat Channel stability Piorarian habitat | 1.49 1.60 3.60 4.80 4.17 2.17 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60.90 | 5-30% <5% 60-100% 5-30% 60-100% | Grasses, trees Grasses Grasses, shrubs Grasses Grasses | Rooted emergent Attached algae, rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 | BB12-1 BB13 BB14 BB15 BB16 RC1 | Clay, silt Clay, silt Clay, silt, sand Clay, silt, gravel Clay, silt, gravel Clay, silt, sand, gravel, cobble | Clay, silt, till Clay, silt Clay, silt, sand Clay, silt Clay, silt Clay, silt | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping | Confined Unconfined Unconfined Unconfined Unconfined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 | In Regime In Transition In Transition In Regime In Transition | Al, DI Al, WI WI Al WI WI | 23 25 23 24 22 16 | Fair Good Fair Fair Fair Fair | Riparian habitat conditions, physical instream habitat Channel stability | 1.49 1.60 3.60 4.80 4.17 2.17 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 | 5-30% <5% 60-100% 5-30% 60-100% 60-100% | Grasses, trees Grasses Grasses, shrubs Grasses Grasses Grasses Grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted emergent Rooted floating | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 | Clay, silt Clay, silt Clay, silt, sand Clay, silt, gravel Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble | Clay, silt, till Clay, silt Clay, silt, sand Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, salab failure, rotational slip and slump | Confined Unconfined Unconfined Unconfined Unconfined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 | In Regime In Transition In Transition In Regime In Transition In Transition | AI, DI AI, WI WI AI WI WI WI | 23 25 23 24 22 24 22 16 15 | Fair Good Fair Fair Fair Fair Fair | Riparian habitat conditions, physical instream habitat Channel stability Channel stability Channel stability Channel stability Riparian habitat conditions, channel stability Riparian habitat conditions, channel stability | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 | 5-30% <5% 60-100% 5-30% 60-100% 60-100% 60-100% | Grasses, trees Grasses Grasses, shrubs Grasses Grasses Grasses Grasses Grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted floating Rooted floating | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC3 | Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, gravel Clay, silt, sand, gravel, cobble | Clay, silt, till Clay, silt Clay, silt, sand Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand Clay, silt, sand | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment | Confined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.38 0.4 | In Regime In Transition In Transition In Regime In Transition In Transition In Transition In Transition | AI, DI AI, WI WI AI WI WI WI WI PI | 23 25 23 24 22 24 22 16 15 20 | Fair Good Fair Fair Fair Fair Fair Fair | Riparian habitat conditions, physical instream habitat | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.78 60-90 | 5-30% <5% 60-100% 5-30% 60-100% 60-100% 60-100% 5-30% | Grasses, trees Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted floating Rooted floating | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightende, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC3 | Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, gravel Clay, silt, gravel Clay, silt, sand, gravel, cobble Clay, silt, gravel, sand, cobble Clay, silt, gravel, sand, cobble | Clay, silt, till Clay, silt Clay, silt Clay, silt Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, parent Clay, silt, parent | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment | Confined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.38 0.4 | In Regime In Transition In Transition In Regime In Transition | AI, DI AI, WI WI AI WI WI PI | 23 25 23 24 22 16 15 20 20 | Fair Good Fair Fair Fair Fair Fair | Riparian habitat conditions, physical instream habitat | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.45 60-90 1.78 60-90 | 5-30% <5% 60-100% 5-30% 60-100% 60-100% 5-30% | Grasses, trees Grasses Grasses, shrubs Grasses Grasses Grasses Grasses Grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted floating Rooted floating Rooted floating Rooted floating Rooted floating | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC4 RC4-1-1 | Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, gravel Clay, silt, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand Clay, silt, sand Clay, silt, sand | Clay, silt, till Clay, silt, sand Clay, silt Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel Clay, silt | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Fluvial entrainment | Confined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.34 0.179 | In Regime In Transition In Regime | AI, DI AI, WI WI AI WI WI PI WI, AI | 23 25 23 24 22 16 15 20 26 19 | Fair Good Fair Fair Fair Fair Fair Fair Good Fair | Riparian habitat conditions, physical instream habitat | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.78 60-90 1.78 30-60 2.20 60-90 | 5-30% <5% 60-100% 5-30% 60-100% 60-100% 5-30% 5-30% <5% | Grasses, trees Grasses Grasses, shrubs Grasses Grasses Grasses Grasses Grasses Grasses Shrubs Grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Heavy vegetation encroachment Straight solt agriculture ditch |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC3 RC4 RC4-1-1 RC4-1-1A | Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand, cobble Clay, silt, sand Clay, silt, sand Clay, silt | Clay, silt, till Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand Clay, silt, sand Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel Clay, silt Clay, silt | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Huvial entrainment Minor slumping <5% | Confined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.34 0.179 0.129 | In Regime In Transition In Regime In Regime | Al, Dl Al, Wl Wl Al Wl Wl Pl Pl Wl, Al Wl | 23 25 23 24 22 16 15 20 26 26 19 28 | Fair Good Fair Fair Fair Fair Fair Fair Good Fair Good | Riparian habitat conditions, physical instream habitat Image: Channel stability Channel stability Image: Channel stability Channel stability, physical instream habitat Image: Channel stability Channel stability Image: Channel stability Riparian habitat conditions, channel stability Image: Channel stability Riparian habitat conditions, channel stability Image: Channel stability Channel stability Image: Channel stability Riparian habitat conditions, channel stability Image: Channel stability Physical instream habitat, water quality N/A Physical instream habitat, water quality Image: Channel stability | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.45 60-90 1.78 30-60 1.78 30-60 0.74 30-60 | 5-30% <5% 60-100% 5-30% 60-100% 60-100% 5-30% 5-30% <5% | Grasses, trees Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Trees Trees, grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted floating <td< td=""><td>some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Heavy vegetation encroachment Straight sota agricultural ditch</td></td<> | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Heavy vegetation encroachment Straight sota agricultural ditch |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC3 RC4-1-1 RC4-1-1A RC5-1A-1A | Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, gravel Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand Clay, silt, sand Clay, silt, gravel, sand, cobble Clay, silt, gravel, sand Clay, silt Clay, sil | Clay, silt, till Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand Clay, silt, parent Clay, silt, sand, gravel Clay, silt | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Fluvial entrainment Kinor slumping <5% | Confined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.34 0.179 0.129 | In Regime In Transition In Regime | Al, Dl Al, Wl Wl Al Wl Wl Wl Wl Wl, Al Wl | 23 25 23 24 22 22 16 15 20 26 19 28 | Fair Good Fair Fair Fair Fair Fair Fair Good Fair Fair Good Sood Fair | Riparian habitat conditions, physical instream habitat Channel stability Channel stability Channel stability Channel stability Channel stability Riparian habitat conditions, channel stability Riparian habitat conditions, channel stability Riparian habitat conditions, channel stability Channel stability Riparian habitat conditions, channel stability Physicial instream habitat, water quality | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.45 60-90 1.78 60-90 1.78 30-60 2.20 60-90 0.74 30-60 | 5-30% <5% 60-100% 5-30% 60-100% 60-100% 5-30% 5-30% <5% | Grasses, trees Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Trees, grasses Trees, grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted emergent Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Straight shot agriculture ditch Straight agricultural ditch |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC3 RC4 RC4-1-1 RC4-1 R | Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand, cobble Clay, silt, gravel, gravel, sand, cobble Clay, silt, gravel, gravel, sand, cobble Clay, silt, gravel, gravel | Clay, silt, till Clay, silt Clay, silt, sand Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand Clay, silt, parent Clay, silt, sand, gravel Clay, silt | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Fluvial entrainment Huvial entrainment Fluvial e | Confined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.34 0.79 0.129 | In Regime In Transition In Regime In | AI, DI AI, WI WI AI WI WI PI WI WI, AI WI | 23 25 23 24 22 22 16 15 20 26 19 28 | Fair Good Fair Fair Fair Fair Fair Good Fair Fair Good Asser | Riparian habitat conditions, physical instream habitat Channel stability Channel stability Channel stability Channel stability Channel stability Riparian habitat conditions, channel stability Riparian habitat conditions, channel stability Riparian habitat conditions, channel stability Channel stability N/A Physicial instream habitat, water quality | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 1.23 60-90 1.45 60-90 1.78 60-90 1.78 60-90 1.78 30-60 2.20 60-90 0.74 30-60 | 5-30% <5% 60-100% 5-30% 60-100% 60-100% 5-30% 5-30% <5% <5% | Grasses, trees Grasses Grasses, shrubs Grasses Grasses Grasses Grasses Grasses Grasses, trees Shrubs Grasses Trees, grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted emergent Rooted floating Rooted emergent Rooted emergent Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Heavy vegetation encroachment Straight shot agricultured dich Straight agricultural ditch. |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC3 RC4-1-1 RC4-1-1A RC5-1A-1A | Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, gravel Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand, cobble Clay, silt, gravel, gravel, sand, cobble Clay, silt, gravel, gravel, sand, cobble Clay, silt, gravel, g | Clay, silt, till Clay, silt Clay, silt, sand Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand Clay, silt, parent Clay, silt, parent Clay, silt, sand, gravel Clay, silt | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Fluvial entrainment Minor slumping <5% | Confined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.4 0.34 0.179 0.129 | In Regime In Transition In Regime In | Al, DI Al, WI WI Al WI WI PI WI WI, Al WI | 23 25 23 24 22 22 16 15 20 26 19 28 | Fair Good Fair Fair Fair Fair Fair Fair Good Fair Good Asser | Riparian habitat conditions, physical instream habitat Channel stability Channel stability Channel stability, physical instream habitat Channel stability Riparian habitat conditions, channel stability Channel stability Physical instream habitat, water quality | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.78 60-90 1.78 60-90 1.78 60-90 1.78 30-60 2.20 60-90 0.74 30-60 | 5-30% <5% | Grasses, trees Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Trees, grasses Trees, grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted demergent Rooted emergent Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightende, slumping common, several vegetated Islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Straight agriculture ditch Straight agricultural ditch Straight agricultural ditch. |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-10-20 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC3 RC4-1-1 RC5-1A-1A RC4-1-1A-1 | Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, gravel Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, gravel, sand, cobble Clay, silt, gravel, sand, Cobble Clay, silt, sand Clay, silt, sand Clay, silt, sand | Clay, silt, till Clay, silt, sand Clay, silt Clay, silt Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel Clay, silt, sand, gravel Clay, silt Clay, silt, sand, gravel Clay, silt Clay, silt, sand, gravel Clay, silt Clay, silt, sand | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, banks slumping Fluvial entrainment Fluvial entrainment Fluvial entrainment Fluvial entrainment Fluvial entrainment Fluvial entrainment Filing/sloughing | Confined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.38 0.4 0.129 0.129 | In Regime In Transition In Transition In Regime In Transition In Regime In Regime In Regime In Regime | Al, DI Al, WI WI Al WI WI PI WI WI, Al WI WI WI | 23 25 23 24 22 16 15 20 26 19 28 25 | Fair Good Fair Fair Fair Fair Fair Fair Good Fair Good Good | Riparian habitat conditions, physical instream habitat Channel stability Channel stability Channel stability, physical instream habitat Channel stability, physical instream habitat Channel stability Riparian habitat conditions, channel stability Riparian habitat conditions, channel stability Riparian habitat conditions, channel stability Riparian habitat, water quality Physical instream habitat, water quality | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 5.35 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.78 60-90 1.78 30-60 2.20 60-90 0.74 30-60 0.95 0-30 | 5-30% <5% | Grasses, trees Grasses Trees, grasses Trees, grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted mergent Rooted floating Rooted mergent Rooted mergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Straight agricultural ditch Straight agricultural ditch Straight agricultural ditch. Bartaight agricultural ditch. Straight agricultural ditch. Straight agricultural ditch. Straight agricultural ditch. Straight agricultural grant of low observed, minior slumping observed, minior slumping |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC3 RC4-1-1 RC5-1A-1A RC4-1-1A-1 | Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, gravel Clay, silt, gravel, cobble Clay, silt, gravel, cobble Clay, silt, gravel, sand, Clay, silt, gravel, sand, Clay, silt, sand, Society, | Clay, silt, till Clay, silt, sand Clay, silt, sand Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel Clay, silt, sand | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Minor slumping <<5% | Confined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.34 0.179 0.129 0.129 | In Regime In Transition In Transition In Regime In Transition In Transition In Transition In Transition In Transition In Transition In Regime In Regime In Regime In Regime | AI, DI AI, WI WI AI WI WI WI WI, AI WI WI WI WI WI | 23 25 23 24 22 16 15 20 26 19 28 26 19 28 | Fair Good Fair Fair Fair Fair Fair Fair Good Fair Good Fair Sood Fair | Riparian habitat conditions, physical instream habitat Channel stability Channel stability Channel stability, physical instream habitat Channel stability, physical instream habitat Channel stability Riparian habitat conditions, channel stability Physical instream habitat, water quality | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 5.35 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.45 60-90 1.78 30-60 2.20 60-90 0.74 30-60 0.95 0-30 | 5-30% -<5% 60-100% 60-100% 60-100% 60-100% 5-30% 5-30% -<5% -<5% | Grasses, trees Grasses Grasses, shrubs Grasses Grasses Grasses Grasses Grasses Grasses Shrubs Grasses Trees, grasses Trees, grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted mergent Rooted emergent Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grases Heavy vegetation encroachment Straight diraster Heavy vegetation encroachment Straight agricultural ditch Straight agricultural ditch Straight agricultural ditch, beaver dams retaining water, no flow observed, minin slumping observed, minin slumping |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2020-06-28 2020-06-28 2020-06-28 2020-06-28 2020-06-28 2020-06-28 2020-06-28 200-06-28 | BB12-1 BB13 BB13 BB15 BB16 RC1 RC2 RC4 RC4-1-1 RC4-1-1A-1 RC4-1-1A-2 | Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand Clay, silt, sand Clay, silt Clay, sil | Clay, silt, till Clay, silt Clay, silt, sand Clay, silt, sand, gravel Clay, silt | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Minor slumping <5% | Confined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.29 0.28 0.38 0.4 0.38 0.4 0.34 0.179 0.129 | In Regime In Transition In Transition In Regime In Transition In Transition In Transition In Transition In Transition In Transition In Regime In Regime In Regime In Regime In Regime | AI, DI AI, WI WI WI WI WI WI WI, AI WI WI WI | 23 25 23 24 22 22 16 15 20 26 19 28 26 29 28 | Fair Good Fair Fair Fair Fair Fair Good Fair Good Fair Good Fair Good | Riparian habitat conditions, physical instream habitat | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 5.35 4.98 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 1.45 60-90 1.45 60-90 1.78 60-90 1.78 60-90 1.78 60-90 0.74 30-60 0.95 0-30 0.83 30-60 | 5-30% <5% | Grasses, trees Grasses Trees, grasses Trees, grasses Trees | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted mergent Rooted mergent Rooted mergent Rooted emergent Rooted emergent Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Heavy vegetation encroachment Straight agricultural ditch Straight agricultural ditch Straight agricultural ditch Straight agricultural ditch, beaver dams retaining water, no flow observed, minor slumping observed, minor slumping observed, minor slumping |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2020-06-28 2020-06-28 2020-06-28 2020-06-28 2020-06-28 2020-06-28 2020-06-28 2020-06-28 2020-06-28 2020-06-28 2020-06-28 2020-06-28 2020-06-28 200- | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC4 RC4-1-1 RC5-1A-1A RC4-1-1A-1 RC4-1-1A-2 RC4-1-1A-3 | Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel, cobble Clay, silt, sand Clay, silt, sand Clay, silt | Clay, silt, till Clay, silt Clay, silt, sand Clay, silt, sand, gravel Clay, silt Clay, silt Clay, silt Clay, silt | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Huvial entrainment Fluvial entrainment Fluvial entrainment Juner slumping <5% | Confined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.38 0.4 0.34 0.179 0.129 0.129 | In Regime In Transition In Regime In Regime In Regime In Regime In Regime | AI, DI AI, WI WI WI WI WI WI WI WI WI WI | 23 25 23 24 22 22 16 15 20 26 20 26 25 25 | Fair Good Fair Fair Fair Fair Fair Fair Good Fair Good Good Good | Riparian habitat conditions, physical instream habitat | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 5.35 4.98 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 1.45 60-90 1.45 60-90 1.78 60-90 1.78 60-90 1.78 60-90 0.74 30-60 0.95 0-30 0.83 30-60 | 5-30% -<5% 60-100% 60-100% 60-100% 60-100% 5-30% 5-30% <-5% <5% <5% | Grasses, trees Grasses Trees, grasses Trees, grasses Trees | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted emergent Rooted emergent Rooted emergent Rooted emergent Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Heavy vegetation encroachment Straight stot agricultured dich Straight agricultural ditch Straight agricultural ditch Straight agricultural ditch, no flow observed, minor slumping observed, minor slumping observed, minor slumping observed, minor slumping observed, trees growing on channel bed, mostly stable |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2021-10-19 2021-10-20 2021-10-20 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC4 RC4-1-1 RC4-1-1A RC4-1-1A-1 RC4-1-1A-2 RC4-1-1A-3 | Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel, cobble Clay, silt, sand Clay, silt, sand Clay, silt Clay, sil | Clay, silt, till Clay, silt, sand Clay, silt, sand, gravel Clay, silt Clay | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Fluvial entrainment Minor slumping <5% Failing/sloughing Undercutting, banks slumping <5% | Confined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.38 0.4 0.34 0.179 0.129 0.29 0.098 | In Regime In Transition In Regime In R | Al, DI Al, WI WI WI WI WI WI WI WI WI WI WI | 23 25 23 24 22 22 16 15 20 26 26 28 28 25 25 26 | Fair Good Fair Fair Fair Fair Fair Good Fair Good Fair Good Sood Asses | Riparian habitat conditions, physical instream habitat Channel stability Channel stability Channel stability Channel stability Channel stability Riparian habitat conditions, channel stability Physical instream habitat, water quality | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.78 60-90 1.78 30-60 2.20 60-90 0.74 30-60 0.95 0-30 0.83 30-60 | 5-30% <5% 60-100% 5-30% 60-100% 60-100% 60-100% 5-30% 5-30% <5% <5% <5% <5% | Grasses, trees Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Trees, grasses Trees, grasses Trees Trees | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted emergent Rooted emergent Rooted emergent Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Heavy vegetation encroachment Straight agricultural ditch Straight agricultural ditch Straight agricultural ditch Straight agricultural ditch, no flow observed, minor slumping observed, mins slumping activity Former agricultural ditch, no flow observed, trees growing on channel bed, mostly stable |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2021-10-19 2021-10-20 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC3 RC4 RC4-1-1A RC4-1-1A RC4-1-1A-1 RC4-1-1A-2 RC4-1-1A-3 | Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand Clay, silt, sand Clay, silt Clay, sil | Clay, silt, till Clay, silt, sand Clay, silt, sand, gravel Clay, silt, sand, gravel Clay, silt C | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, banks slumping Undercutting, banks slumping Huvial entrainment Fluvial entrainment Fluvial entrainment Fluvial entrainment Fluvial entrainment Undercutting, banks slumping <5% | Confined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.38 0.4 0.179 0.129 0.129 0.129 0.098 0.098 | In Regime In Transition In Regime In Regime In Regime In Regime In Regime | Al, DI Al, WI Al, WI Al WI WI WI WI WI WI WI WI WI | 23 25 23 24 22 22 16 15 20 26 19 28 28 28 25 25 26 | Fair Good Fair Fair Fair Fair Fair Fair Good Assee Good Assee | Riparian habitat conditions, physical instream habitat Channel stability Channel stability Channel stability Channel stability Channel stability Riparian habitat conditions, channel stability Channel stability Phycial instream habitat, water quality | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 5.35 4.98 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 1.23 60-90 1.45 60-90 1.78 60-90 1.78 60-90 1.78 30-60 2.20 60-90 0.74 30-60 0.95 0-30 0.83 30-60 | 5-30% <5% | Grasses, trees Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Trees, grasses Trees, grasses Trees | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted emergent Rooted emergent Rooted emergent Rooted emergent Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Heavy vegetation encroachment Straight agricultured ditch Straight agricultured ditch Straight agricultural ditch, Straight agricultural ditch, beaver dams retaining water, no flow observed, minimal geomorphic activity Former agricultural ditch, no flow observed, minimal geomorphic activity Former agricultural ditch, no flow observed, grasses and wendfow son channel bed, mostly stable |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2021-10-19 2021-10-20 2021-10-20 2021-10-20 2021-10-20 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC3 RC4-1-1A RC5-1A-1A RC4-1-1A-3 | Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand, cobble Clay, silt, gravel, sand, cobble Clay, silt, gravel, sand, cobble Clay, silt, sand Clay, silt, sand Clay, silt Clay, | Clay, silt, till Clay, silt, sand Clay, silt Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel Clay, silt Clay, silt, sand Clay, silt | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Ruvial entrainment Fluvial entrainment Falling/sloughing Undercutting, banks slumping <5% | Confined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.34 0.179 0.129 0.129 0.129 | In Regime In Transition In Regime In Regime In Regime In Regime In Regime | AI, DI AI, WI WI AI WI WI WI WI WI WI WI WI WI | 23 25 23 24 22 16 15 20 26 19 28 26 25 25 26 26 26 30 | Fair Good Fair Fair Fair Fair Fair Fair Fair Good Fair Good Good Good Good | Riparian habitat conditions, physical instream habitat | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 5.35 4.98 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.78 60-90 1.78 60-90 1.78 30-60 2.20 60-90 0.74 30-60 0.95 0-30 | 5-30% <5% | Grasses, trees Grasses, shrubs Grasses Grasses Grasses Grasses Grasses Grasses Grasses, trees Shrubs Grasses Trees, grasses Trees, grasses Trees, masses Trees, provide the statement of the stat | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightende, slumping common, several vegetated islands observed straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Straight ditched channel, high banks with tall grasses Heavy vegetation encroachment Straight agricultural ditch Straight agricultural ditch Straight agricultural ditch, beaver dams retaining water, no flow observed, minora slumping observed, minora slumping observed, minora slumping observed, minora slumping observed, minora slumping observed, grasses and wetland species observed graves and wetland species o |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2021-10-19 2021-10-20 2021-10-20 2021-10-20 2021-10-19 2021-10-19 2022-07-13 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC3 RC4-1-1 RC4-1-1A RC4-1-1A-1 RC4-1-1A-3 RC4-1-1A-3 | Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, gravel Clay, silt, gravel, cobble Clay, silt, gravel, cobble Clay, silt, gravel, sand, cobble Clay, silt, gravel, sand, cobble Clay, silt, sand Clay, silt Clay, si | Clay, silt, till Clay, silt, sand Clay, silt Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel Clay, silt, sand, gravel Clay, silt Clay, silt, sand | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, sabs failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Minor slumping <<5% | Confined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.34 0.179 0.129 0.129 0.129 0.098 | In Regime In Transition In Regime | AI, DI AI, WI WI WI WI WI WI, AI WI WI WI WI WI WI | 23 25 23 24 22 22 16 15 20 26 19 28 26 19 28 25 26 26 30 19 | Fair Good Fair Fair Fair Fair Fair Fair Fair Good Fair Good Good Good Fair Fair | Riparian habitat conditions, physical instream habitat | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 5.35 4.98 5.18 4.77 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.78 60-90 1.78 30-60 2.20 60-90 0.74 30-60 0.93 30-60 0.83 30-60 | 5-30% <530% | Grasses, trees Grasses, trees Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Trees, grasses Trees, herbaceous, grasses Grasses, trees | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted emergent Rooted emergent Rooted emergent Rooted emergent Rooted emergent Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightende, slumping common, several vegetated islands observed straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grases Heavy vegetation encroachment Straight ditched channel, high banks with tall grases Heavy vegetation encroachment Straight agricultural ditch. Beaver, minimal geomorphic activity Former agricultural ditch, no flow observed, minor slumping observed, minor slumping observed, minor slumping observed, grases and wetland species observed graves and wetland species observed grasses and wetland species observed g |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-07-13 2022-07-14 2022-07-14 2022-07-14 2022-07-14 2022-07-14 2022-0 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC4 RC4-1-1 RC4-1-1A RC4-1-1A-1 RC4-1-1A-2 RC4-1-1A-3 RC5-1 RC5-1 RC5-1 | Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand, gravel, cobble Clay, silt, gravel, cobble Clay, silt, gravel, cobble Clay, silt, gravel, sand, cobble Clay, silt, gravel, | Clay, silt, till Clay, silt, sand Clay, silt Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel Clay, silt, sand | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Huvial entrainment Huvial entrainment Minor slumping <5% | Confined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.34 0.179 0.129 0.129 0.129 0.129 0.098 0.098 0.098 | In Regime In Transition In Regime | AI, DI AI, WI WI WI WI WI WI WI WI WI WI | 23 25 23 24 22 22 16 15 20 26 19 28 26 19 28 25 26 26 30 19 | Fair Good Fair Fair Fair Fair Fair Fair Fair Fair | Riparian habitat conditions, physical instream habitat Channel stability Channel stability Channel stability Channel stability Riparian habitat conditions, channel stability Riparian habitat, water quality Phsycial instream habitat, water quality | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 5.35 4.98 5.18 4.77 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.45 60-90 1.78 30-60 2.20 60-90 0.74 30-60 0.95 0-30 0.83 30-60 0.83 30-60 | 5-30% <5% | Grasses, trees Grasses, strubs Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Trees, grasses Trees, herbaceous, grasses Grasses, trees | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Straight ditched channel, high banks with tall grasses Heavy vegetation encroachment Straight shot agricultural ditch Straight agricultural ditch, no flow observed, minor slumping observed, minor slumping observed, minor slumping observed, minor slumping observed, minor slumping observed, grasses and wetland species observed graving on semi-dry bed, minimal geomorphic activity Straight agricultural ditch. |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2021-10-20 2021-20-20 2021-20-20 2021-20-20 2021-20-20 2021-20-20 2021-20-20 2021-20-20 2021-20-20 2021-20-20 2021-20-20 2021-20-20 2021-20-20 2021-20-20 2021-20-20 2021-20-20 2021-20-20 2021-20-20 2021-2 | BB12-1 BB13 BB13 BB15 BB16 RC1 RC2 RC4 RC4-1-1 RC4-1-1A RC4-1-1A-1 RC4-1-1A-2 RC4-1-1A-3 RC5-1 RC5-2 | Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand Clay, silt, sand Clay, silt Clay, sil | Clay, silt, till Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand, gravel Clay, silt Clay, silt, sand Clay, silt Clay, silt Clay, silt Clay, silt, sand | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Huvial entrainment Vinor slumping <5% | Confined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.29 0.28 0.38 0.4 0.34 0.4 0.34 0.179 0.129 0.129 0.098 0.098 | In Regime In Transition In Regime | AI, DI AI, WI VI VI VI VI VI VI VI VI VI V | 23 25 23 24 22 22 16 15 20 26 19 28 26 26 26 26 26 30 19 28 | Fair Good Fair Fair Fair Fair Fair Good Fair Good Good Good Good Fair Asses Good | Riparian habitat conditions, physical instream habitat | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 5.18 4.77 2.22 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.45 60-90 1.78 60-90 1.78 30-60 2.20 60-90 0.74 30-60 0.95 0-30 0.83 30-60 0.83 30-60 | 5-30% <5% | Grasses, trees Grasses, trees Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Trees, grasses Trees, grasses Trees, frees Grasses Grasses Trees, frees | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted mergent Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Straight shott agricultural ditch Straight shott agricultural ditch Straight agricultural ditch, beaver dams retaining water, no flow observed, minor slumping observed, minor slumping observed, minor slumping observed, grasses and wetland species observed growing on channel bed, mostly stable Shallow pooled water but no flow observed, grasses and wetland species observed growing on semi-dry bed, minimal gemorphic activity Straight agricultural ditch. |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2021-10-19 2021-10-20 2021-10-20 2021-10-19 2021-10-19 2021-10-19 2022-07-13 2022-07-14 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC4 RC4-1-1 RC4-1-1A RC4-1-1A RC4-1-1A-2 RC4-1-1A-3 RC5-1 RC5-1 RC5-1-1 | Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel, cobble Clay, silt, sand Clay, silt, sand Clay, silt Clay, sil | Clay, silt, till Clay, silt, sand Clay, silt, sand, gravel Clay, silt Clay | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Fluvial entrainment Vinor slumping <5% | Confined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.38 0.4 0.34 0.179 0.129 0.129 0.129 0.098 0.098 | In Regime In Transition In Regime | AI, DI AI, WI VI VI VI VI VI VI VI VI VI V | 23 25 23 24 22 22 16 15 20 26 20 26 29 28 25 25 26 26 26 30 19 9 19 | Fair Good Fair Fair Fair Fair Fair Good Fair Good Good Good Fair Asses Good Fair | Riparian habitat conditions, physical instream habitat | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 5.18 4.77 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 1.24 60-90 1.25 60-90 1.45 60-90 1.78 60-90 1.78 60-90 1.78 60-90 0.74 30-60 0.95 0-30 0.83 30-60 0.83 30-60 0.83 30-60 0.83 30-60 0.83 30-60 | 5-30% <5% | Grasses, trees Grasses, shrubs Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Trees, grasses Trees Trees, herbaceous, grasses Grasses, trees Grasses Trees | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted demergent Rooted floating Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Straight agricultural ditch, beaver dams retaining water, no flow observed, minor slumping observed, minor slumping observed, minor slumping observed, minor slumping observed, straight agricultural ditch, no flow observed, grasses and wetland species observed growing on channel bed, mostly stable Straight agricultural ditch. Straight agricultural ditch. |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2021-10-19 2021-10-19 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2021-10-20 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC4 RC4-1-1 RC4-1-1A RC4-1-1A RC4-1-1A-1 RC4-1-1A-2 RC4-1-1A-3 RC5-1 RC5-1 RC5-1 RC5-1-1 | Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel, cobble Clay, silt, sand Clay, silt, sand Clay, silt Clay, sil | Clay, silt, till Clay, silt, sand Clay, silt, sand, gravel Clay, silt Clay, silt, sand Clay, silt Clay, sil | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Fluvial entrainment Ninor slumping <5% | Confined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.38 0.4 0.34 0.179 0.129 0.129 0.098 0.098 0.098 | In Regime In Transition In Regime | Al, DI Al, WI Al, WI WI WI WI WI WI WI WI WI WI | 23 25 23 24 22 22 16 15 20 26 26 19 28 28 25 25 26 26 30 19 9 19 9 28 | Fair Good Fair Fair Fair Fair Fair Good Fair Good Good Good Fair Poorly de Fair | Riparian habitat conditions, physical instream habitat Channel stability Channel stability Channel stability Channel stability Riparian habitat conditions, channel stability Channel stability N/A Phsycial instream habitat, water quality Phsycial instream habitat, water quality Phsycial instream habitat, water quality ed as a part of RC-11A-1 Phsycial instream habitat, water quality Phsycial instream habitat, water quality, physical instream habitat Phsycial instream habitat Physical instr | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 5.35 4.98 5.18 4.77 3.93 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.78 60-90 1.78 60-90 1.78 30-60 2.20 60-90 0.74 30-60 0.95 0-30 0.83 30-60 0.83 30-60 0.69 0-30 1.03 0-30 1.03 0-30 | 5-30% <5% | Grasses, trees Grasses, shrubs Grasses Grasses Grasses Grasses Grasses Grasses Grasses Trees, grasses Trees, grasses Trees, grasses Grasses Grasses Grasses Grasses Grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted emergent | some undercuting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Straight ditched channel, high banks with tall grasses Heavy vegetation encroachment Straight agricultural ditch Straight agricultural ditch Straight agricultural ditch, no flow observed, minimal geomorphic activity Former agricultural ditch, no flow observed, grasses and wetland species observed growing on semi-dry bed, minimal geomorphic activity Straight agricultural ditch. |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-07-13 2022-07-13 2022-07-14 2022-07-15 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC3 RC4 RC4-1-1A RC4-1-1A-1 RC4-1-1A-1 RC4-1-1A-3 RC4-1-1A-3 RC5-1-1A-3 RC5-1-1 RC5-1-2 | Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand, gravel, cobble Clay, silt, sand Clay, silt, sand Clay, silt Clay, silt Clay, silt Clay, silt N/A N/A N/A N/A | Clay, silt, till Clay, silt, sand Clay, silt, sand, gravel Clay, silt Clay, silt, sand | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, slab failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Minor slumping <5% | Confined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.34 0.34 0.129 0.29 0.38 0.4 0.34 0.129 0.129 0.129 0.098 0.098 0.098 | In Regime In Transition In Regime In Reg | Al, DI Al, WI Al, WI Al WI WI WI WI WI WI WI WI WI WI | 23 25 23 24 22 22 16 15 20 26 19 28 28 25 25 26 26 30 19 28 25 25 26 30 19 19 28 | Fair Good Fair Fair Fair Good Fair Fair Fair Good Fair Good Good Good Good Fair Fair Fair Fair Fair Fair Fair Fair | Riparian habitat conditions, physical instream habitat Channel stability Channel stability Channel stability, physical instream habitat Channel stability Riparian habitat conditions, channel stability Physical instream habitat, water quality Physical instream habitat, water quality, physical instream habitat Riparian habitat conditions, water quality, physical instream ha | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 5.35 4.98 5.18 4.77 3.93 2.68 | 0.36 60-90 0.35 30-60 0.88 60-90 1.48 30-60 1.23 60-90 1.45 60-90 1.78 60-90 1.78 60-90 1.78 60-90 1.78 60-90 1.78 60-90 0.74 30-60 0.95 0-30 0.83 30-60 0.95 0-30 0.69 0-30 0.73 60-90 0.73 60-90 | 5-30% <5% | Grasses, trees Grasses, shrubs Grasses Grasses Grasses Grasses Grasses Grasses Grasses Trees, grasses Trees, herbaceous, grasses Grasses, trees Grasses, trees Grasses Grasses Grasses Grasses Grasses Grasses Grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightende, slumping common, several vegetated islands observed straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Straight agricultural ditch, beaver dams retaining water, no flow observed, minor slumping observed, minoral geomorphic activity Former agricultural ditch, no flow observed, minoral geomorphic activity Shallow pooled water but no flow observed, grasses and wetland species observed growing on semi-dry bed, minimal geomorphic activity Straight agricultural ditch, extreme vegetation encroachment Straight agricultural ditch, extreme vegetation encroachment |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-07-13 2022-07-14 2022-07-15 2022-07-15 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC3 RC4 RC4-1-1 RC4-1-1A RC4-1-1A RC4-1-1A RC4-1-1A-1 RC4-1-1A-2 RC4-1-1A-3 RC5-1 RC5-1 RC5-1 RC5-1-1 | Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, gravel Clay, silt, sand, gravel, cobble Clay, silt, gravel, sand, Sold, So | Clay, silt, till Clay, silt, sand Clay, silt Clay, silt Clay, silt Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel Clay, silt, sand Clay, silt, sand Clay, silt Clay, silt, sand | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, sabs failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Huvial entrainment Minor slumping <5% | Confined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.38 0.4 0.129 0.129 0.129 0.129 0.129 0.129 0.129 0.098 0.098 0.098 0.098 | In Regime In Transition In Regime In Reg | AI, DI AI, WI AI, WI AI WI WI WI WI WI WI WI WI WI PI WI WI PI PI PI PI PI PI | 23 25 23 24 22 22 16 15 20 26 19 28 25 25 26 26 26 26 19 28 25 25 26 19 19 28 | Fair Good Fair Fair Fair Fair Fair Good Fair Good Good Good Good Asses Good Fair Asses Good Fair | Riparian habitat conditions, physical instream habitat | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 5.35 4.98 5.35 4.98 5.18 4.77 3.93 2.68 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.78 60-90 1.78 30-60 2.20 60-90 0.74 30-60 0.95 0-30 0.83 30-60 0.95 0-30 0.95 0-30 1.03 0-30 | 5-30% -<5% 60-100% 60-100% 60-100% 60-100% 5-30% 5-30% 5-30% -<5% <5% < | Grasses, trees Grasses, trees Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Trees, grasses Trees, herbaceous, grasses Grasses, trees Grasses, trees Grasses, trees Grasses, trees Grasses, trees Grasses, trees | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted demergent Rooted floating Rooted mergent Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed Straight ditched channel, recovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Straight ditched channel, high banks with tall grasses Heavy vegetation encroachment Straight agricultural ditch. Beavy vegetation encroachment Straight agricultural ditch. Deserved, minor slumping observed, minor slumping observed, trees growing on channel bed, mostly stable Shallow pooled water but no flow observed, grasses and wetland species observed growing on semi-dry bed, minimal geomorphic activity Straight agricultural ditch, extreme vegetation encroachment Straight agricultural ditch, extreme vegetation encroachment. |
| 2021-10-28 2021-10-20 2021-10-20 2021-10-20 2021-10-20 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-06-28 2022-07-19 2021-10-20 2021-10-19 2022-07-13 2022-07-14 2022-07-15 2022-07-15 | BB12-1 BB13 BB14 BB15 BB16 RC1 RC2 RC3 RC4 RC4-1-1A RC4-1-1A RC4-1-1A-2 RC4-1-1A-3 RC5-1A-1A RC5-1A-1A RC5-1-1 RC5-1-1 RC5-1-1 | Clay, silt Clay, silt Clay, silt, sand Clay, silt, sand Clay, silt, sand, gravel, cobble Clay, silt, gravel, cobble Clay, silt, gravel, sand, cobble Clay, silt Clay, silt Clay, silt N/A N/A Clay, silt Clay, silt | Clay, silt, till Clay, silt Clay, silt, sand Clay, silt, sand, gravel Clay, silt, sand | Banks slumping Banks slumping Banks slumping Banks slumping Banks slumping Undercutting, banks slumping Undercutting, sabs failure, rotational slip and slump Fluvial entrainment Fluvial entrainment Huvial entrainment Minor slumping <5% | Confined Unconfined | 0.103 0.21 0.32 0.19 0.29 0.28 0.38 0.4 0.34 0.129 0.129 0.129 0.129 0.129 0.098 0.098 0.098 0.098 | In Regime In Transition In Regime In Reg | AI, DI AI, WI WI WI WI WI WI WI WI WI PI WI WI WI PI PI PI PI PI | 23 25 23 24 22 16 15 20 26 19 28 25 26 26 19 28 26 19 28 25 26 19 19 28 20 19 28 20 20 20 20 20 19 19 28 20 20 20 20 20 20 20 20 20 20 20 20 20 | Fair Good Fair Fair Fair Fair Fair Good Fair Good Good Good Good Fair | Riparian habitat conditions, physical instream habitat | 1.49 1.60 3.60 4.80 4.17 2.17 7.09 3.83 4.80 5.35 4.98 5.18 4.77 3.93 2.68 2.30 | 0.36 60-90 0.35 30-60 0.88 60-90 1.68 30-60 1.23 60-90 2.08 60-90 1.45 60-90 1.78 30-60 2.20 60-90 0.74 30-60 0.55 0-30 0.83 30-60 0.55 0-30 1.03 0-30 0.52 60-90 0.52 60-90 | 5-30% <530% | Grasses, trees Grasses, trees Grasses, shrubs Grasses Grasses Grasses Grasses Grasses Shrubs Grasses Trees, grasses Trees, grasses Trees, herbaceous, grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses Grasses | Rooted emergent Attached algae, rooted emergent Rooted emergent Rooted emergent Rooted floating Rooted emergent | some undercutting and exposed till noted Somewhat naturalized ditched agricultural channel, partially straightened, slumping common, several vegetated islands observed trecovering planform Heavy backwatering from large beaver dam Straight ditched channel, recovering planform Heavy vegetation encroachment Entrenched channel, high banks with tall grasses Heavy vegetation encroachment Straight ditched drannel, high banks with tall grasses Heavy vegetation encroachment Straight agricultural ditch. Straight agricultural ditch. Straight agricultural ditch. Straight agricultural ditch. Straight agricultural ditch. no flow observed, minor slumping observed, trees growing on channel bed, mostly stable Shallow pooled water but no flow observed, grasses and wetland species observed growing on semi-dry bed, minimal geomorphic activity Straight agricultural ditch, extreme vegetation encroachment Straight agricultural ditch, |

| 2023-12-12 RCB | Clay, silt, sand | Clay, silt, sand | Banks slumping, fracture lines, exposed roots | Unconfined | 0.43 In Transition | WI | 18 Fair | Riparian Habitat Conditions | 8.20 | 1.88 60-90 | 60-100% Grasses | Rooted Emergent | fractures |
|----------------|------------------|------------------|---|------------|--------------------|----|---------|-----------------------------|------|------------|-----------------|-----------------|------------------------------|
| | | | | | | | | | | | | | locations, many slumps and |
| | | | | | | | | | | | | | Large cutfaces along several |

Appendix E Photographic Record























Feature characteristic of a large pond due to back watering from a beaver dam.



Riparian vegetation consisting of grasses and shrubs, low entrenchment identified.

Photo: 21 Bear Brook: BB5-5A-3-1A




















































Appendix F Detailed Assessment Summaries

GEO

MORPHIX

Earth Science Observation

Detailed Geomorphological Assessment Summary

Reach BB1

| Project Number: | PN22024 | Date: | 2022-07-14 |
|------------------------|---|----------------------|------------|
| Client: | Taggart Investments and Algonquins of Ontario | Length Surveyed (m): | 112.5 |
| Location: | Tewin Lands | # of Cross-Sections: | 8 |

| Reach Characteristics | | | |
|-----------------------------------|--------------------------------|--------------------------------------|----------------------|
| Drainage Area (km ²): | 53.8 | Dominant Riparian Vegetation Type: | Grasses, Trees |
| Geology/Soils: | Offshore glaciomarine deposits | Extent of Riparian Cover: | Continuous |
| Surrounding Land Use: | Agricultural, Forest | Width of Riparian Cover: | >10 (channel widths) |
| Valley Type: | Unconfined | Age Class of Riparian Vegetation: | Mature (>30 yrs) |
| Dominant Instream Vegetation | Type: Floating, Emergent | Extent of Encroachment into Channel: | None |
| Portion of Reach with Vegetation | on: 70% | Density of Woody Debris: | High |

| Hydrology | | | |
|--|--------------|--|------|
| Measured Discharge (m ³ /s): | N/A | Calculated Bankfull Discharge (m ³ /s): | 4.88 |
| Modelled 2-year Discharge (m ³ /s): | Not modelled | Calculated Bankfull Velocity (m/s): | 0.42 |
| Modelled 2-year Velocity (m/s): | Not modelled | | |

| Profile Characteristics | | Planform Characteristics | |
|---------------------------|-------|--------------------------|------|
| Bankfull Gradient (%): | 0.03 | Sinuosity: | 3.84 |
| Channel Bed Gradient (%): | 0.04 | Meander Belt Width (m): | N/A |
| Riffle Gradient (%): | 1.98 | Radius of Curvature (m): | 25 |
| Riffle Length (m): | 11.52 | Meander Amplitude (m): | 70 |
| Riffle-Pool Spacing (m): | 34.59 | Meander wavelength (m): | 85 |

Longitudinal Profile



| Bank Characteristics | | | | | |
|----------------------|---------|---------|---------|------------------------|-----------|
| | Minimum | Maximum | Average | | |
| Bank Height (m): | 1.50 | 2.90 | 2.18 | Bank Material (range): | Silt-Clay |
| Bank Angle (deg): | 45 | 90 | 73 | | |
| Root Depth (m): | 0.15 | 0.40 | 0.26 | | |
| Root Density (%): | 20 | 50 | 39 | | |
| Bank Undercut (m): | 0.02 | 0.35 | 0.17 | | |

Cross-Sectional Characteristics

| | Minimum | Maximum | Average |
|-----------------------------|------------|---------|---------|
| Bankfull Width (m): | 5.61 | 12.50 | 9.63 |
| Average Bankfull Depth (m): | 0.94 | 1.76 | 1.22 |
| Bankfull Width/Depth (m/m): | 6 | 10 | 8 |
| Wetted Width (m): | 4.78 | 7.94 | 6.15 |
| Average Water Depth (m): | 0.20 | 0.41 | 0.33 |
| Wetted Width/Depth (m/m): | 14 | 31 | 19 |
| Entrenchment Ratio (m/m): | Low (>2.2) | | |
| Maximum Water Depth (m): | 0.43 | 0.72 | 0.60 |
| Manning's <i>n</i> : | | 0.055 | |

2.0

2.0

2.0





| ı) |
|----|
| |
| |
| |
| |

Subpavement: Particle shape: Embeddedness (%): Particle range (riffle): Particle Range (pool):

Clay N/A (Clay/sand) N/A (Clay/sand) Clay-Sand Clay-Sand

Cumulative Particle Size Distribution



| Channel Thresholds | | | |
|--|------|---|--------------|
| Flow Competency (m/s): | | Tractive Force at Bankfull (N/m ²): | 4.79 |
| for D ₅₀ : | 0.27 | Tractive Force at 2-year flow (N/m ²): | Not modelled |
| for D ₈₄ : | 0.27 | Critical Shear Stress (D ₅₀) (N/m ²): | 1.46 |
| Unit Stream Power at Bankfull (W/m ²): | 1.99 | | |

General Field Observations

Channel Description

Reach BB1 is a low gradient channel that passes through an unconfined valley. Riparian vegetation was characterized by grasses and some mature trees. Rooted submergent and emmergent vegetation was common along the reach, however vegetation encroachment was minimal. Substrate consisted of clay to sand in both the pools and the riffles. Average bankfull width and depth were 9.63 m and 1.22 m, respectivly. Some undercutting was observed, up to 0.35 m and bank slumping was present.

Cross Section 4 - Facing Downstream



GEO

MORPHIX

Detailed Geomorphological Assessment Summary

Reach BB5

| Project Number: | PN21063 | Date: | 2021/11/11 |
|-----------------|---|----------------------|------------|
| Client: | Taggart Investments and Algonquins of Ontario | Length Surveyed (m): | 183.6 |
| Location: | Tewin Lands Ottawa | # of Cross-Sections: | 10 |

| Reach Characteristics | | | |
|-----------------------------------|--------------------------------|--------------------------------------|-----------------------|
| Drainage Area (km ²): | 31.7 | Dominant Riparian Vegetation Type: | Grass/Herbaceous Veg. |
| Geology/Soils: | Offshore glaciomarine deposits | Extent of Riparian Cover: | Continuous |
| Surrounding Land Use: | Grassland/Forest | Width of Riparian Cover: | >10 Channel Widths |
| Valley Type: | Partially Confined | Age Class of Riparian Vegetation: | Established |
| Dominant Instream Vegetation | Type: None observed | Extent of Encroachment into Channel: | Minimal |
| Portion of Reach with Vegetation | on: N/A | Density of Woody Debris: | Low |

| Hydrology | | | |
|--|--------------|--|------|
| Measured Discharge (m ³ /s): | 0.21 | Calculated Bankfull Discharge (m ³ /s): | 3.20 |
| Modelled 2-year Discharge (m ³ /s): | Not modelled | Calculated Bankfull Velocity (m/s): | 0.66 |
| Modelled 2-year Velocity (m/s): | Not modelled | | |

| Profile Characteristics | | Planform Characteristics | |
|---------------------------|-------|--------------------------|------|
| Bankfull Gradient (%): | 0.02 | Sinuosity: | 1.21 |
| Channel Bed Gradient (%): | 0.09 | Meander Belt Width (m): | N/A |
| Riffle Gradient (%): | 1.27 | Radius of Curvature (m): | 15 |
| Riffle Length (m): | 17.83 | Meander Amplitude (m): | 30 |
| Riffle-Pool Spacing (m): | 26.64 | Meander wavelength (m): | 45 |

Longitudinal Profile



Bank Characteristics

| | Minimum | Maximum | Average | | |
|--------------------|---------|---------|---------|------------------------|-----------|
| Bank Height (m): | 2.25 | 3.85 | 3.00 | Bank Material (range): | Clay-Sand |
| Bank Angle (deg): | 55 | 85 | 70 | | |
| Root Depth (m): | 0.20 | 0.30 | 0.23 | | |
| Root Density (%): | 20 | 80 | 73 | | |
| Bank Undercut (m): | 0.00 | 0.12 | 0.02 | | |

Cross-Sectional Characteristics

| | Minimum | Maximum | Average |
|-----------------------------|---------|------------|---------|
| Bankfull Width (m): | 5.10 | 7.38 | 5.97 |
| Average Bankfull Depth (m): | 0.57 | 1.06 | 0.82 |
| Bankfull Width/Depth (m/m): | 5 | 13 | 8 |
| Wetted Width (m): | 3.61 | 5.61 | 4.39 |
| Average Water Depth (m): | 0.22 | 0.55 | 0.41 |
| Wetted Width/Depth (m/m): | 7 | 18 | 12 |
| Entrenchment Ratio (m/m): | | Low (>2.2) | |
| Maximum Water Depth (m): | 0.37 | 0.96 | 0.68 |
| Manning's <i>n</i> : | | 0.040 | |



Photograph at cross section 7 (looking downstream)



Grain size (mm)

Channel Thresholds

| Flow Competency (m/s): | |
|--|------|
| for D ₅₀ : | 0.27 |
| for D ₈₄ : | 0.27 |
| Unit Stream Power at Bankfull (W/m ²): | 4.73 |

Tractive Force at Bankfull (N/m^2) : Tractive Force at 2-year flow (N/m^2) : Critical Shear Stress (D_{50}) (N/m^2) : 7.22 Not modelled 1.46

General Field Observations

Channel Description

Reach BB5 was a low gradient, meandering channel that passed through a partially confined valley. Riparian vegetation was characterized by grasses in the floodplain and on the valley slopes. There was minimal encrochment of vegetation to the channel and some reeds were found in th channel. Substrate consisted of clay to Sand in riffles and pools. Average bankfull width and depth were 5.97 m and 0.82 m, repsectively. Undercutting was minimal and was measured up to a maximum of 0.12 m.

Cross Section 3 - Facing Upstream



Detailed Geomorphological Assessment Summary

Reach BB5-5

| Project Number: | PN21063 | Date: | 2021-11-08 |
|-----------------|---|----------------------|------------|
| Client: | Taggart Investments and Algonquins of Ontario | Length Surveyed (m): | 201.6 |
| Location: | Tewin Lands, Ottawa | # of Cross-Sections: | 10 |

| Reach Characteristics | | | | | |
|-----------------------------------|--|--------------------------------------|--------------------------|--|--|
| Drainage Area (km ²): | 31.7 | Dominant Riparian Vegetation Type: | Grass/Herbaceous/Trees | | |
| Geology/Soils: | Nearshore + offshore glaciomarine deposits | Extent of Riparian Cover: | Continuous | | |
| Surrounding Land Use | Forest/Grassland | Width of Riparian Cover: | >10 Channel Widths | | |
| Valley Type: | Partially Confined | Age Class of Riparian Vegetation: | Established (5-30 Years) | | |
| Dominant Instream Ve | egetation Type: Reeds | Extent of Encroachment into Channel: | Minimal | | |
| Portion of Reach with | Vegetation: 5% | Density of Woody Debris: | Low | | |

| Hydrology | | | |
|--|--------------|--|------|
| Measured Discharge (m ³ /s): | 0.11 | Calculated Bankfull Discharge (m ³ /s): | 1.99 |
| Modelled 2-year Discharge (m ³ /s): | Not modelled | Calculated Bankfull Velocity (m/s): | 0.78 |
| Modelled 2-year Velocity (m/s): | Not modelled | | |

| Profile Characteristics | | Planform Characteristics | |
|---------------------------|-------|--------------------------|------|
| Bankfull Gradient (%): | 0.20 | Sinuosity: | 1.29 |
| Channel Bed Gradient (%): | 0.22 | Meander Belt Width (m): | N/A |
| Riffle Gradient (%): | 1.04 | Radius of Curvature (m): | 7 |
| Riffle Length (m): | 11.34 | Meander Amplitude (m): | 20 |
| Riffle-Pool Spacing (m): | 14.28 | Meander wavelength (m): | 30 |

Longitudinal Profile



Bank Characteristics Minimum Maximum Average Bank Height (m): 1.52 2.70 2.14 Clay-Sand Bank Material (range): 30 Bank Angle (deg): 85 64 Root Depth (m): 0.20 0.50 0.22 25 70 45 Root Density (%): Bank Undercut (m): 0.45 0.07 0

Cross-Sectional Characteristics

| | Minimum | Maximum | Average |
|-----------------------------|---------|------------|---------|
| Bankfull Width (m): | 2.50 | 6.40 | 4.34 |
| Average Bankfull Depth (m): | 0.43 | 0.72 | 0.59 |
| Bankfull Width/Depth (m/m): | 5 | 14 | 8 |
| Wetted Width (m): | 1.20 | 3.20 | 2.25 |
| Average Water Depth (m): | 0.11 | 0.41 | 0.28 |
| Wetted Width/Depth (m/m): | 5 | 16 | 9 |
| Entrenchment Ratio (m/m): | | Low (>2.2) | |
| Maximum Water Depth (m): | 0.21 | 0.69 | 0.47 |
| Manning's <i>n</i> : | | 0.040 | |



Photograph at cross section 2 (looking downstream)



| Channel Thresholds | | | | | |
|--|------|---|--------------|--|--|
| Flow Competency (m/s): | | Tractive Force at Bankfull (N/m ²): | 11.51 | | |
| for D ₅₀ : | 0.27 | Tractive Force at 2-year flow (N/m ²): | Not modelled | | |
| for D ₈₄ : | 0.27 | Critical Shear Stress (D ₅₀) (N/m ²): | 1.46 | | |
| Unit Stream Power at Bankfull (W/m ²): | 9.01 | | | | |

General Field Observations

Channel Description

Reach BB5-5 was a minimal gradient, meandering channel that passed through a partially confined valley. Riparian vegetation was characterized by grasses in the floodplain and on the valley slopes. There was minimal encrochment of vegetation to the channel and some reeds were found in th channel. Substrate consisted of clay to sand in riffles and pools. Average bankfull width and depth were 4.34m and 0.59 m, repsectively. Undercutting frequency was minimal and was measured up to a maximum of 0.45 m.



GEO

Detailed Geomorphological Assessment Summary

Reach BB5-5A-3

| Project Number: | PN21063 | Date: | 2021/11/11 |
|-----------------|---|----------------------|------------|
| Client: | Taggart Investments and Algonquins of Ontario | Length Surveyed (m): | 99.6 |
| Location: | Tewin Lands, Ottawa | # of Cross-Sections: | 8 |

| Reach Characteristics | | | | | |
|-----------------------------------|---------------------------|--------------------------------------|------------------------|--|--|
| Drainage Area (km²): | 6.8 | Dominant Riparian Vegetation Type: | Treed and Herbaceous | | |
| Geology/Soils: | ore glaciomarine deposits | Extent of Riparian Cover: | Continuous | | |
| Surrounding Land Use: | Forest | Width of Riparian Cover: | >10 Channel Widths | | |
| Valley Type: | Partially Confined | Age Class of Riparian Vegetation: | Established (5-30 yrs) | | |
| Dominant Instream Vegetation Typ | e: None present | Extent of Encroachment into Channel: | Minimal | | |
| Portion of Reach with Vegetation: | 0% | Density of Woody Debris: | Moderate | | |

| Hydrology | | | |
|--|--------------|--|------|
| Measured Discharge (m ³ /s): | 0.08 | Calculated Bankfull Discharge (m ³ /s): | 2.23 |
| Modelled 2-year Discharge (m ³ /s): | Not modelled | Calculated Bankfull Velocity (m/s): | 0.97 |
| Modelled 2-year Velocity (m/s): | Not modelled | | |

| Profile Characteristics | | Planform Characteristics | |
|---------------------------|-------|--------------------------|------|
| Bankfull Gradient (%): | 0.47 | Sinuosity: | 1.82 |
| Channel Bed Gradient (%): | 0.56 | Meander Belt Width (m): | N/A |
| Riffle Gradient (%): | 1.87 | Radius of Curvature (m): | 10 |
| Riffle Length (m): | 9.20 | Meander Amplitude (m): | 20 |
| Riffle-Pool Spacing (m): | 11.40 | Meander wavelength (m): | 30 |

Longitudinal Profile



Bank Characteristics

| | Minimum | Maximum | Average | | |
|--------------------|---------|---------|---------|------------------------|-----------|
| Bank Height (m): | 0.41 | 3.90 | 1.48 | Bank Material (range): | Clay-Sand |
| Bank Angle (deg): | 20 | 90 | 54 | | |
| Root Depth (m): | 0.10 | 0.90 | 0.35 | | |
| Root Density (%): | 10 | 80 | 47 | | |
| Bank Undercut (m): | 0.00 | 0.93 | 0.16 | | |

Cross-Sectional Characteristics

| | Minimum | Maximum | Average |
|-----------------------------|---------|------------|---------|
| Bankfull Width (m): | 3.06 | 12.93 | 6.22 |
| Average Bankfull Depth (m): | 0.25 | 0.51 | 0.37 |
| Bankfull Width/Depth (m/m): | 10 | 52 | 19 |
| Wetted Width (m): | 1.55 | 6.81 | 3.72 |
| Average Water Depth (m): | 0.06 | 0.34 | 0.18 |
| Wetted Width/Depth (m/m): | 12 | 79 | 26 |
| Entrenchment Ratio: | | Low (>2.2) | |
| Maximum Water Depth (m): | 0.10 | 0.55 | 0.30 |
| Manning's <i>n</i> : | | 0.040 | |
| | | | |

2.0

7.5

17.0



Photograph at cross section 2 (looking upstream)



Substrate Characteristics

Subpavement: Particle shape: Embeddedness (%): Particle range (riffle): Particle Range (pool):

Clay, Till Angular, Sub-rounded 0-20 Clay-Cobble Clay-Cobble

Cumulative Particle Size Distribution



| Channel Thresholds | | | |
|--|-------|---|--------------|
| Flow Competency (m/s): | | Tractive Force at Bankfull (N/m ²): | 20.39 |
| for D ₅₀ : | 0.50 | Tractive Force at 2-year flow (N/m ²): | Not modelled |
| for D ₈₄ : | 0.73 | Critical Shear Stress (D ₅₀) (N/m ²): | 5.46 |
| Unit Stream Power at Bankfull (W/m ²): | 19.69 | | |

General Field Observations

Channel Description

Reach BB5-5A-3 was a moderate gradient, meandering channel that passed through a partially confined valley. Riparian vegetation was characterized by grasses in the floodplain and trees on the valley slopes. Substrate consisted of clay to cobbles in riffles and pools. Average bankfull width and depth were 6.31 m and 0.39 m, repsectively. Undercutting was fairly common and was measured up to a maximum of 0.93 m.



GEO

MORPHIX

Detailed Geomorphological Assessment Summary

Reach BB6

| Project Number: | PN21063 | Date: | 2021/11/09 |
|-----------------|---|----------------------|------------|
| Client: | Taggart Investments and Algonquins of Ontario | Length Surveyed (m): | 170.7 |
| Location: | Tewin Lands, Ottawa | # of Cross-Sections: | 10 |

| Reach Characterist | tics | | | |
|-----------------------------------|----------------------|----------------------|--------------------------------------|--------------------------|
| Drainage Area (km ²): | | 20.7 | Dominant Riparian Vegetation Type: | Grass/Herbaceuous/Trees |
| Geology/Soils: | Nearshore + offshore | laciomarine deposits | Extent of Riparian Cover: | Continuous |
| Surrounding Land Use | 9: | Forest | Width of Riparian Cover: | >10 Channel Widths |
| Valley Type: | | Partially Confined | Age Class of Riparian Vegetation: | Established (5-30 Years) |
| Dominant Instream V | egetation Type: | Reeds | Extent of Encroachment into Channel: | Minimal |
| Portion of Reach with | Vegetation: | 5% | Density of Woody Debris: | Low |

| Hydrology | | | |
|--|--------------|--|------|
| Measured Discharge (m ³ /s): | 0.07 | Calculated Bankfull Discharge (m ³ /s): | 2.23 |
| Modelled 2-year Discharge (m ³ /s): | Not modelled | Calculated Bankfull Velocity (m/s): | 0.88 |
| Modelled 2-year Velocity (m/s): | Not modelled | | |

| Profile Characteristics | | Planform Characteristics | |
|---------------------------|-------|--------------------------|------|
| Bankfull Gradient (%): | 0.21 | Sinuosity: | 1.42 |
| Channel Bed Gradient (%): | 0.23 | Meander Belt Width (m): | N/A |
| Riffle Gradient (%): | 0.55 | Radius of Curvature (m): | 10 |
| Riffle Length (m): | 9.68 | Meander Amplitude (m): | 20 |
| Riffle-Pool Spacing (m): | 11.28 | Meander wavelength (m): | 30 |

Longitudinal Profile

. .



Bank Characteristics

| | Minimum | Maximum | Average | | |
|--------------------|---------|---------|---------|------------------------|-----------|
| Bank Height (m): | 2.00 | 3.30 | 2.94 | Bank Material (range): | Clay-Sand |
| Bank Angle (deg): | 45 | 90 | 69 | | |
| Root Depth (m): | 0.15 | 0.30 | 0.18 | | |
| Root Density (%): | 70 | 80 | 79 | | |
| Bank Undercut (m): | 0.00 | 0.23 | 0.06 | | |

Cross-Sectional Characteristics

| | Minimum | Maximum | Average |
|-----------------------------|---------|------------------|---------|
| Bankfull Width (m): | 2.63 | 7.35 | 4.67 |
| Average Bankfull Depth (m): | 0.56 | 1.23 | 0.93 |
| Bankfull Width/Depth (m/m): | 3 | 6 | 5 |
| Wetted Width (m): | 2.04 | 3.76 | 2.68 |
| Average Water Depth (m): | 0.18 | 0.45 | 0.25 |
| Wetted Width/Depth (m/m): | 5 | 16 | 11 |
| Entrenchment Ratio (m/m): | Mo | oderate (1.4 - 2 | 2.2) |
| Maximum Water Depth (m): | 0.29 | 0.62 | 0.40 |
| Manning's <i>n</i> : | | 0.040 | |
| | | | |



Photograph at cross section 6 (looking downstream)



Substrate Characteristics

| Particle Size (mm) D ₁₀ : D ₅₀ : D ₈₄ : |) 2.0 2.0 2.0 | | Subpavement: Particle shape: Embeddedness (%): Particle range (riffle): Particle Range (pool): | Till N/A (sand) 0 Clay-Sand Clay-Sand | |
|---|------------------------|----|--|---|------|
| 100 90 80 70 60 50 40 30 | | | ve Particle Size Distribution | | |
| | | 10 | Grain size (mm) | 00 | 1000 |

| Channel Thresholds | | | | |
|--|-------|---|-------------|--|
| Flow Competency (m/s): | | Tractive Force at Bankfull (N/m ²): | 19.34 | |
| for D ₅₀ : | 0.27 | Tractive Force at 2-year flow (N/m ²): | Not modelle | |
| for D ₈₄ : | 0.27 | Critical Shear Stress (D ₅₀) (N/m ²): | 1.46 | |
| Unit Stream Power at Bankfull (W/m ²): | 21.03 | | | |

General Field Observations

Channel Description

Reach BB6 was a minimal gradient, meandering channel that passed through a partially confined valley. Riparian vegetation was characterized by grasses in the floodplain and on the valley slopes. There was minimal encrochment of vegetation to the channel and some reeds were found in the channel. Substrate consisted of Clay to Sand in riffles and pools. Average bankfull width and depth were 4.73 m and 0.94 m, repsectively. Undercutting frequency was minimal and was measured up to a maximum of 0.45 m.



GEO

MORPHIX

Earth Science

Detailed Geomorphological Assessment Summary

Reach RC1

| Project Number: | PN21063 | Date: | 2022-06-29 |
|-----------------|---|----------------------|------------|
| Client: | Taggart Investments and Algonquins of Ontario | Length Surveyed (m): | 108.8 |
| Location: | Tewin Lands, Ontario | # of Cross-Sections: | 8 |

| Reach Characteristics | | | | |
|-----------------------------------|---|--------------------------------------|---------------------|--|
| Drainage Area (km ²): | 11.52 | Dominant Riparian Vegetation Type: | Grasses | |
| Geology/Soils: N | earshore + offshore glaciomarine deposits | Extent of Riparian Cover: | Fragmented | |
| Surrounding Land Use: | Agricultural/Grassland | Width of Riparian Cover: | 4-10 channel widths | |
| Valley Type: | Unconfined | Age Class of Riparian Vegetation: | 5-30 yrs | |
| Dominant Instream Vege | tation Type: Emergent species | Extent of Encroachment into Channel: | Minimal | |
| Portion of Reach with Ve | getation: 5% | Density of Woody Debris: | Low | |

| Hydrology | | | |
|--|----------------------|--|------|
| Measured Discharge (m ³ /s): | 0.04 | Calculated Bankfull Discharge (m ³ /s): | 4.87 |
| Modelled 2-year Discharge (m ³ /s): | 4.58 (JFSA modelled) | Calculated Bankfull Velocity (m/s): | 1.10 |
| Modelled 2-year Velocity (m/s): | Not modelled | | |
| | | | |

| Profile Characteristics | | Planform Characteristics | |
|---------------------------|------|--------------------------|------|
| Bankfull Gradient (%): | 0.20 | Sinuosity: | 1.42 |
| Channel Bed Gradient (%): | 0.03 | Meander Belt Width (m): | N/A |
| Riffle Gradient (%): | 0.40 | Radius of Curvature (m): | 7.5 |
| Riffle Length (m): | 13 | Meander Amplitude (m): | 20 |
| Riffle-Pool Spacing (m): | 21 | Meander wavelength (m): | 35 |

Longitudinal Profile



Bank Characteristics Minimum Maximum Average Bank Material (range): Bank Height (m): 1.40 2.00 1.68 Clay to sand 40 90 72 Bank Angle (deg): Root Depth (m): 0.15 10.00 0.82 20 37 45 Root Density (%): 0.00 0.30 0.10 Bank Undercut (m):

Cross-Sectional Characteristics

| | Minimum | Maximum | Average |
|-----------------------------|------------|---------|---------|
| Bankfull Width (m): | 4.90 | 8.09 | 6.30 |
| Average Bankfull Depth (m): | 0.72 | 0.87 | 0.79 |
| Bankfull Width/Depth (m/m): | 6 | 11 | 8 |
| Wetted Width (m): | 2.56 | 5.92 | 3.63 |
| Average Water Depth (m): | 0.19 | 0.44 | 0.34 |
| Wetted Width/Depth (m/m): | 8 | 16 | 11 |
| Entrenchment Ratio (m/m): | Low (>2.2) | | |
| Maximum Water Depth (m): | 0.33 | 0.73 | 0.54 |
| Manning's <i>n</i> : | | 0.045 | |





Substrate Characteristics

| Particle Size (mm) | | |
|--------------------|--|--|
| D ₁₀ : | | |
| D ₅₀ : | | |
| D ₈₄ : | | |

2.0

2.0

2.0

Subpavement: Particle shape: Embeddedness (%): Particle range (riffle): Particle Range (pool):

Clay Platy, sub-rounded, sub-angular 50 Clay-Sand Clay-Sand

Cumulative Particle Size Distribution



| Channel Thresholds | | | | |
|--|------|---|--------------|--|
| Flow Competency (m/s): | | Tractive Force at Bankfull (N/m ²): | 13.9 | |
| for D ₅₀ : | 0.09 | Tractive Force at 2-year flow (N/m ²): | Not modelled | |
| for D ₈₄ : | 0.09 | Critical Shear Stress (D ₅₀) (N/m ²): | 0.15 | |
| Unit Stream Power at Bankfull (W/m ²): | 11.2 | | | |

General Field Observations

Channel Description

Reach RC1 was a low gradient meandering channel that flowed through an unconfined valley. Riparian vegetation was predominantly characterized by grasses and small shrubs. There was minor encroachment of emergent-type vegetation into the channel. Channel substrates consisted mainly of clays and sands. Although, some gravel and cobbles were found in riffles. Average bankfull width and depth were 6.30 m and 0.79 m, repsectively. Bank undercutting was observed up to a maximum of 0.30 m. In addition, bank slumping was common throughout the reach.



GEO

MORPHIX

Earth Science

Detailed Geomorphological Assessment Summary

Reach RCB

| Project Number: | PN21063 | Date: | 2023-12-14 |
|-----------------|---|----------------------|------------|
| Client: | Taggart Investments and Algonquins of Ontario | Length Surveyed (m): | 141.4 |
| Location: | Tewin Lands, Ontario | # of Cross-Sections: | 8 |

| Reach Characteristics | | | |
|-----------------------------------|------------------------------|--------------------------------------|--------------------|
| Drainage Area (km²): | 11.8 | Dominant Riparian Vegetation Type: | Grasses |
| Geology/Soils: | Sandy glaciofluvial deposits | Extent of Riparian Cover: | Continuous |
| Surrounding Land Use: | Agricultural | Width of Riparian Cover: | >10 channel widths |
| Valley Type: | Unconfined | Age Class of Riparian Vegetation: | Mature |
| Dominant Instream Vegetation Typ | Rooted Emergent | Extent of Encroachment into Channel: | Moderate |
| Portion of Reach with Vegetation: | 50% | Density of Woody Debris: | Low |

| Hydrology | | | |
|---|----------------------|--|------|
| Measured Discharge (m ³ /s): | 0.36 | Calculated Bankfull Discharge (m ³ /s): | 4.67 |
| Modelled 2-year Discharge (m3/s): | 5.23 (JFSA modelled) | Calculated Bankfull Velocity (m/s): | 1.00 |

| Profile Characteristics | | Planform Characteristics | |
|---------------------------|----------------|--------------------------|------|
| Bankfull Gradient (%): | 0.27 | Sinuosity: | 1.51 |
| Channel Bed Gradient (%): | 0.26 | Meander Amplitude (m): | 12 |
| Riffle Gradient (%): | N/A no riffles | Meander wavelength (m): | 23 |
| Riffle Length (m): | N/A no riffles | Radius of curvature (m): | 9 |
| Riffle-Pool Spacing (m): | N/A no riffles | | |

Longitudinal Profile



| Bank Characteristics | | | | | | | | |
|----------------------|---------|---------|---------|------------------------|------------------|--|--|--|
| | Minimum | Maximum | Average | | | | | |
| Bank Height (m): | 1.40 | 2.80 | 1.88 | Bank Material (range): | Clay, Silt, Sand | | | |
| Bank Angle (deg): | 45 | 90 | 74 | | | | | |
| Root Depth (m): | 0.15 | 50.00 | 20.02 | | | | | |
| Root Density (%): | 20 | 60 | 43 | | | | | |
| Bank Undercut (m): | 0.00 | 0.35 | 0.11 | | | | | |

Cross-Sectional Characteristics

| | Minimum | Maximum | Average |
|-----------------------------|------------|---------|---------|
| Bankfull Width (m): | 3.82 | 9.72 | 5.85 |
| Average Bankfull Depth (m): | 0.66 | 0.98 | 0.80 |
| Bankfull Width/Depth (m/m): | 5 | 14 | 7 |
| Wetted Width (m): | 1.73 | 3.64 | 2.73 |
| Average Water Depth (m): | 0.17 | 0.41 | 0.31 |
| Wetted Width/Depth (m/m): | 5 | 21 | 10 |
| Maximum Water Depth (m): | 0.35 | 0.56 | 0.46 |
| Entrenchment Ratio: | Low (>2.2) | | |
| Manning's <i>n</i> : | | 0.045 | |
| | | | |







Grain size (mm)

GEO Morphix Ltd.

| Channel Thresholds | | | | | | | |
|--|-------|---|--------------|--|--|--|--|
| Flow Competency (m/s): | | Tractive Force at Bankfull (N/m ²): | 21.23 | | | | |
| for D ₅₀ : | 0.27 | Tractive Force at 2-year flow (N/m ²): | Not modelled | | | | |
| for D ₈₄ : | 0.27 | Critical Shear Stress (D ₅₀) (N/m ²): | 1.46 | | | | |
| Unit Stream Power at Bankfull (W/m ²): | 21.14 | | | | | | |

General Field Observations

Channel Description

Reach RCB meanders through active agriculture with a grassy buffer between the channel and the cultivated lands. There was no riffle formations, and was mostly composed of runs and pools. The riparian vegetation encroaches the channel and instream rooted emergent vegetation was well established. Channel slumps, fracture lines and undercutting was observed throughout the reach. The channel bed was composed of soft silt and sand over a compact clay-till subpavement. Some sections of the reach exhibited exposed compact clay-till on the bed. During the time of the assessment, the channel was iced over, however the average bankfull width and depth was 5.85 m and 0.80 m respectivley, and wetted with and depth at 2.73 m and 0.31 m , respectivly.



Cross Section 3 - Facing Downstream
Appendix G TRCA Meander Belt Width Values

GEO MORPHIX™

| Reach | Drainage Area (km²) | Discharge (m³/s) | Gradient (m/m) |
|---------------|---------------------|------------------|----------------|
| BB5-5A-3-1A | 0.25 | 0.14 | 0.005 |
| BB5-5A-3-1A-1 | 0.20 | 0.12 | 0.004 |
| BB5-5A-3B | 5.41 | 0.40* | 0.001 |
| BB5-5A-3B-1 | 0.30 | 0.17 | 0.003 |
| BB5-5A-3C | 5.41 | 0.40* | 0.001 |
| BB5-5A-3D | 5.41 | 0.40* | 0.001 |
| BB5-5A-3D-1 | 0.12 | 0.08 | 0.005 |
| BB5-5C-1 | 2.93 | 0.19* | 0.002 |
| BB5-5C-1A | 2.85 | 1.30 | 0.002 |
| BB5-5C-1A-1 | 0.18 | 0.11 | 0.004 |
| BB5-5C-1A-2 | 0.02 | 0.01 | 0.001 |
| BB5-5D | 0.16 | 0.10 | 0.006 |
| BB5-5D-1 | 0.02 | 0.02 | 0.001 |
| BB9 | 18.57 | 2.09* | 0.002 |
| BB10 | 18.57 | 2.09* | 0.002 |
| BB10-1 | 0.72 | 0.38 | 0.012 |
| BB10-1A | 0.68 | 0.36 | 0.001 |
| BB10-1B | 0.55 | 0.30 | 0.004 |
| BB11 | 18.57 | 2.09* | 0.002 |
| BB12 | 17.28 | 2.09* | 0.002 |
| BB13 | 14.40 | 1.43* | 0.002 |
| BB14 | 14.40 | 1.43* | 0.002 |
| BB15 | 12.26 | 1.43* | 0.002 |
| BB16 | 12.26 | 1.43* | 0.002 |
| RC5 | 0.30 | 0.06 | 0.001 |

*Interpolated 2-year flow provided by JFSA based on SNC Bear Brook and tributary flood hazard mapping

Appendix H Utility Crossing Assessment



Existing conditions at **Crossing 1** on the south side of Piperville Road. Left photo is facing down at the box culvert opening; right photo is facing southwest at the roadside ditch.



Project #: PN22024



Project #: PN22024







Existing conditions at **Crossing 6** on the south side of Piperville Road. Left photo is facing southeast; right photo is facing east along Piperville Road. Some erosion scars and fallen trees were observed.







southwest towards the output of the roadside ditch; right photograph is taken facing southeast.





downstream; right photograph is taken facing southwest towards the mouth of the culvert.











A conditions at Crossing 16 on the south side of Russell Road. Left photo is facing sout upstream; right photo is facing southeast. Some slumping was observed..









Existing conditions at **Crossing 20** on the east side of Ramsayville Road. Left phot is taken facing west; right photo is taken facing northeast. Some slumping was observed.



photo is facing east. Some minor slumping was observed.

























southwest along the roadside ditch; right photograph is taken facing southeast towards downstream.




| Crossing ID | Culvert Type | Watercourse Type | Culvert Height | Water Depth | Culvert Depth | Bankfull Width | Bankfull Depth | Description |
|----------------|---------------------|-----------------------------------|-------------------|----------------|------------------|-------------------|-------------------|---|
| 001N | Concrete box | Agricultural/residential ditch | 0.90 | 0.17 | 2.10 | - | - | |
| 001S | Concrete box | Agricultural/residential ditch | 0.90 | 0.15 | 2.10 | - | - | |
| 002N | Corrugated steel | Agricultural/residential ditch | 0.68 | 0.38 | 0.76 | - | - | |
| 0025 | Corrugated steel | Agricultural/residential ditch | 0.77 | 0.15 | 0.81 | - | - | |
| 003N | Corrugated steel | Agricultural/residential | 0.60 | 0.00 | 0.61 | - | - | |
| 0035 | Corrugated steel | Agricultural/residential ditch | 0.61 | 0.14 | 0.61 | - | - | |
| 004N | Concrete box | Agricultura/residential ditch | 1.50 | 0.50 | 3.00 | - | - | |
| 004S | Concrete box | Agricultural/residential ditch | 1.75 | 0.27 | 3.00 | - | - | |
| 005N | Corrugated steel | Agricultural/residential ditch | 0.72 | 0.19 | 0.72 | - | - | |
| 0055 | Corrugated steel | Agricultural/residential ditch | 0.72 | 0.01 | 0.72 | - | - | |
| 006N | Corrugated steel | Stream | 5.00 | 0.46 | 5.00 | 5.94 | 2.25 | A stream meander is present immediately upstream of the culvert. Some slumping was observed on both banks. |
| 006S | Corrugated steel | Stream | 5.00 | 0.46 | 5.00 | 6.81 | 2.25 | Many fallen and leaning trees due to bank slumping observed. Exposed roots and soil present. Bed substrate is composed of fine materials. |
| 007E | Corrugated steel | Roadside ditch | 0.60 | 0.06 | 0.60 | - | - | |

| Crossing ID | Culvert Type | Watercourse Type | Culvert Height | Water Depth | Culvert Depth | Bankfull Width | Bankfull Depth | Description |
|----------------|-------------------------|--------------------------------|-------------------|----------------|------------------|-------------------|-------------------|-------------|
| 007W | Corrugated steel | Roadside ditch | 0.60 | 0.13 | 0.60 | - | - | |
| 008N | Corrugated steel | Roadside ditch | 1.00 | 0.27 | 1.00 | - | - | |
| 0085 | Corrugated steel | Roadside ditch | 1.00 | 0.20 | 1.00 | - | - | |
| 009N | Corrugated steel | Roadside ditch | 0.55 | 0.07 | 0.60 | - | - | |
| 0095 | Corrugated steel | Roadside ditch | 0.55 | 0.04 | 0.60 | - | - | |
| 010N | Concrete cylinder | Roadside ditch | 1.20 | 0.12 | 2.00 | - | - | |
| 0105 | Concrete cylinder | Roadside ditch | 1.20 | 0.00 | 2.00 | - | - | |
| 011E | Corrugated steel, wings | Roadside ditch | 0.78 | 0.28 | 0.72 | - | - | |
| 011W | Corrugated steel, wings | Roadside ditch | 0.78 | 0.18 | 0.72 | - | - | |
| 012N | Concrete cylinder | Agricultural/roadside ditch | 0.83 | 0.02 | 0.83 | - | - | |
| 0125 | Concrete cylinder | Agricultural/roadside ditch | 0.83 | 0.02 | 0.83 | - | - | |
| 013N | Concrete cylinder | Agricultural ditch | 1.50 | 0.18 | 1.50 | - | - | |
| 0135 | Concrete cylinder | Agricultural ditch | 1.50 | 0.11 | 1.50 | - | - | |
| 014N | Concrete cylinder | Agricultural ditch | 0.84 | 0.00 | 0.82 | - | - | |
| 014S | Concrete cylinder | Agricultural ditch | 0.84 | 0.27 | 0.82 | - | - | |

| Crossing ID | Culvert Type | Watercourse Type | Culvert Height | Water Depth | Culvert Depth | Bankfull Width | Bankfull Depth | Description |
|----------------|------------------------|--------------------|-------------------|----------------|------------------|-------------------|-------------------|---|
| 015N | Concrete cylinder | Agricultural ditch | 1.10 | 0.01 | 1.10 | - | - | |
| 0155 | Concrete cylinder | Agricultural ditch | 1.10 | 0.02 | 1.10 | - | - | |
| 016N | Concrete box, wings | Stream | 2.25 | 0.14 | 4.20 | - | - | |
| 0165 | Concrete box, wings | Stream | 2.25 | 0.40 | 4.20 | - | - | |
| 017E | Corrugated steel | Roadside ditch | 0.55 | 0.04 | 0.50 | - | - | |
| 017W | Corrugated steel | Roadside ditch | 0.55 | 0.00 | 0.50 | - | - | |
| 018E | Bridge | Stream | N/A | N/A | N/A | 6.64 | 1.50 | Channel flows below right side of bridge, while sediment deposition occupies the left side. The right bank approximately 10 meters upstream of the bridge is nearly vertical with some slumping and exposed tree roots. |
| 018W | Bridge | Stream | N/A | N/A | N/A | 6.36 | 1.75 | Sediment deposition on left side of channel forms lower terrace in narrow stream valley downstream of bridge. Right bank is slightly less vertical than it is upstream. |
| 019E | Corrugated steel | Stream | 1.00 | 0.01 | 1.00 | 5.79 | 1.75 | Meandering stream flowing along relatively flat bottom of small valley (approximately 5 meter tall valley walls and 5-10 meters wide). The base of the right valley wall has a vertical scour and |

| ely 0.80 m owing along n of small 5 meter tall 0 meters egetated by vall slopes |
|--|
| owing along n of small 5 meter tall 0 meters egetated by vall slopes |
| n of small 5 meter tall 0 meters 2getated by vall slopes |
| 5 meter tall 0 meters egetated by vall slopes |
| 0 meters egetated by vall slopes |
| egetated by vall slopes |
| vall slopes |
| |
| pling and |
| S. |
| ream with |
| oth banks. |
| eposit along |
| ediately |
| opening. |
| ream with |
| ooth banks |
| egetation |
| channel. |
| eposit along |
| ediately |
| t opening. |
| el erosion |
| |
| el erosion |
| ownetroom |
| parcoly |
| t denosit |
| t) culvert |
| |
| plin s. real poth po |

| Crossing ID | Culvert Type | Watercourse Type | Culvert Height | Water Depth | Culvert Depth | Bankfull Width | Bankfull Depth | Description |
|----------------|--------------------------------|------------------|-------------------|----------------|------------------|-------------------|-------------------|---|
| | | | | | | | | Right bank is nearly vertical, some |
| 0225 | Corrugated steel, double | Stream | 4.00 | 0.00 | 4.00 | 9.40 | 1.50 | Channel flows within valley. Left (west) culvert in pair of corrugated steel culverts is occupied by silt sediment deposit which extends upstream of the crossing as a medial bar with sparse vegetation. Flow is primarily through right (east) culvert. Right bank is nearly vertical, slumping with exposed roots. |
| 023E | Concrete box | Stream | N/A | N/A | N/A | - | - | Unable to get measurements due to construction |
| 023W | Concrete box | Stream | N/A | N/A | N/A | - | - | Unable to get measurements due to construction |
| 024N | Concrete box | Stream | 1.95 | 0.34 | 5.20 | 5.66 | 2.40 | Undercut (0.20 m deep) along tall left bank. Terraced right bank has minor slumping along the top of bank. |
| 0245 | Concrete box | Stream | 1.95 | 0.17 | 5.20 | 6.80 | 1.15 | Undercut (0.35 m deep) along tall left bank. Terraced right bank; higher bank has some exposed roots and soil along its base. Some downed trees downstream of crossing. |
| 025N | Corrugated steel | Stream | 2.50 | 0.04 | 2.50 | - | - | Unable to get measurements due to construction |
| 0255 | Corrugated steel | Stream | 2.50 | 0.08 | 2.50 | - | - | Unable to get measurements due to construction |

| Crossing ID | Culvert Type | Watercourse Type | Culvert Height | Water Depth | Culvert Depth | Bankfull Width | Bankfull Depth | Description |
|----------------|----------------------|--------------------|-------------------|----------------|------------------|-------------------|-------------------|---|
| 026N | Corrugated steel | Roadside ditch | 0.72 | 0.05 | 1.00 | - | - | |
| 0265 | Corrugated steel | Roadside ditch | 0.70 | 0.00 | 0.70 | - | - | |
| 027E | Concrete cylinder | Stream/wetland | 1.30 | 0.26 | 1.60 | 6.87 | 1.00 | Channel downstream of culvert is entrenched with 1 m height banks with undercuts ranging from 0.10- 0.20 m. Channel bed is lined with angular cobble stones, banks are comprised of silt and sand sized sediment. |
| 027W | Concrete cylinder | Stream/wetland | 1.30 | 0.10 | 1.60 | 3.72 | 1.00 | Upstream of culvert channel is undefined and flows through a saturated wetland within a wide valley vegetated with a mix of native and invasive wetland species. |
| 028E | Corrugated steel | Stream | N/A | N/A | N/A | 2.77 | 0.4 | No concerning erosion observed. |
| 028W | Corrugated steel | Stream | N/A | N/A | N/A | 3.3 | 1.1 | No concerning erosion observed. |
| 029E | Corrugated steel | Stream | 1.10 | 0.23 | 1.30 | 5.23 | 1.50 | No concerning channel erosion observed. Banks are composed of grasses and bed was comprised of fine sediments. Concrete around culvert is degrading. |
| 029W | Corrugated steel | Stream | 1.10 | 0.31 | 1.30 | 4.63 | 2.00 | No concerning channel erosion observed. Very little flow observed. |
| 030E | Corrugated steel | Agricultural ditch | 1.3 | 0.05 | 1.75 | - | - | |

| Crossing ID | Culvert Type | Watercourse Type | Culvert Height | Water Depth | Culvert Depth | Bankfull Width | Bankfull Depth | Description |
|----------------|----------------------|--------------------|-------------------|----------------|------------------|-------------------|-------------------|---|
| 030W | Corrugated steel | Agricultural ditch | 1.3 | 0.2 | 1.75 | - | - | |
| 031E | Corrugated steel | Stream | 1.80 | 0.20 | 2.00 | 3.44 | 2.50 | Slumping and exposed soil was observed approx. 5m downstream of the culvert. Grasses were present in the channel, very little flow was observed. |
| 0311 | Corrugated steel | Stream | 1.80 | 0.10 | 2.00 | 4.22 | 2.00 | Channel flowing within a 2m deep valley. Banks were composed of cobble with established grasses growing overtop. No major signs of erosion observed. |
| 032E | Concrete cylinder | Roadside ditch | 2.50 | 0.15 | 2.50 | 4.24 | 1.00 | Due to a recent storm, many trees were down in the channel. Some exposed soil and roots were observed upstream of the culvert. Bed materials composed of silt, sand and cobbles. |
| 032W | Concrete cylinder | Stream | 2.50 | 0.12 | 2.50 | 3.93 | 2.25 | Several down trees due to recent storm. Some exposed soil sand tree roots observed. |
| 033N | Corrugated steel | Agricultural ditch | 0.74 | 0.24 | 0.85 | - | - | |
| 0335 | Corrugated steel | Agricultural ditch | 0.74 | 0.08 | 0.85 | - | - | |
| 034N | Concrete box | Stream | 1.05 | 0.32 | 3.50 | 8.73 | 0.50 | Backwater wider than culvert opening with cattails growing in silty bed sediments upstream of culvert. |

| Crossing ID | Culvert Type | Watercourse Type | Culvert Height | Water Depth | Culvert Depth | Bankfull Width | Bankfull Depth | Description |
|----------------|----------------------|------------------|-------------------|----------------|------------------|-------------------|-------------------|--|
| 034S | Concrete box | Stream | 1.05 | 0.58 | 3.50 | 5.79 | 0.30 | Backwater wider than culvert opening, poorly defined banks, |
| 035E | Concrete box | Stream | 3.00 | 0.35 | 2.50 | 6.95 | 2.00 | Some slumping and exposed soil observed on both banks downstream of the culvert. Banks were composed of grasses and bed was silt, sand and cobbles. |
| 035₩ | Concrete box | Stream | 3.00 | 0.35 | 2.50 | 5.02 | 1.40 | Exposed soils and roots observed upstream of the culvert. Right bank composed of a manicured lawn and cobbles. Bed is composed of primarily cobbles. |
| 036E | Concrete cylinder | Roadside ditch | 1.20 | 0.13 | 1.20 | - | - | |
| 036W | Concrete cylinder | Roadside ditch | 1.20 | 0.11 | 1.20 | - | - | |



Legend



Servicing Lines

Tewin Secondary Plan Subwatershed Study

Potential Future Crossing Locations

Ottawa, Ontario

Imagery: City of Ottawa, 2019. Watercourse: MNRF, 2021 Boundary Areas: Algonquins of Ontario/ Taggart, 2021., GEO Morphix Ltd., 2021. Reach Break and ID, Crossing Location: GEO Morphix Ltd., 2021. Servicing Lines: JFSA, 2022. Print Date: June 2023. PN22024. Drawn By: M.O. K.W.